

July 08, 2014

Portland Public School  
Attn: Mr. Steve Effros  
Project Manager, Facilities and Asset Management  
501 N. Dixon Street  
Portland, Oregon 97227

Re: Report of Geotechnical Engineering Services  
Vertical Settlement and Lateral Movement  
Tubman School Site for Portland Public Schools  
Portland, Oregon  
RhinoOne Project No. PPS-2013-003

Dear Mr. Effros:

RhinoOne Geotechnical Engineering is pleased to submit this report of our preliminary analysis of the settlement and lateral movement issues at the Tubman Middle School Site in Portland, Oregon. We conducted a site walk with you on December 30, 2013. You subsequently provided us with a set of documents for review. These documents are referenced below:

- Burns, Bear, McNeil & Schneider, Grading and Roof Plan, Eliot Elementary School For Multnomah County School District Number 1, Sheet 1 of 9, 1952 (BBMS).
- ODOT, Retaining Wall East Bank Freeway Section, Plan & Elevation, Sheet Number 15928 dated 5/5/1960; Standard Retaining Walls, Front Face Vertical, Sheet Number 15552, dated 1/14/1960.
- Kelly Strazer & Associates Geotechnical Investigation and Report, Proposed Additions to Harriet Tubman Middle School, Portland, Oregon dated March 29, 1983 (KSA-1).
- Unthank Seder Poticha Architects, PC, Set of Plans for "Additions and Remodeling", dated October 1983 (USPA).
- Kelly Strazer & Associates, Slope Failure Problem, Harriet Tubman Middle School Project, Portland, Oregon dated April 15, 1983 (KSA-2).
- Kelly Strazer & Associates, Unstable Soil Area, Harriet Tubman Middle School Project, Portland, Oregon letter dated January 18, 1984 (KSA-3).
- Kelly Strazer & Associates, Observation of Pile Driving during Construction, Harriet Tubman Middle School Project, Portland, Oregon dated March 14, 1984 (KSA-4).

**Current Conditions:**

We completed a site walk with you and representatives of Oregon Department of Transportation (ODOT) on April 18, 2014. Building settlements were observed at the southwest corner and at the generator room with some additional distress observed between these two points. Distress was observed in the parking lot on the west side of the building as evidenced by various asphalt repairs over the years. Standing water was also observed in a clean-out which indicates that the water is not draining properly. A 2- to 4- inch crack running along the entire height was observed in the ODOT retaining wall downslope from the southwest corner of the building. Figure 1 shows a schematic of observed building movements. The pattern of movement appears to be lateral ground movement which subsequently causes vertical movements.

**Review of Existing Data:**

We understand that the original school building was constructed in 1952. Figure 2 of the KSA-1 (1983) report (see attachments) indicates the approximate top of pre-fill slope based on 1908 Sanborn Insurance Maps. Review of the contours on the 1952 grading plan (see attachments) indicates that the elevations along the edge of bank were  $\pm 129$  feet to  $\pm 136$  feet in 1952 and therefore the site was filled sometimes before 1952. The top of the bank has also moved towards the west and south of the 1908 line. Based on this map, most of the 1952 structure was placed on native ground except the southern-most 30 feet and a small portion of the northwest corner of the building. The central area of the site which is indicated as "Play Area and Night Parking" and where the 1983 addition was constructed has significant depth of un-documented fill. The grading plan also indicates the finished elevations for "Play Area and Night Parking" areas on the order of  $\pm 134$  feet to  $\pm 138$  feet. This indicates that some additional fill was also placed for this addition in 1952. Our review indicates that there are several areas of undocumented fills on this site. Review of the KSA-1 report indicates that the 1952 structure was placed on timber piles.

We understand that ODOT built a retaining wall near the southwest side of the school property in 1960's. We reviewed sheets 15928 and 15552 (see attachments) provided to us by ODOT and also conducted an on-site meeting on April 18 between the staff of PPS and ODOT. The retaining wall is approximately 200 feet long with a maximum height of 14 feet from base of foundation to the top of wall. The wall was designed for a 2H: 1V slope. Based on the standard plans (Sheet 15552), the base width of the foundation is 8'6" with the section towards the school being 3'3". We do not have access to as-builds so the limits and type of backfill for the wall could not be determined. A 2- to 4- inch separation along the entire height of the wall was observed between the panels of the retaining wall which indicates that the wall has moved over the years. We also understand that ODOT constructed a viaduct for both the north and south bound lanes of I-5 above a ravine north of the retaining wall. It is possible that un-documented fill has been placed over the years encroaching over the ravine.

Expansion to the school building was planned in 1980's. KSA was contracted by the School District to complete a geotechnical study (KSA-1). KSA completed five (5) borings in 1980 and an additional eleven (11) borings in 1983. Figure 2 from KSA report shows the location of these borings. KSA also observed shallow surficial sliding, block movements, cracking and previous asphalt patching during this study. These features are also shown on Figure 2 of KSA-1 report. Based on these borings, KSA developed fill depth contour maps as indicated in Figure 14 of the KSA-1 report (attached). The depth of fill is zero near the east side the site to as much as 30 feet or more near the south west portions of the site. The fill has been described as un-documented fill. KSA recommended that the new building addition be

supported on driven timber piles to an ultimate capacity of 25 tons. Review of grading plans indicates that some minor filling was also performed for this addition.

The piles were subsequently driven as summarized in KSA-4 (1984) report dated March 14, 1984. A total of 220 piles were installed for the main building. The lengths of piles were from a low of  $\pm 18$  feet to about  $\pm 40$  feet. Pile driving was terminated based on the Engineering News Formula. Review of the as-builds indicates that the piles are embedded approximately 4 inches into the pile cap. This indicates that the piles are free head and have potentially lost contact with the cap in areas of large movement. Piles with this condition have limited lateral load capacity.

The new generator room was located on the west side near the northwest side of the building. The generators were mentioned in KSA-3 report. We were not able to establish the foundation conditions for this room, but we postulate that it is placed on shallow foundations. This is because we did not find any pile driving records for the generator room.

**Causation:**

Based on our observation and discussions with you, it appears that most of the building distress is on the west wall with large settlements noted at the southwest corner. The parking area and the driveways are showing distress as indicated by un-even surface and previous asphalt patching. The generator room is also showing separation from the main building.

The site has undergone several instances of filling. Based on the previous boring logs, it appears that 30 feet or more of fill is placed at some locations. In addition, the subgrade was not prepared for filling with the old topsoil and organics still present. We interpret that the fill slope is moving laterally. This lateral movement is causing large lateral loads on the piles. Timber piles with minimum embedment in the pile caps are not adequate to carry loads of this magnitude. The lateral movement is likely causing the piles to separate from the pile cap. This lateral movement with subsequent vertical settlement is most likely causing distress to the building as observed along the west wall.

The effect of lateral movement is more pronounced in the parking lot area with uneven settlements, several asphalt patches and movement of the generator room. These movements have also changed the drainage patterns which may explain why standing water is observed in the cleanouts.

The ODOT retaining wall was constructed per the standard plans in 1960's. Since we do not have access to as-builds, the limits and types of backfill and drainage systems are not known. The retaining wall has shown distress as evidenced by the wall separation. The retaining wall movement indicates that the slope behind the wall has moved in the past. This wall movement with subsequent slope movements could also explain some of the distress observed in the driveways and parking areas.

**Potential Remedial Options:**

Based on our review, we have discussed conceptual review options and preliminary budgets. These budgets do not include any internal building work that may be needed as part of this remediation system. The remedial options can be divided into three distinct items.

**Building Wall**– The west and south wall of the building in the impacted area is recommended to be underpinned using a micropile and grade beam system. The micropiles should be installed in groups of 2 at a spacing of approximately 6 feet on center. The first micropile installed inside the building should be vertical whereas the second micropile installed from outside the building should have a batter of 15 degrees. The micropiles should be a minimum of 8-inches in diameter with an outer casing for lateral loads installed to a minimum depth of 25 feet or possibly more in some areas. The total depth of micropile will be on the order of 45- to 50- feet. A continuous grade beam should be installed below the existing wall with the micropiles connected to it. For preliminary budget estimate, we have assumed a 200 feet length of wall will require remedial measures. The grade beam will most likely be 3 feet thick and 3- to 4- feet wide running along the entire length of the wall.

**Soldier Pile Wall for Slope Stabilization** – We recommend that a soldier pile wall system be constructed at the edge of the slope upslope from the ODOT retaining wall. The soldier pile wall system consists of steel beams installed in a drilled hole and backfilled with structural concrete. For this site, a soldier pile wall constructed from the top will be the most practical option. The soldier piles will be installed at spacing of 6- feet, with 30- to 36- inch diameter and to a depth of 45 to 50 feet. A steel beam like HP 14x117 will be placed entire depth. For preliminary budget purposes, assume that the length of this wall will be on the order of 200 feet.

**Parking Lot Reconstruction** – The district should decide on the potential use of the parking lot. If this lot will be used for bus traffic then remedial measures will be required. Most of the parking lot is located on un-documented fill. We recommend that five feet of this fill be removed. The exposed subgrade should then be compacted. A bi-axial geogrid with a geotextile composite should then be installed over the prepared subgrade. Four feet of 3" minus clean rock should then be installed over the geogrid and compacted in layers. The pavement structural section of asphalt concrete over crushed rock should then be installed. The actual design of the section should be done based on the intended use.

**Slopes on the North end of the Project:** The slopes on the north side of the property in the vicinity of the ODOT viaducts have not shown severe signs of distress and therefore were not considered in this study. We recommend that these slopes be monitored for any future signs of distress before any remedial measures are taken.

**Budget Cost Estimate:**

We have prepared budget estimates for the items mentioned above. Please note that these are “order of magnitude” numbers only. Additional geotechnical study is required to delineate the lists of stabilization areas. Calculations of building loads, micropile and/or soldier pile wall design and the parking lot design will need to be finalized before the budgets are finalized.

**Table 1: Estimated Budgets**

Item	Estimated Budget	
	Low	High
<b>Building Underpinning (Micropile Wall with new Foundation - 200 Feet of Wall)</b>		
Number of Micropiles	70 (8" Diameter, 25 Feet Cased, 45- to 50- Feet Long)	
Construction Costs	\$525,000	\$612,500
New Foundation (200L x 4 W x 3 D)	\$36,000	\$45,000
Design	\$35,000	\$45,000
Construction Engineering/Observation	\$45,000	\$55,000
<b>Sub-Total</b>	<b>\$641,000</b>	<b>\$757,500</b>
<b>Soldier Pile Wall for Slope Stabilization</b>		
Number of Soldier Piles	35 (30 Inch Diameter, 50 Feet Deep)	
Construction Costs	\$350,000	\$437,500
Design	\$40,000	\$50,000
Construction Engineering/Observation	\$30,000	\$40,000
<b>Sub-Total</b>	<b>\$420,000</b>	<b>\$527,500</b>
<b>Parking Lot Re-construction</b>		
Area	Assume 250 Feet Long by 40 Feet Wide by 5 Feet (1850 Yards)	
Construction Costs	\$138,750	\$175,750
Design and Construction Observation	\$25,000	\$35,000
<b>Sub-Total</b>	<b>\$163,750</b>	<b>\$210,750</b>
<b>Total Estimate Costs</b>	<b>\$1,224,750</b>	<b>\$1,495,750</b>
These are order of magnitude numbers only. More field work, analysis and design is required before refining these estimates		

**Additional Geotechnical Studies:**

We recommend that additional geotechnical studies be completed to better characterize the slide movement and to refine the remedial options. These studies will include installation of at least three inclinometers with vibrating wire piezometers on the downslope sections. The vibrating wire piezometers can be used to record water levels over time. Initialize these inclinometers and monitor them over the next three years on an annual frequency. We also recommend that you engage a surveyor to install some settlement monitoring points on the building, retaining walls and certain selected locations and monitor these at the same time as the inclinometers. We will select these monitoring locations in conjunction with you and the surveyors. This monitoring data will enable determination of depth, direction and rate of movement over time which will enable us to refine our stabilization approach. The services of a structural engineer will also be required as the project moves forward to design the new foundation and connection details.

**Limitations**

This letter report has been prepared for the exclusive use of the addressee for preparing budgets for this project. The opinions, comments and conclusions presented in this report were based upon information derived from our review of previous work completed at this site and also a review of previous timber pile installations. Conditions between, or beyond, the previous exploratory borings may vary from those encountered. The budgets are to be used only as an order of magnitude number. Additional field investigation and design is required to refine the remedial measures and budgets.

**Closure**

RhinoOne appreciates this opportunity to provide these services to you and look forward to future involvement in this project. If you have any questions or wish to further discuss this project, please contact me at 360.852.6367.

Sincerely,



Rajiv Ali, PE, GE  
Managing Principal  
RhinoOne Geotechnical  
rajiv@rhinooneeng.com



**Attachments:**

Figure 1: Site Plan and Current Conditions


Attachments 2: Figure 2 from KSA-1

Attachments 3-5: Sheet 1 of 9 – 1952 Tubman Site Plan


Attachments 6-7: ODOT Sheets 15552 and 15928

Attachments 8: Figure 14 from KSA-1





## Legend



Parking Area Distress

Drawing Not to Scale



4610 NE 77<sup>th</sup> Avenue, Suite 126  
Vancouver, Washington 98662  
360-258-1738

**Tubman Middle School**  
2231 N. Flint Avenue, Portland, OR 97227

Figure 1 - Current Conditions


Project No:  
PPS-2014-003

Date:  
June 2014



Drawn By:  
ST

Reviewed by:  
RA










REVISIONS	DATE	BY	APP'D.
1. SUGGESTION TO DELETE EXISTING BUILDING	10-26-52	W.C.B.	
2. SUGGESTION TO DELETE EXISTING BUILDING	10-26-52	W.C.B.	
3. SUGGESTION TO DELETE EXISTING BUILDING	10-26-52	W.C.B.	
4. SUGGESTION TO DELETE EXISTING BUILDING	10-26-52	W.C.B.	
5. SUGGESTION TO DELETE EXISTING BUILDING	10-26-52	W.C.B.	



  

<b>ELIOT ELEMENTARY SCHOOL</b>		SHEET NO. 1	
FOR		OF 13	
MULTNOMAH COUNTY SCHOOL DIST. No. 1			
LOTS 1 THROUGH 7 & 14 THROUGH 20 - BLOCK 37 - ALBINA ADDITION			
N. PAGE - FLINT AND GANTENBERG AVE. - PORTLAND, OREGON			
BURNS, BEAR, MCNEIL & SCHNEIDER			
ARCHITECTS			
2940 S. E. BELMONT ST. - PORTLAND 15, OREGON			












PLAN  
SCALE 1/4" = 10'  
SURVEYED BY MARSHALL BROS. PORTLAND, OREG. AUG. 1952  
NOTE: CONTRACTOR TO VISIT SITE TO ASCERTAIN WORK REQUIRED.



PLAN VIEW  
Scale 1"=10'-0"




ELEVATION  
Scale 1"=10'-0"




TYPICAL WALL SECTION


Note:  
All bars "a" are full height in 4 ft wall. Stop all longitudinal bars 2" cl. of contraction and expansion joints.



CONTRACTION JOINT  
Up outside face, across top and 1'-0" down back of wall.




SHEAR KEY DETAIL



EXPANSION JOINT

1/2" Premolded joint filler thru. wall and footing.  
3/4" x 1/2"  
6" rubber waterstop as manufactured by Serviced Products Corporation or approved equal. Through wall only.




TYPICAL WALL SECTION

Note:  
Final position of outside face of wall is to be vertical. Batter outside face of wall 1/8" ft. to compensate for wall rotation and deflection.

Note:  
See Dwg. # 15552 for standard retaining wall with 2:1 slope.

DATE	REVISION	OREGON STATE HIGHWAY DEPARTMENT BRIDGE DIVISION	
		RETAINING WALLS	
		EAST BANK FREEWAY SECTION	
		PLAN & ELEVATION & DETAILS	
APPROVED:		DATE: 4-5-60	SHEET: 1 OF 2
DESIGNED: RAA	CHECKED: 551	ACCOMPANIED BY DWG. NO. 15552	
DRAWN: RAA	CALC. BOOK: 551	BRIDGE NO. 8783	DRAWING NO. 15928






										Reinforcing Steel in Stem of Wall				Steel in Ftg	
H	B	C	S'	S	T	Toe Press lbs/sqft	Quan./lin. ft		Bars "a"		Bars "b" + "b" h		Bars "c"		
							Conc.	Steel	Size	Spacing	Size	Spacing	Size	Spacing	
4'-0"	4'-0"	2'-8"	6"	6"	8"	451	0.203	14.64	# 4	10"	None		# 4	12"	
6'-0"	6'-0"	3'-6"	7"	8"	6"	525	0.320	20.05	# 4	9"	"		# 4	12"	
8'-0"	7'-6"	4'-9"	8"	9"	9"	585	0.456	34.26	# 5	8"	"		# 4	12"	
10'-0"	9'-0"	4'-10"	8"	10"	10"	733	0.589	64.49	# 6	7 1/2"	# 4	18"	# 4	7"	
12'-0"	10'-6"	6'-0"	8"	1'-0"	1'-0"	806	0.785	92.46	# 7	7 1/2"	# 4	18"	# 4	6 1/2"	
14'-0"	12'-0"	6'-0"	8"	1'-0"	1'-0"	966	0.902	145.15	# 8	7"	# 4	18"	# 6	7"	
16'-0"	13'-6"	7'-4"	8"	1'-2"	1'-2"	1042	1.147	182.87	# 8	6"	# 4	18"	# 6	7"	
18'-0"	14'-6"	7'-11"	9"	1'-4"	1'-3"	1176	1.380	229.08	# 9	6 1/2"	# 4	18"	# 7	8"	
20'-0"	15'-6"	8'-6"	9"	1'-6"	1'-4"	1260	1.602	298.19	# 10	6 1/2"	# 4	18"	# 8	10"	
22'-0"	16'-6"	9'-0"	10"	1'-8"	1'-5"	1440	1.832	362.07	# 10	6"	# 4	18"	# 8	10"	
24'-0"	18'-0"	9'-6"	10"	1'-10"	1'-6"	1640	2.111	456.19	# 11	6 1/2"	# 4	18"	# 9	9 1/2"	

### DESIGN OF RETAINING WALL WITH LEVEL ROADWAY

△ TYPE A WALL

\* Note:  
All bars "a" are full  
height in 4'-0" wall.



H	B	C	S'	S	T	Toe Press lb/sq.ft.	Quan./lin. ft.	Conc.	Steel
4'-0"	3'-0"	1'-8"	6"	6"	8"	558	0.136	9.95	
6'-0"	4'-0"	2'-6"	6"	6"	8"	637	0.198	14.38	
8'-0"	5'-0"	3'-1"	8"	8"	8"	753	0.305	22.88	
10'-0"	6'-3"	3'-10"	8"	9"	9"	824	0.417	38.00	
12'-0"	7'-6"	4'-9"	8"	11"	10"	903	0.558	77.68	
14'-0"	8'-6"	5'-3"	8"	1'-0"	11"	1062	0.693	92.79	
16'-0"	9'-6"	5'-10"	8"	1'-2"	1'-0"	1203	0.863	113.83	
18'-0"	10'-6"	6'-5"	9"	1'-4"	1'-2"	1372	1.103	168.00	
20'-0"	11'-6"	7'-0"	9"	1'-6"	1'-4"	1545	1.341	207.73	
22'-0"	14'-6"	9'-0"	9"	1'-9"	1'-6"	1992	1.755	362.85	


ull  
11.

H	Reinforcing Steel in Stem of Wall		Steel in Ftg.
	Bars "a"	Bars "b" & "b" h	Bars "c"
4'-0"	#4 bars @ 12"	None	#4 bars @ 12"
6'-0"	#4 bars @ 9"	"	"
8'-0"	#5 bars @ 9"	"	"
10'-0"	#6 bars @ 8"	"	"
12'-0"	#7 bars @ 6½"	#4 bars @ 18"	"
14'-0"	#8 bars @ 8"	"	"
16'-0"	#9 bars @ 8"	"	"
18'-0"	#10 bars @ 8"	"	"
20'-0"	#10 bars @ 7"	"	"
22'-0"	#11 bars @ 6½"	"	#5 bars @ 12"


A.

### DESIGN OF RETAINING WALL WITH 2:1 SLOPE


△ TYPE B WALL



### CONTRACTION JOINT



### EXPANSION JOINT




### SHEAR KEY DETAIL


FOR INFORMATION ONLY

Final position of outside face of wall to be vertical as shown. Batter outside face of wall 1/16" per foot to compensate for wall rotation and deflection.

4" dia. weep holes at not over 30'-0" ctrs. Continuous gravel or crushed rock backing. Center of weep hole to be 6" above finish grade at face of wall.



### TYPICAL WALL SECTION



H	B	C	S'	S	T	Toe Press lb/sq.ft.	Quan./lin. ft.	Conc.	Steel
4'-0"	3'-0"	1'-6"	6"	6"	8"	578	0.136	10.52	
6'-0"	4'-0"	2'-3"	6"	6"	8"	704	0.197	16.37	
8'-0"	5'-0"	2'-10"	8"	8"	8"	875	0.304	27.14	
10'-0"	6'-0"	3'-2"	8"	10"	8"	1083	0.407	42.70	
12'-0"	7'-3"	3'-9"	8"	1'-0"	10"	1225	0.569	70.13	
14'-0"	8'-6"	4'-4"	8"	1'-2"	1'-0"	1423	0.758	107.32	
16'-0"	9'-6"	4'-8"	9"	1'-4"	1'-2"	1616	0.982	144.18	
18'-0"	10'-10"	5'-4"	9"	1'-6"	1'-2"	1834	1.168	184.43	
20'-0"	12'-0"	5'-9"	10"	1'-9"	1'-4"	2049	1.485	230.98	

H	Reinforcing Steel in Stem of Wall		Steel in Ftg
	Bars "a"	Bars "b" + "b" h	Bars "c"
4'-0"	# 4 bars @ 12"	None	# 4 bars @ 12"
6'-0"	# 4 bars @ 6 1/2"	"	"
8'-0"	# 5 bars @ 6 1/2"	"	"
10'-0"	# 6 bars @ 6 1/2"	"	"
12'-0"	# 8 bars @ 9"	# 4 bars @ 18"	"
14'-0"	# 8 bars @ 6 1/2"	"	"
16'-0"	# 8 bars @ 6 1/2"	"	"
18'-0"	# 10 bars @ 7"	"	"
20'-0"	# 10 bars @ 6"	"	"

### DESIGN OF RETAINING WALL WITH 1 1/2:1 SLOPE

△ TYPE C WALL

#### General Notes:


These walls designed with resultant of all forces striking at midpoint of base, giving uniform bearing pressure. All concrete to be class "A" and shall attain a breaking strength of 3300 p.s.i. in 28 days, ( $f_c = 1320$  p.s.i.) All reinforcing steel shall be intermediate grade deformed bars. Bars from #3 to #11 inclusive shall conform to ASTM Specification A305 and shall be lapped 20 diameters at all splices unless noted or shown otherwise. All bars shall be placed 2" clear of nearest face of concrete unless noted or shown otherwise. ( $f_s = 20,000$  p.s.i.) Place expansion joints at approx. 90' ctrs. through wall and footing and contraction joints at approx. 30' ctrs. in wall only. See Plan & Elev. for location. All workmanship and materials shall conform to the specifications for bridges of the Oregon State Highway Commission.

DATE	REVISION	OREGON STATE HIGHWAY DEPARTMENT BRIDGE DIVISION	
10-9-60	Added wall types	STANDARD RETAINING WALLS FRONT FACE VERTICAL	
10-9-60	Shear Key Detail		
WMT/3	7-12-63 add H=22' 24', Type "A"	UNIFORM BEARING	
WMT/4	9-30-63 add H=22', Type "B"		
WMT/4	7-20-64 Revised scoring detail.	DATE: 1-14-60	
CLY/4	11-21-64 Weep hole, Tilt, Trench Exc.		
APPROVED:	BRIDGE ENGINEER	SHEET _____ OF _____	
DESIGNED: MAC	CHECKED: _____		
DRAWN: MAC	CALC. BOOK: 525	BRIDGE NO. STANDARD	
		DRAWING NO. 15552	

# LEGEND

K-1 ⊕ EXPLORATORY TEST BORINGS made by KELLY/STRAZER Associates, Inc.

B-1 ⊕ PREVIOUS EXPLORATORY TEST BORINGS made by KELLY/STRAZER Associates, Inc. (refer to report dated July 21, 1980)



GRAPHIC SCALE  
32 0 32 64 FT  
1" = 32 FEET



bus loading

Kelly/Strazer Associates  
Geotechnical Consultants

HARRIET TUBMAN MIDDLE SCHOOL  
PROJECT  
Portland, Oregon

FILL THICKNESS  
ISOPACH MAP  
Mar., 1983

0-192.02

FIGURE  
14