

| | |
|-----|-----------------------|
| 268 | Marysville K-8 School |
|-----|-----------------------|

Exterior

| Deficiency | ID | Qty | UoM | Priority |
|--|------|----------|-----|----------|
| The Exterior Soffit Is Damaged And Requires Repair | 2566 | 5,000 | SF | 5 |
| Sub Total for System | | 7 | | |

Interior

| Deficiency | ID | Qty | UoM | Priority |
|---|-------|-----------|---------|----------|
| Door opening width insufficient. | 11972 | 4 | Ea. | 2 |
| Acoustical Wall Treatment is missing and is needed | 14605 | 3,960 | SF | 3 |
| Door is not equiped with Card Key Access | 17631 | 52 | Ea. | 3 |
| Interior Doors Require Replacement | 2580 | 52 | Door | 3 |
| The Carpet Flooring Is Damaged And Requires Replacement | 2575 | 12,000 | SF | 3 |
| The Ceramic Tile Flooring Is Damaged And Requires Replacement | 2578 | 5,000 | SF | 3 |
| The Vinyl Composition Tile Flooring Is Damaged And Requires Replacement | 2576 | 30,000 | SF | 3 |
| The Wood Flooring Is Damaged And Requires Replacement | 2577 | 5,000 | SF | 3 |
| Blinds are missing or in poor condition. | 14617 | 150 | SF Surf | 4 |
| Interior Ceramic Walls Require Repair Or Replacement | 2574 | 8,000 | SF Wall | 4 |
| Interior Toilet Partition Require Repair Or Replacement | 2573 | 20 | Ea. | 4 |
| Miscellaneous ADA deficiency | 11977 | 1 | Ea. | 4 |
| Interior Gypboard Walls Require Repainting | 2572 | 75,000 | SF Wall | 5 |
| Large rooms lack capacity signs. | 14618 | 8 | Ea. | 5 |
| The Acoustical Ceilings Tiles Are Damaged And Require Replacement | 2571 | 40,000 | SF | 5 |
| The Concrete Flooring Requires Repair or Repainting | 2579 | 2,000 | SF | 5 |
| Sub Total for System | | 16 | | |

Mechanical

| Deficiency | ID | Qty | UoM | Priority |
|--|------|-----------|-------|----------|
| The Air Handler HVAC Component Is Damaged And Requires Replacement | 2592 | 20,000 | CFM | 2 |
| The Boiler HVAC Component Is Damaged And Requires Replacement | 2594 | 4,620 | MBH | 2 |
| The Fan Coil HVAC Component Is Damaged And Requires Replacement | 2593 | 4 | TonAC | 2 |
| The Radiant Heat HVAC Component Is Damaged And Requires Replacement | 2595 | 38 | Ea. | 2 |
| Air Compressor is Inoperable and Requires Replacement | 2597 | 1 | Ea. | 3 |
| Kitchen Air/Exhaust Inadequate And Should Be Increased | 2588 | 4 | Ea. | 3 |
| The 4 X 6 Exhausts/Ventilators Are Missing/Damaged And Require Replacement | 2586 | 2 | Ea. | 3 |
| The Make Up Air Equipment Is Damaged And Requires Replacement | 2596 | 2 | Ea. | 3 |
| Controls Are Inadequate And Should Be Replaced With DDC Controls | 2589 | 51,684 | SF | 4 |
| The 2 X 2 Exhausts/Hoods Are Missing/Damaged And Require Replacement | 2585 | 4 | Ea. | 4 |
| Duct Cleaning Required | 2591 | 4,500 | SF | 5 |
| Sub Total for System | | 11 | | |

Electrical

| Deficiency | ID | Qty | UoM | Priority |
|---|-------|----------|-----|----------|
| Circuits need to be added to support additional outlets | 16631 | 7 | Ea. | 3 |
| Lightning Protection System is Missing and Needed | 2600 | 51,684 | SF | 3 |
| The Electrical Receptacles Are Inadequate And Require Replacement | 2602 | 20 | Ea. | 3 |
| The Mounted Building Lighting Is Damaged And Should Be Replaced | 2599 | 12 | Ea. | 3 |
| The 1 X 4 Interior Fluorescent Lighting Is Damaged And Should Be Replaced | 2601 | 300 | Ea. | 4 |
| Room does not have tamper-proof light switching. | 14608 | 1 | Ea. | 5 |
| Room has insufficient electrical outlets. | 14606 | 66 | Ea. | 5 |
| Room lacks controls to partially dim lights. | 14616 | 8 | Ea. | 5 |
| Room lighting is inadequate or in poor condition. | 14615 | 16,360 | SF | 5 |
| Sub Total for System | | 9 | | |

| | |
|-----|-----------------------|
| 268 | Marysville K-8 School |
|-----|-----------------------|

Plumbing

| Deficiency | ID | Qty | UoM | Priority |
|---|-------|-----|----------|----------|
| Completely nonaccessible toilet room. | 11973 | 1 | Ea. | 1 |
| Drinking Fountain unit not accessible. | 11978 | 1 | Ea. | 4 |
| Drinking Fountain unit not accessible. | 11979 | 2 | Ea. | 4 |
| The Non-Refrigerated Drinking Fountain is Damaged And Should Be Replaced | 2598 | 12 | Ea. | 4 |
| Room lacks a drinking fountain. | 14614 | 16 | Ea. | 5 |
| Room lacks private toilets. | 14612 | 10 | Ea. | 5 |
| The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed | 14613 | 10 | Ea. | 5 |
| Sub Total for System | | | 7 | |

Fire and Life Safety

| Deficiency | ID | Qty | UoM | Priority |
|--|-------|-----|----------|----------|
| Fire Alarm is Missing or Inadequate | 13772 | 1 | LS | 1 |
| Building not equipped with Card Key Access Control | 18067 | 1 | Ea. | 3 |
| Computer room lacks independent AC. | 18132 | 1 | Ea. | 3 |
| Sub Total for System | | | 3 | |

Technology

| Deficiency | ID | Qty | UoM | Priority |
|---|-------|-----|----------|----------|
| Administrative / Support area lacks data drop(s) | 17267 | 15 | Ea. | 3 |
| Administrative or support area lacks VOIP phone handset | 17461 | 15 | Ea. | 3 |
| Building lacks enough wireless data points | 17053 | 5 | Ea. | 3 |
| Classroom lacks technology upgrade | 14619 | 26 | Ea. | 3 |
| Room has insufficient dataports. | 14607 | 148 | Ea. | 5 |
| Sub Total for System | | | 5 | |

Conveyances

| Deficiency | ID | Qty | UoM | Priority |
|---|-------|-----|----------|----------|
| Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) | 11974 | 1 | Ea. | 1 |
| Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) | 11975 | 1 | Ea. | 1 |
| Sub Total for System | | | 2 | |

Specialties

| Deficiency | ID | Qty | UoM | Priority |
|---|-------|-----|----------|----------|
| The Base Storage Cabinets Require Replacement | 2582 | 220 | LF | 4 |
| The Upper Storage Cabinets Require Replacement | 2583 | 220 | LF | 4 |
| The Wardrobe Storage Cabinets Require Replacement | 2584 | 220 | LF | 4 |
| Room has insufficient tackboard area. | 14610 | 9 | Ea. | 5 |
| Room has insufficient writing area. | 14609 | 11 | Ea. | 5 |
| Room lacks appropriate amount of teacher storage. | 14611 | 29 | Ea. | 5 |
| Stage lacks necessary equipment. | 13952 | 1 | Ea. | 5 |
| Sub Total for System | | | 7 | |

Other

| Deficiency | ID | Qty | UoM | Priority |
|---|-------|-----|-----------|----------|
| General hazardous materials deficiency | 13687 | 1 | LS | 2 |
| Sub Total for System | | | 1 | |
| Sub Total for Building A - Main Building | | | 73 | |
| Total for Campus | | | 91 | |