

School Paint Summary

NAME	Room	Occupant type	Current condition
------	------	---------------	-------------------

Date of Re-Survey: _____

EAST SYLVAN

18- Staff Rest Room	Common area	Some peeling on lower part of interior window frame.
Cafeteria/Gym	Common area	Gym walls and window frames are intact from recent painting 2012. Wear on wall surround seating units. Front edges of seats have wear and nicks. Could be painted.
Classroom 19 and hallway	Grades 6-8	Spot peeling on exterior wall areas need to be sealed up.
East Side: Exterior	Exterior- Front of School	Bare wood and peeling paint on window frames. #3 cracking paint on entry pillars. #3 open some spots of the entry door frames. Green doors are sealed and intact- #1.
Front entry Doors- Green Color	Exterior- Front of School	Front Entry doors to school. Painted fall 2013. Found not to be lead containing paint from lab sample.
Interior Walls & classroom Window Frames	Common area	Interior walls of school are overall intact condition. Classrooms have mostly stained/varnished window frames, some are showing staining from water due to age and weathering.
Library	Common area	Wall paint in good condition. Sealed wood shelves and floor.
North Side: exterior	Exterior- Playground Area	Door and frames are intact. Cement Wall area intact.
South Side: Exterior	Exterior- Playground Area	Cracking paint on lower part of metal cafeteria window frames. Upper wood window frames have extensive peeling on 2nd story.
Stairwell by Door #3	Common area	Some spot peeling on ceiling of stairwell by door #3 at rear of school.
West Side: Exterior	Exterior- Playground Area	Extensive peeling on window frames and upper areas of siding outside classrooms. Some peeling on upper wall of outside basketball court area.