

Cascade Radon, Inc. Testing, Mitigation, Systems Design CCB 180537 / CASCARI927C1 Fed ID 26-1809992 12839 NE Airport Way Bldg. 9 Portland, Oregon 97230 Phone: (503) 421-4813 Fax: (503) 281-6170 Office@CascadeRadon.com

Jefferson High School

5210 N Kerby Ave., Portland, OR 97217

December 29, 2017





Cascade Radon, Inc. Testing, Mitigation, Systems Design CCB 180537 / CASCARI927C1 Fed ID 26-1809992 12839 NE Airport Way Bldg. 9 Portland, Oregon 97230 Phone: (503) 421-4813 Fax: (503) 281-6170 Office@CascadeRadon.com


Purpose

Initial short-term testing was performed by PBS Engineering and Environmental Inc. in 36 locations throughout the building beginning December 12, 2016 and ending December 15, 2016. Testing indicated 9.2 pCi/L in room A75 and 11 pCi/L in Office A36 of the building. In January of 2017 a follow up test was performed in these two rooms using a continuous radon monitor as a confirmation test, the result of those tests came back with a radon average of 7.9 pCi/L in room A75 and 10.7 pCi/L in the Office A36. Due to the radon averages testing twice the EPA's action level, Cascade Radon was hired to diagnose the the effected room and develop a mitigation strategy to reduce the radon levels.

The installation of two sub-slab depressurization systems was used to reduce the radon below the EPA action level of 4 pCi/L. See attached pages for a description of the system components.







System #2 mitigation fan is located on the western roof of the building. Vent piping runs down the side of the building, into the receiving room and into the faculty dining room A75. This system was painted to help it blend in on the more visible western exterior.




Suction point location in a storage coral of the wood shop.



Pressure Gauge

System #1, initial suction point is located in a storage coral in the wood shop. The vent piping continues to the fan location on the roof above. The system includes a manometer (pressure gauge), which is a simple means of seeing the system is working mechanically. A manometer also shows how much negative pressure (depressurization) the system is creating. It is understood such a pressure gauge DOES NOT monitor radon levels.



This portion of system #1 is the vent piping continuing from the suction point across the wood shop and through the roof deck to the mitigation fan on the roof.



System #2, the suction point is located in The faculty serving room adjacent to room A75. The vent piping continues to the fan located on the western roofline. The system includes a manometer (pressure gauge), which is a simple means of seeing the system is working mechanically. A manometer also shows how much negative pressure (depressurization) the system is creating. It is understood such a pressure gauge DOES NOT monitor radon levels.



Vent routing from Faculty Serving room up into the drop ceiling of the corridor.



Vent piping coming through the foundation wall from the corridor drop ceiling and into the receiving room.

Vent routing from the receiving room through the receiving corridor and to the exterior foundation wall.





Exterior vent routing to the fan location on the western roof







Credentials

Cascade Radon, Inc. 12839 NE Airport Way Bldg. 9 Portland, OR 97230 (503)421-4813 office@cascaderadon.com CCB180537 CASCARI977C1 NEHA/NRPP# 104815RMT NRSB# 1G0008

Snyder Roofing of Oregon LLC 12650 SW Hall Blvd. Tigard, OR 97223 (503)620-5252 Snyder-builds.com CCB135987

Christensen Electric, Inc. 17201 NE Sacramento Street Portland, OR 97230 (503)419-3300 info@christenson.com CCB458

Accurate Concrete Cutting 6816 NE 40th Ave. Vancouver, WA 98661 Ij@accurate-concrete-cut.com CCB191788 W.A. Contr. License# ACCURCC153M2



CASCADE RADON, INC. Testing, Mitigation, Systems Design CCB 180537 / CASCARI927C1

December 29, 2017 C-65037

- To: Portland Public Schools 501 N. Dixon Street Portland, OR 97227
- RE: Jefferson High School 5210 N Kerby Ave. Portland, OR 97217

Effective: November 30, 2017

Cascade Radon, Inc. warrants that all work has been performed in a workmanlike manner and according to the best standard practices. All materials and equipment are new, unless otherwise specified, and of first quality.

Cascade Radon, Inc. guarantees that the installation will maintain average, longterm, indoor radon levels, based upon approved 9 month duration Alpha-Track testing at or below 4 pCi/L for a period of 10 years.

With the exception of the exhaust fan unit(s), Cascade Radon, Inc. warrants that all labor, work, materials and equipment will be free from faults in material or workmanship for period of ten (10) years from the date of substantial completion.

Includes 5-year manufactures replacement warranty on exhaust fan unit(s), beginning at time of initial activation, with any related work and materials provided at no cost to the Client.

All warranties and guarantees are transferable to future owners of the same property.

Warranty or service inquires, please call (503) 421-4813

Sincerely, Wade Gervais Division Manager Cascade Radon, Inc. 12839 NE Airport Way Portland, OR 97230 Phone: (503) 421-4813 Fax: (503) 281-6170 Office@CascadeRadon.com



Performance Figures – AMG Legend, AMG Radon Extract Fan

CFM at STATIC PRESSURE in w.g.

| Model | Volts | Watts | Max. Amps | 0" | 0.5" | 0.75" | 1.0" | 1.25" | 1.5" | 1.75" | 2.0" | 2.2" | 2.4" | 2.6" |
|--------------|------------|--------|-------------|-----|------|-------|------|-------|------|-------|------|------|------|------|
| AMG Legend | 115V 60 Hz | 125 | 1.32 | 353 | 280 | 245 | 210 | 180 | 149 | 110 | 70 | 43 | 19 | 0 |
| Weight 8 lbs | 3 07 | Ean Sr | ood: 3100 m | m | | | | | | | | | l . | |


Performance shown is for installation type D-Ducted inlet, Ducted outlet.

Performance ratings do not include the effects of appurtenances in the airstream.

Speed (rpm) shown is nominal. Performance is based on actual speed of test.

The performance figures shown have been corrected to standard air density.









AMG EAGLE

Performance Figures – AMG Eagle, AMG Radon Extract Fan

CFM at STATIC PRESSURE in w.g.

| Model | Volts | Watts Ma | x. Amps | 0" | 0.5" | 0.75" | 1.0" | 1.25" | 1.5" | 1.75" | 2.0" | 2.25" | 2.5" | 2.75" | 3.0" | 3.25" | 3.5" | 3.985" |
|-------------|------------|------------------|---------|-----|------|-------|------|-------|------|-------|------|-------|------|-------|------|-------|------|--------|
| AMG Eagle 1 | 115V 60 Hz | 160 | 1.37 | 124 | 114 | 109 | 104 | 99 | 91 | 83 | 76 | 69 | 61 | 52 | 41 | 30 | 18 | 0 |
| | | - · · · · | 1 0450 | | | | | | | | | | | | | | | |

Weight 12 lbs. 1 oz. Fan Speed: 3150 rpm


Performance shown is for installation type D-Ducted inlet, Ducted outlet.

Performance ratings do not include the effects of appurtenances in the airstream.

Speed (rpm) shown is nominal. Performance is based on actual speed of test.

The performance figures shown have been corrected to standard air density.











TEST DETAILS:

Jefferson High School 5210 N Kerby Ave Portland, OR 97217 Portland Public School


Test Start Date/Time:Tuesday, November 14, 2017 // 10:07 AMTest End Date/Time:Thursday, November 16, 2017 // 10:11 AM

Location of Instrument: Woodshop Office (A41E)

Notes:

Serial#:

TEST RESULTS:



80188

Version 1.6 Page 1 of 2



INTERVAL REPORT:

| Hour T | B AC | | emp | Humd | Alpha | |
|----------------|-----------|---------------|------------|--------------|---------------|----------------|
| 1 | | 0.5 | 67 | 49 | 19 | |
| 2 3 4 | | 0.4 | 69 69 | 46 | 16 21 | |
| 3 4 | | 0.6 0.6 | 69 69 | 44 42 | 21 | |
| 5 | | 0.7 | 69 | 42 | 21 | |
| 6 | | 0.9 | 70 | 42 | 29 | |
| 7 | | 1.4 | 70 | 41 | 48 | |
| 8 | | 2.4 | 70 | 39 | 80 | |
| 9 | | 2.0 | 70 | 38 | 66 | |
| 10 | | 1.7 | 70 69 | 38 39 | 56 | |
| 11 12 | | 2.6 3.1 | 69 69 | 39 39 | 85 100 | |
| 12 | | 4.2 | 69 | 39 | 135 | |
| 14 | | 2.8 | 69 | 39 | 91 | |
| 15 | | 2.9 | 69 | 38 | 96 | |
| 16 | | 3.3 | 69 | 39 | 108 | |
| 17 | | 3.3 | 69 | 38 | 109 | |
| 18 | | 3.7 | 69 | 38 | 119 | |
| 19 20 | | 3.8 3.6 | 69 69 | 39 39 | 123 117 | |
| 20 21 | | 3.0 3.0 | 69 69 | 40 | 98 | |
| 22 | | 2.9 | 69 | 40 | 94 | |
| 23 | | 2.0 | 69 | 42 | 66 | |
| 24 | | 1.5 | 69 | 41 | 50 | |
| 25 | | 1.8 | 69 | 42 | 58 | |
| 26 | | 1.2 | 69 | 42 | 39 | |
| 27 | | 0.8 | 69 | 42 | 27 | |
| 28 | | 1.0 | 68 | 42 | 33 | |
| 29 20 | | 0.6 | 68 69 | 45 45 | 22 | |
| 30 31 | | 1.4 1.6 | 69 69 | 45 45 | 46 53 | |
| 32 | | 1.0 | 68 | 43 | 41 | |
| 33 | | 1.9 | 68 | 42 | 63 | |
| 34 | | 2.4 | 69 | 42 | 78 | |
| 35 | | 1.6 | 68 | 42 | 53 | |
| 36 | | 1.9 2.0 | 68 | 41 | 64 | |
| 37 | | 2.0 | 68 | 41 | 67 | |
| 38 | | 2.5 | 68 | 41 | 81 | |
| 39 40 | | 2.2 2.8 | 68 69 | 41 41 | 73 93 | |
| 40 41 | | 2.8 3.5 | 69 68 | 41 40 | 93 114 | |
| 42 | | 2.6 | 68 | 40 | 84 | |
| 43 | | 2.8 | 69 | 40 | 90 | |
| 44 | | 2.7 | 69 | 41 | 88 | |
| 45 | | 2.8 | 69 | 40 | 93 | |
| 46 | | 2.1 | 69 | 41 | 69 | |
| 47 | | 1.9 | 69 | 40 | 62 | |
| Ainimum: | 0.6 pCi/L | Maximun | n: | 4.2 pCi/L | | Average: |
| | | Tama | ra Linde | | | Date |
| | | | ication #: | | | Duit |
| | | | | | | |
| | | Licens | | | CCB 180537/ 0 | CASCARI927C1 |
| | | Licens | se 2: | | NRPP 1089 | 46RT, 108953RT |
| RadStar RS800 | Radon | Detector/Moni | tor | | | |
| Serial#: 01979 | Calib.#: | : 00319 Bkg | nd15 Te | st ID#: 8018 | 88 | |

Version 1.6 Page 2 of 2

2.2 pCi/L



TEST DETAILS:


Jefferson High School 5210 N Kerby Ave Portland, OR 97217 Portland Public Schools

Test Start Date/Time:Thursday, November 30, 2017 // 4:00 PMTest End Date/Time:Tuesday, December 05, 2017 // 4:00 PM

Location of Instrument: A75/Faculty Dining

Notes:

TEST RESULTS:



Version 1.6 Page 1 of 4



INTERVAL REPORT:

| Hour | Т | В | AC | pCi/L | Temp | Hun | | Alpha |
|-----------|-------|---|----------|------------|-----------|----------|----------|-------|
| 1 | | | | 0.8 | 68 | | 50 | 27 |
| 2 3 | | | | 1.1 | 71 | | 42 | 37 |
| 3 | | | | 1.6 | 72 | | 40 | 52 |
| 4 | | | | 2.0 | 72 | | 39 | 63 |
| 5 | | | | 2.2 | 73 | | 39 | 69 |
| 6 | | | | 1.8 | 73 | | 39 | 58 |
| 7 | | | | 2.0 | 73 | | 39 | 63 |
| 8 | | | | 2.8 | 73 | | 39 | 90 |
| 9 | | | | 2.4 | 73 | | 39 | 76 |
| 10 | | | | 3.0 | 73 | | 39 | 95 |
| | | | | | 72 | | | |
| 11 | | | | 2.6 | 71 | | 40 | 82 |
| 12 | | | | 2.2 | 71 | | 40 | 70 |
| 13 | | | | 2.1 | 71 | | 41 | 67 |
| 14 | | | | 2.6 | 71 | | 44 | 82 |
| 15 | | | | 2.2 | 71 | | 44 | 71 |
| 16 | | | | 2.2 | 71 | | 42 | 72 |
| 17 | | | | 1.5 | 72 | | 41 | 50 |
| 18 | | | | 1.0 | 71 | | 40 | 33 |
| 19 | | | | 1.1 | 71 | | 41 | 35 |
| 20 | | | | 0.7 | 71 | | 41 | 23 |
| 21 | | | | 0.6 | 71 | | 41 | 21 |
| 22 | | | | 0.6 | 71 | | 41 | 20 |
| | | | | 0.0 | 71 | | | |
| 23 | | | | | 71 | | 41 | 25 |
| 24 | | | | 1.6 | 71 | | 42 | 53 |
| 25 | | | | 1.5 | 71 | | 42 | 47 |
| 26 | | | | 2.3 | 71 | | 41 | 75 |
| 27 | | | | 2.3 | 70 | | 40 | 74 |
| 28 | | | | 1.6 | 71 | | 40 | 52 |
| 29 | | | | 1.8 | 70 | | 40 | 57 |
| 30 | | | | 1.8 | 71 | | 40 | 57 |
| 31 | | | | 1.2 | 70 | | 40 | 40 |
| 32 | | | | 1.7 | 71 | | 40 | 55 |
| 33 | | | | 1.9 | 71 | | 40 | 60 |
| 34 | | | | 2.4 | 71 | | 40 | 77 |
| | | | | 2.4 1.9 | 71 | | 40 | 60 |
| 35 | | | | | 71 | | | |
| 36 | | | | 2.9 | 71 | | 40 | 91 |
| 37 | | | | 1.9 | 71 | | 40 | 61 |
| 38 | | | | 1.9 | 71 | | 40 | 61 |
| 39 | | | | 2.3 | 71 | | 40 | 73 |
| 40 | | | | 2.8 | 70 | | 40 | 90 |
| 41 | | | | 2.4 | 71 | | 40 | 76 |
| 42 | | | | 2.8 | 71 | | 39 | 90 |
| 43 | | | | 2.2 | 71 | | 39 | 71 |
| 44 | | | | 3.0 | 71 | | 40 | 95 |
| 45 | | | | 2.7 | 71 | | 40 | 87 |
| 46 | | | | 2.7 | 71 | | 39 | 87 |
| 40 | | | | 2.2 | 71 | | 39 | 71 |
| 47 | | | | 2.2 | 70 | | 39 39 | 73 |
| | | | | | | | | |
| 49 | | | | 1.9 | 71 | | 38 | 61 |
| 50 | | | | 2.4 | 70 | | 38 | 76 |
| 51 | | | | 3.2 | 70 | | 38 | 102 |
| 52 | | | | 1.8 | 71 | | 38 | 57 |
| 53 | | | | 1.8 | 70 | | 38 | 59 |
| 54 | | | | 2.1 | 70 | | 37 | 67 |
| 55 | | | | 1.3 | 70 | | 38 | 42 |
| 56 | | | | 2.2 | 70 | | 38 | 72 |
| 57 | | | | 1.6 | 70 | | 37 | 52 |
| 57 | | | | 1.0 | 70 | | 57 | 52 |
| adStar RS | 5800 | | Radon I | Detector/M | onitor | | | |
| erial#: | 02395 | | Calib.#: | 00327 F | 3kgnd10 T | est ID#: | 80038 | |
| | | | | | 0 | | | |



| 58 | 1.4 | 70 | 36 | 44 |
|---|---|---|--|---|
| $\begin{array}{c} 59\\ 60\\ 61\\ 62\\ 63\\ 64\\ 65\\ 66\\ 67\\ 68\\ 69\\ 70\\ 71\\ 72\\ 73\\ 74\\ 75\\ 76\\ 77\\ 78\\ 79\\ 80\\ 81\\ 82\\ 83\\ 84\\ 85\\ 86\\ 87\\ 88\\ 89\\ 90\\ 91\\ 92\\ 93\\ 94\\ 95\\ 96\\ 97\\ 98\\ 89\\ 90\\ 91\\ 92\\ 93\\ 94\\ 95\\ 96\\ 97\\ 98\\ 99\\ 100\\ 101\\ 102\\ 103\\ 104\\ 105\\ 106\\ 107\\ 108\\ 109\\ 110\\ 111\\ 112\\ 113\\ 114\\ 115\\ 116\\ 117\\ 118\\ 119\\ \end{array}$ | $ \begin{array}{c} 1.4 \\ 1.4 \\ 1.4 \\ 1.5 \\ 1.2 \\ 1.7 \\ 0.9 \\ 1.0 \\ 1.3 \\ 1.2 \\ 1.0 \\ 1.1 \\ 1.1 \\ 1.1 \\ 1.0 \\ 0.9 \\ 0.9 \\ 0.9 \\ 0.9 \\ 0.9 \\ 0.9 \\ 0.9 \\ 0.9 \\ 0.9 \\ 0.6 \\ 1.1 \\ 0.8 \\ 0.6 \\ 0.6 \\ 1.3 \\ 0.8 \\ 0.8 \\ 1.1 \\ 0.9 \\ 1.2 \\ 1.0 \\ 1.8 \\ 1.2 \\ 0.9 \\ 0.8 \\ 1.2 \\ 0.7 \\ 1.1 \\ 0.5 \\ 0.7 \\ 1.5 \\ 2.5 \\ 1.7 \\ 1.8 \\ 2.3 \\ 2.0 \\ 2.7 \\ 3.0 \\ 3.1 \\ 3.3 \\ 3.2 \\ 4.1 \\ 2.9 \\ 3.6 \\ 3.5 \\ 2.4 \\ 1.8 \\ 1.0 \\ 1.0 \\ 1.1 \\ 1.2 \\ 1.1 \\ 1.1 \\ 1.2 \\ 1.1 \\ 1.1 \\ 1.2 \\ 1.1 \\ 1.2 \\ 1.1 \\ 1$ | 70 69 70 71 71 71 71 71 71 71 71 | 36 36 36 36 36 35 35 35 35 35 35 36 36 35 35 35 36 36 36 36 36 36 36 36 36 36 36 36 36 36 36 36 36 37 38 37 38 37 38 37 38 37 38 37 38 37 38 37 38 37 38 37 38 37 38 | $\begin{array}{c} 44\\ 44\\ 44\\ 50\\ 39\\ 54\\ 30\\ 33\\ 41\\ 40\\ 34\\ 36\\ 35\\ 34\\ 30\\ 30\\ 25\\ 31\\ 20\\ 35\\ 28\\ 19\\ 20\\ 41\\ 27\\ 27\\ 35\\ 31\\ 39\\ 34\\ 58\\ 40\\ 30\\ 26\\ 38\\ 25\\ 35\\ 31\\ 39\\ 34\\ 58\\ 40\\ 30\\ 26\\ 38\\ 25\\ 35\\ 31\\ 39\\ 34\\ 58\\ 40\\ 30\\ 26\\ 38\\ 25\\ 35\\ 31\\ 39\\ 34\\ 58\\ 40\\ 30\\ 26\\ 38\\ 25\\ 35\\ 31\\ 39\\ 34\\ 58\\ 40\\ 30\\ 26\\ 38\\ 25\\ 35\\ 31\\ 39\\ 34\\ 58\\ 40\\ 30\\ 26\\ 38\\ 25\\ 35\\ 31\\ 39\\ 34\\ 58\\ 40\\ 30\\ 26\\ 38\\ 25\\ 35\\ 35\\ 18\\ 24\\ 50\\ 79\\ 54\\ 57\\ 74\\ 64\\ 86\\ 94\\ 100\\ 106\\ 102\\ 129\\ 93\\ 114\\ 112\\ 76\\ 59\\ 32\\ 34\\ 41\\ 40\\ 37\\ 39\\ \end{array}$ |
| | Radon Detector/Monito Calib.#: 00327 Bkgno | or d10 Test ID#: | 80038 | |

Version 1.6 Page 3 of 4

| Tamara Linde Cascade Radon 12839 NE Airport W Portland, OR 97230 Phone: 503-421-4 office@cascaderador | 813 Fax: 5 | 03-281-6170 | | | | Rn | |
|--|------------|-------------|---------|-----------|-------------|----------------|-----------|
| 120 | | 1.2 | 71 | 34 | 38 | | |
| Minimum: | 0.5 pCi/L | Maximum: | | 4.1 pCi/L | | Average: | 1.7 pCi/L |
| | | Tam | ara | C Linde | | 12/6/17 | |
| | | Tamara | Linde | | | Date | |
| | | Certifica | tion #: | | | | |
| | | License | 1: | CCH | 3 180537/ 0 | CASCARI927C1 | |
| | | License | 2: | Ν | RPP 1089 | 46RT, 108953RT | |