



# ARLETA

## ACCESSIBILITY SUMMARY



Arleta School  
5109 SE 66th Avenue  
Portland, OR 97206

### SUMMARY

Most common areas at Arleta are located on the ground level, with the cafeteria in a separate building. Priority should be given to providing an elevator for second floor access to classrooms and auditorium balcony at this school. The elevator, door hardware and plumbing on floors other than the main level comprise the majority of the upgrade work. The major accessibility upgrades for Arleta are summarized on this sheet.

### ACCESSIBILITY UPGRADES TO MEET 2008 ADA GUIDELINES

Site Elements	Restripe accessible stalls and access aisle Striped accessible route Accessible path through fence to sidewalk
Accessible Route & Reach Ranges	Handrails at accessible entry stairs Partial exterior elevator access for second floor Classroom lever handle hardware Lift at stage
Plumbing Elements	Accessible boys and girls restrooms at cafeteria building Drinking fountains near gym and cafeteria
Communication Elements	Assisted listening devices at media center and auditorium Signage
Special Spaces	Auditorium balcony wheelchair seating
Recreational Facilities	Soft surface play area wheelchair accessibility

### COST BREAKDOWN

Cost information provided is based on 2009 estimated unit costs for direct construction including general contractor overhead. Additionally, estimated hard costs and soft costs provided by PPS have been included.

Site Elements	\$46,912
Accessible Route & Reach Ranges	\$446,137
Plumbing Elements	\$27,673
Communication Elements	\$12,071
Special Spaces	\$0
Built-In Elements	\$0
Recreational Facilities	\$34,821
Special Education	\$2,340
<b>Total</b>	<b>\$569,954</b>