148 Chief Joseph Elementary School

1/7/2008 1:41 PM

School and Site Level Deficiencies

Site

Deficiency	ID	Qty UoM	Priority
Ramp or ramp run not accessible.	9739	50 LF	1
K Play Area Requires Impact Resistant Material	8792	1 Ea.	2
Concrete Walks Are Damaged And Require Replacement	8790	1,000 SF	3
Asphalt Paving Is Damaged And Requires Replacement	8788	20 CAR	4
Exterior Basketball Goals Are Damaged And Require Replacement	8794	4 Ea.	4
Fencing Is Damaged And Should Be Replaced (4' Chain Link Fence)	8786	250 LF	4
Bollards Are Damaged And Require Replacement	8791	12 Ea.	5
Bus drop-off area does not have a canopy.	13972	100 LF	5
	8793	3,000 SF	5
Paved Play Requires Recoating And Resurfacing			
School lacks dedicated K playground/equipment.	13913	1 Ea.	5
School lacks marquee or marquee in poor condition.	13828	1 Ea.	5
Tree Requires Trimming	9742	20 Ea.	5
	Sub Total for System	12	
Roofing			
Deficiency	ID	Qty UoM	Priority
Awning Or Canopy Metal Roofing System Requires Replacement	9735	250 SF	3
	Sub Total for System	1	
Interior			
Deficiency	ID	Qty UoM	Priority
Handrail/Railing needs minor repairs	9732	300 LF	3
Elementary School lacks appropriate wayfinding system.	14130	1 Ea.	5
	Sub Total for System	2	
Electrical			
Deficiency	ID	Qty UoM	Priority
School site lacks appropriate lighting.	14068	10 Ea.	5
	Sub Total for System	1	
Technology			
Deficiency	ID	Qty UoM	Priority
Facility lacks centralized video distribution equipment	16785	1 Ea.	3
Facility lacks VOIP central equipment	16873	1 Ea.	3
	Sub Total for System	2	
	Sub Total for School and Site Level	18	
Building: A - Main Building			
_			
Roofing			
Deficiency	ID	Qty UoM	Priority
Edge Metal Is Loose And Should Be Resecured	8736	200 LF	2
a	Sub Total for System	1	
Structural			
Deficiency	ID	Qty_UoM	Priority
			_
LC: The Structural / Foundation Systems system is beyond its useful life.	9755	50 SF	2
	9755 Sub Total for System	50 SF 1	2
			2
Exterior			2 Priority
Exterior Deficiency	Sub Total for System	1	
LC: The Structural / Foundation Systems system is beyond its useful life. Exterior Deficiency The Aluminum Window Is Damaged And Requires Replacement The Aluminum Window Is Damaged And Requires Replacement	Sub Total for System	1 Qty_UoM	Priority

School Deficiency Listing

1/7/2008 1:41 PM

Chief Joseph Elementary School 148

Exterior

Deficiency	ID	Qty Uol	
The Wood Window Is Damaged And Requires Replacement	8805	85 Ea.	
Cementitious Waterproofing requires replacement	9748	5,000 SF	3
Exterior door hardware is damaged and should be replaced	8804	2 Ea.	
Exterior Doors is not equipped with Card Key Access	17924	18 Ea.	
The Metal Panel Exterior Is Damaged And Requires Repair	8800	200 SF	
The Wood Exterior Door Requires Repainting	8801	16 Do	
The Wood Exterior Is Damaged And Requires Repair	8799	5,000 SF	Wall 3
The Exterior Soffit Is Damaged And Requires Replacement	8798	2,500 SF	4
The Exterior Requires Cleaning	8795	500 SF	Wall 5
The Exterior Requires Painting	8797	30,000 SF	Wall 5
	Sub Total for System	13	
Interior			
Deficiency	ID	Qty Uol	M Priority
Acoustical Wall Treatment is missing and is needed	15999	912 SF	3
Door is not equiped with Card Key Access	17548	31 Ea.	3
The Carpet Flooring Is Damaged And Requires Replacement	8819	3,000 SF	3
The Vinyl Composition Tile Flooring Is Damaged And Requires Replacement	8821	1,500 SF	3
The Vinyl Composition Tile Flooring Is Damaged And Requires Replacement	9758	50 SF	3
Interior Ceramic Walls Require Repair Or Replacement	8818	200 SF	Wall 4
Interior Toilet Partition Require Repair Or Replacement	8817	4 Ea.	4
The Plaster Ceilings Are Damaged And Requires Repair	8809	500 SF	4
Classroom door lacks the appropriate vision panel.	16003	1 Ea.	5
Interior Ceilings Requires Repainting	8812	1,000 SF	5
Interior Doors Require Repainting	8823	31 Do	or 5
Interior Gypboard Walls Require Repainting	8813	6,000 SF	Wall 5
Interior Walls Require Repainting	8811	16,000 SF	5
Interior Wood Walls Require Repainting	8815	5,000 SF	Wall 5
Interior Wood Walls Require Repainting	9266	16,937 SF	Wall 5
The Acoustical Ceilings Tiles Are Damaged And Require Replacement	8807	1,000 SF	5
The Exposed Ceilings Are Damaged And Requires Repainting	8810	1,000 SF	5
	Sub Total for System	17	
Mechanical	·		
Deficiency	ID	Qty Uol	M Priority
Controls Are Inadequate And Should Be Repaired?	8840	14,937 SF	2
The Boiler HVAC Component Is Damaged And Requires Replacement	11624	2,400 MB	H 2
The Fan Coil HVAC Component Is Damaged And Requires Replacement	11625	12 Tor	
The Large Diameter Exhausts/Hoods Are Missing/Damaged And Require Replacement	8834	1 Ea.	
Air Compressor is Inoperable and Requires Replacement	8850	1 Ea.	
Kitchen Air/Exhaust Inadequate And Should Be Increased	8837	1 Ea.	
Test And Balancing Required	8839	16,937 SF	
The 2 X 4 Exhausts/Hoods Are Missing/Damaged And Require Replacement	8835	13 Ea.	
The 4 X 4 Exhausts/Hoods Are Missing/Damaged And Require Replacement	8836	13 La.	
Exhaust Fan Ventilation Is Damaged And Should Be Replaced	8845	8 Ea.	
	9727		
Exhaust Fan Ventilation Is Damaged And Should Be Replaced The Small Diameter Exhauste/Handa Are Missing/Damaged And Require Replacement		2 Ea.	
The Small Diameter Exhausts/Hoods Are Missing/Damaged And Require Replacement	8832	8 Ea.	
Duct Cleaning Required	8841	16,937 SF	
Duct Register is Damaged And Should Be Replaced	8843	24 Ea.	5

Chief Joseph Elementary School

School Deficiency Listing

1/7/2008 1:41 PM

ΝЛ	2	ha	nic	21
IVI	ᄄ	ııa	1116	aı

148

McGilailicai			
Deficiency	ID	Qty UoM	Priority
Exhaust Fan Ventilation Is Missing And Should Be Installed	8844	1 Ea.	5
	Sub Total for System	15	
Electrical			
Deficiency	ID	Qty_UoM	Priority
Circuits need to be added to support additional outlets	16687	5 Ea.	3
The Mounted Building Lighting Is Damaged And Should Be Replaced	8866	5 Ea.	3
The 1 X 4 Interior Fluorescent Lighting Is Damaged And Should Be Replaced	8868	35 Ea.	4
The Canopy Lighting Is Damaged And Should Be Replaced	8865	3 Ea.	4
Room does not have tamper-proof light switching.	16002	1 Ea.	5
Room has insufficient electrical outlets.	16000	50 Ea.	5
Room lighting is inadequate or in poor condition.	16007	10,819 SF	5
	Sub Total for System	7	
Plumbing			
Deficiency	ID	Qty UoM	Priority
Gas Piping Is Damaged And Requires Repair	8864	50 LF	1
Install Fire Sprinklers	8863	3,400 SF	3
The Toilets Plumbing Fixtures Are Damaged And Should Be Replaced	8854	17 Ea.	3
The Custodial Mop Or Service Sink Is Damaged And Should Be Replaced	8852	1 Ea.	4
The Non-Refrigerated Drinking Fountain is Damaged And Should Be Replaced	8851	6 Ea.	4
Room lacks private toilets.	16006	6 Ea.	5
The Rest Room Lavatories Plumbing Fixtures Are Damaged And Should Be Cleaned	8853	13 Ea.	5
	Sub Total for System	7	
Fire and Life Safety			
Deficiency	ID	Qty UoM	Priority
Emergency Lighting Is Inadequate Or Not Present And Should Be Installed	8869	17,000 SF	2
Computer room lacks independent AC.	18230	1 Ea.	3
	Sub Total for System	2	
Technology			
	ID	Oty HoM	Driority
Deficiency Administrative / Support area lacks data drop(s)	17154	Qty UoM 5 Ea.	Priority 3
Administrative or support area lacks VOIP phone handset	17348	5 Ea.	3
Building lacks enough wireless data points	16983	2 Ea.	3
Classroom lacks technology upgrade	16008	11 Ea.	3
Room has insufficient dataports.	16001	100 Ea.	5
	Sub Total for System	5	J
Specialties	out rotal for dystelli	3	
Specialties		o	D
Deficiency Room has insufficient tackboard area.	16005	Qty UoM 1 Ea.	Priority 5
Room has insufficient writing area.	16003	т Еа. 17 Ea.	5
v			
The Base Storage Cabinets Require Repainting	8825	350 LF	5
The Upper Storage Cabinets Require Repainting	8828	60 LF	5
The Wardrobe Storage Cabinets Require Repainting	8830	120 LF	5
	Sub Total for Building A - Main Building	5 73	
BUILDING BURGER A LUCC	Sub Total for Building A - Main Building	73	
Building: B - East Addition			
Site			

148

Chief Joseph Elementary School

School Deficiency Listing

1/7/2008 1:41 PM

	Sub Total for System	1	
Roofing			
Deficiency	ID	Qty UoM	Priority
Debris In Gutters Should Be Removed	8742	520 LF	2
dge Metal At Gutter Is Damaged And Should Be Replaced	8746	520 LF	2
Sutter Screens Are Missing And Needed	8744	520 LF	2
he Metal Downspouts Are Damaged Or Missing And Requires Replacement	8747	80 LF	3
	Sub Total for System	4	
Structural			
Deficiency	ID	Qty UoM	Priority
Chimney requires lateral bracing.	13400	1 LS	1
Vall to roof connections require enhancement	13399	1 LS	1
	Sub Total for System	2	
Exterior			
Deficiency	ID	Qty UoM	Priority
he Aluminum Window Is Damaged And Requires Replacement	8711	37 Ea.	2
he Metal Exterior Door Is Damaged And Requires Replacement	8708	5 Door	2
exterior door hardware is damaged and should be replaced	8710	5 Ea.	3
exterior Doors is not equipped with Card Key Access	17923	21 Ea.	3
exterior Metal Door Requires Repainting	8709	16 Door	3
he Exterior Requires Painting	8707	6,000 SF Wall	5
	Sub Total for System	6	
nterior			
Deficiency	ID	Qty_UoM	Priority
acoustical Wall Treatment is missing and is needed	15986	1,536 SF	3
Door is not equiped with Card Key Access	17547	45 Ea.	3
he Carpet Flooring Is Damaged And Requires Replacement	9267	2,527 SF	3
he Ceramic Tile Flooring Is Damaged And Requires Replacement	8723	1,200 SF	3
he Suspended Ceiling Grid is Damaged And Require Replacement	8713	2,000 SF	3
Blinds are missing or in poor condition.	15996	220 SF Surf	4
nterior Ceramic Walls Require Repair Or Replacement	8721	1,200 SF Wall	4
nterior Gypboard Walls Require Repair	8719	500 SF Wall	4
nterior Toilet Partition Require Repair Or Replacement	8720	4 Ea.	4
he Wood Flooring Is Damaged And Requires Repair	8722	6,000 SF	4
nterior Ceilings Requires Repainting	8717	3,000 SF	5
nterior Doors Require Repainting	8725	40 Door	5
nterior Doors Require Repair	8724	5 Door	5
nterior Millwork Requires Repainting	8718	200 LF	5
nterior Walls Require Repainting	8716	25,000 SF	5
arge rooms lack capacity signs.	15997	4 Ea.	5
The Acoustical Ceillings Tiles Are Damaged And Require Replacement	8712	12,000 SF	5
The Exposed Ceilings Are Damaged And Requires Repainting	8715	1,000 SF	5
The Plaster Ceilings Are Damaged And Requires Repainting	8714	2,000 SF	5
Somingo nilo Damagoo nila Nequitos Nepairung	Sub Total for System	2,000 SF	J
Mechanical	Jan Jan Gyotolii		
Deficiency	ID	Qty UoM	Priority
Complete HVAC Systemwide Replacement	8730	25,279 SF	2
Controls Are Inadequate And Should Be Repaired?	8734	23,279 SF	2
Citchen Fire Suppression Hood is Missing	8732	1 Ea.	2
11 ····· · · · · · · · · · · · ·	8729	1 Ea.	2

Chief Joseph Elementary School

School Deficiency Listing

1/7/2008 1:41 PM

148

Meditalioui			
Deficiency	ID	Qty UoM	Priority
Unit Ventilator requires Replacement	9729	8 Ea.	2
Kitchen Air/Exhaust is Inadequate and Should be Repaired	8731	2 Ea.	3
Test And Balancing Required	8733	25,279 SF	3
Exhaust Fan Ventilation Is Damaged And Should Be Replaced	8739	1 Ea.	4
Duct Cleaning Required	8735	18,000 SF	5
Duct Register is Damaged And Should Be Replaced	8737	40 Ea.	5
Exhaust Fan Ventilation Is Missing And Should Be Installed	8738	7 Ea.	5
	Sub Total for System	11	
Electrical			
Deficiency	ID	Qty UoM	Priority
The Mounted Building Lighting Is Damaged And Should Be Replaced	8741	6 Ea.	3
The 1 X 4 Interior Fluorescent Lighting Is Damaged And Should Be Replaced	8743	50 Ea.	4
The Canopy Lighting Is Damaged And Should Be Replaced	8740	4 Ea.	4
Room does not have tamper-proof light switching.	15990	1 Ea.	5
Room has insufficient electrical outlets.	15987	6 Ea.	5
Room lighting is inadequate or in poor condition.	15995	9,033 SF	5
	Sub Total for System	6	
Plumbing			
Deficiency	ID	Qty UoM	Priority
Completely nonaccessible toilet room.	13277	1 Ea.	1
Drinking Fountain unit not accessible.	13053	2 Ea.	4
Drinking Fountain unit not accessible.	13200	1 Ea.	4
The Refrigerated Water Cooler is Damaged And Should Be Replaced	9261	5 Ea.	4
Room lacks a drinking fountain.	15994	4 Ea.	5
	Sub Total for System	5	-
Fire and Life Safety			
•	ID	Ohr HaM	Deionitu
Deficiency Fire Alarm is Missing or Inadequate	11626	Qty UoM 25,279 SF	Priority 1
Emergency Lighting Is Inadequate Or Not Present And Should Be Installed	8745	25,000 SF	2
Building not equipped with Card Key Access Control	18009	1 Ea.	3
Computer room lacks independent AC.	18229	1 Ea.	3
Company to the acceptance of the company to the com	Sub Total for System	4	Ü
Technology	ous rotal for Oysteill	₹	
		o	D
Deficiency Administrative / Support area lacks data dron(s)	17153	Qty UoM 7 Ea.	Priority 3
Administrative / Support area lacks data drop(s)		ı ⊑a.	3
Administrative or support area lacks VOIP phone handsot		7 50	3
Administrative or support area lacks VOIP phone handset	17347	7 Ea.	3
Building lacks enough wireless data points	17347 17001	3 Ea.	3
Building lacks enough wireless data points Classroom lacks technology upgrade	17347 17001 15998	3 Ea. 8 Ea.	3
Building lacks enough wireless data points Classroom lacks technology upgrade Room has insufficient dataports.	17347 17001 15998 15988	3 Ea. 8 Ea. 24 Ea.	3 3 5
Building lacks enough wireless data points Classroom lacks technology upgrade	17347 17001 15998 15988 15989	3 Ea. 8 Ea. 24 Ea. 1 Ea.	3
Building lacks enough wireless data points Classroom lacks technology upgrade Room has insufficient dataports. Room lacks telephone wiring for VOIP system.	17347 17001 15998 15988	3 Ea. 8 Ea. 24 Ea.	3 3 5
Building lacks enough wireless data points Classroom lacks technology upgrade Room has insufficient dataports.	17347 17001 15998 15988 15989	3 Ea. 8 Ea. 24 Ea. 1 Ea.	3 3 5
Building lacks enough wireless data points Classroom lacks technology upgrade Room has insufficient dataports. Room lacks telephone wiring for VOIP system. Conveyances Deficiency	17347 17001 15998 15988 15989 Sub Total for System	3 Ea. 8 Ea. 24 Ea. 1 Ea. 6	3 5 5 Priority
Building lacks enough wireless data points Classroom lacks technology upgrade Room has insufficient dataports. Room lacks telephone wiring for VOIP system. Conveyances Deficiency Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.)	17347 17001 15998 15988 15989 Sub Total for System	3 Ea. 8 Ea. 24 Ea. 1 Ea. 6 Qty UoM 1 Ea.	3 3 5 5 5 Priority 1
Building lacks enough wireless data points Classroom lacks technology upgrade Room has insufficient dataports. Room lacks telephone wiring for VOIP system. Conveyances Deficiency Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.)	17347 17001 15998 15988 15989 Sub Total for System ID 13085	3 Ea. 8 Ea. 24 Ea. 1 Ea. 6 Qty UoM 1 Ea. 1 Ea.	3 3 5 5 5 Priority 1
Building lacks enough wireless data points Classroom lacks technology upgrade Room has insufficient dataports. Room lacks telephone wiring for VOIP system. Conveyances Deficiency Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.)	17347 17001 15998 15988 15989 Sub Total for System ID 13085 13132	3 Ea. 8 Ea. 24 Ea. 1 Ea. 6 Qty UoM 1 Ea. 1 Ea. 1 Ea.	3 3 5 5 Priority 1 1
Building lacks enough wireless data points Classroom lacks technology upgrade Room has insufficient dataports. Room lacks telephone wiring for VOIP system. Conveyances Deficiency Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.)	17347 17001 15998 15988 15989 Sub Total for System ID 13085	3 Ea. 8 Ea. 24 Ea. 1 Ea. 6 Qty UoM 1 Ea. 1 Ea.	3 3 5 5 5 Priority 1

Chief Joseph Elementary School

School Deficiency Listing

1/7/2008 1:41 PM

S	ne	cia	lti	es
v		uiu		CO

148

Deficiency	ID	Qty UoM	Priority
Room has insufficient tackboard area.	15992	6 Ea.	5
Room has insufficient writing area.	15991	17 Ea.	5
Room lacks appropriate amount of teacher storage.	15993	17 Ea.	5
Stage lacks necessary equipment.	11627	1 Ea.	5
The Base Storage Cabinets Require Repainting	8726	200 LF	5
The Upper Storage Cabinets Require Repainting	8727	35 LF	5
The Wardrobe Storage Cabinets Require Repainting	8728	70 LF	5
	Sub Total for System	7	
Other			
Deficiency	ID	Qty UoM	Priority
General hazardous materials deficiency	13649	1 LS	2
	Sub Total for System	1	

Sub Total for Building B - East Addition

Building: P1 - Portable Classroom Roofing

Deficiency	ID	Qty UoM	Priority
Shingle Roof Requires Replacement	11628	1,920 SF	1
Debris In Gutters Should Be Removed	8758	128 LF	2
Edge Metal At Gutter Is Damaged And Should Be Replaced	8763	128 LF	2
Gutters Are Damaged	8759	128 LF	2
The Metal Downspouts Are Damaged Or Missing And Requires Replacement	8765	40 LF	3
	Sub Total for System	5	

Exterior

Deficiency	ID	Qty UoM	Priority
The Wood Window Is Damaged And Requires Replacement	8751	4 Ea.	2
Exterior Doors is not equipped with Card Key Access	17922	2 Ea.	3
The Wood Exterior Door Requires Repainting	8750	2 Door	3
The Wood Exterior Is Damaged And Requires Repair	8749	200 SF Wall	3
The Exterior Requires Painting	8748	2,100 SF Wall	5
	Sub Total for System	5	

Interior

Deficiency	ID	Qty UoM	Priority
The Carpet Flooring Is Damaged And Requires Replacement	8753	900 SF	3
The Suspended Ceiling Grid is Damaged And Require Replacement	8752	1,000 SF	3
The Vinyl Composition Tile Flooring Is Damaged And Requires Replacement	8754	900 SF	3
Classroom door lacks the appropriate vision panel.	15981	2 Ea.	5
	Sub Total for System	4	

Mechanical

Deficiency	ID	Qty I	JoM F	Priority	
Controls Are Inadequate And Should Be Repaired?	8761 1,	,792	SF	2	
The Package Unit HVAC Component Is Damaged And Requires Replacement	8767	4	TonAC	2	
Test And Balancing Required	8760 1,	,792 \$	SF	3	
Duct Cleaning Required	8762 1,	,792 \$	SF	5	
Duct Grill is Damaged And Should Be Replaced	8766	2 1	Ea.	5	
Duct Register is Damaged And Should Be Replaced	8764	8 I	Ea.	5	
	Sub Total for System	6			

School Deficiency Listing

Chief Joseph Elementary School 148

1/7/2008 1:41 PM

Electrical

Deficiency	ID	Qty UoM	Priority
The Mounted Building Lighting Is Missing And Needed	8768	4 Ea.	3
	Sub Total for System	1	
Plumbing			
Deficiency	ID	Qty UoM	Priority
Room lacks a drinking fountain.	15984	2 Ea.	5
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	15983	2 Ea.	5
	Sub Total for System	2	
Technology			
Deficiency	ID	Qty UoM	Priority
Building lacks enough wireless data points	16914	1 Ea.	3
Classroom lacks technology upgrade	15985	2 Ea.	3
Room has insufficient dataports.	15980	8 Ea.	5
	Sub Total for System	3	
Specialties			
Deficiency	ID	Qty UoM	Priority
Room has insufficient writing area.	15982	6 Ea.	5
The Base Storage Cabinets Require Repainting	8755	20 LF	5
The Upper Storage Cabinets Require Repainting	8756	20 LF	5
The Wardrobe Storage Cabinets Require Repainting	8757	10 LF	5
	Sub Total for System	4	
Sub Total for	or Building P1 - Portable Classroom	30	
	Total for Campus	197	