

152

Forest Park Elementary School

2/8/2008 1:39 PM

School and Site Level Deficiencies**Site**

Deficiency	ID	Qty	UoM	Priority
Gate Is Damaged And Requires Replacement	2350	1	Ea.	4
Bus drop-off area does not have a canopy.	13973	150	LF	5
Paving Requires Restriping	2351	56	CAR	5
School lacks dedicated K playground/equipment.	13914	1	Ea.	5
School lacks marquee or marquee in poor condition.	13829	1	Ea.	5
Sub Total for System		5		

Technology

Deficiency	ID	Qty	UoM	Priority
Facility lacks centralized video distribution equipment	16784	1	Ea.	3
Facility lacks VOIP central equipment	16872	1	Ea.	3
Sub Total for System		2		
Sub Total for School and Site Level		7		

Building: A - Main Building**Site**

Deficiency	ID	Qty	UoM	Priority
Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.)	12430	20	LF	1
Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.)	12441	2	LF	1
Existing curb ramp not compliant.	12428	1	Ea.	3
Handrails missing or not compliant.	12429	80	LF	4
Sub Total for System		4		

Exterior

Deficiency	ID	Qty	UoM	Priority
Exterior Doors is not equipped with Card Key Access	17920	14	Ea.	3
Sub Total for System		1		

Interior

Deficiency	ID	Qty	UoM	Priority
Acoustical Wall Treatment is missing and is needed	15966	3,000	SF	3
Door is not equipped with Card Key Access	17545	64	Ea.	3
Elementary School lacks appropriate wayfinding system.	14131	1	Ea.	5
Large rooms lack capacity signs.	15978	6	Ea.	5
Sub Total for System		4		

Mechanical

Deficiency	ID	Qty	UoM	Priority
Exhaust Fan Ventilation Is Missing And Should Be Installed	2352	4	Ea.	5
Sub Total for System		1		

Electrical

Deficiency	ID	Qty	UoM	Priority
Circuits need to be added to support additional outlets	16686	6	Ea.	3
Lightning Protection System is Missing and Needed	2353	41,898	SF	3
Room does not have tamper-proof light switching.	15970	3	Ea.	5
Room has insufficient electrical outlets.	15967	62	Ea.	5
Room lacks controls to partially dim lights.	15977	1	Ea.	5
Sub Total for System		5		

152

Forest Park Elementary School

2/8/2008 1:39 PM

Plumbing

Deficiency	ID	Qty	UoM	Priority
Completely nonaccessible toilet room.	12439	3	Ea.	1
Drinking Fountain unit not accessible.	12442	3	Ea.	4
Drinking Fountain unit not accessible.	12443	4	Ea.	4
Room lacks a drinking fountain.	15976	14	Ea.	5
Room lacks private toilets.	15974	6	Ea.	5
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	15975	1	Ea.	5
Sub Total for System		6		

Fire and Life Safety

Deficiency	ID	Qty	UoM	Priority
Fire Alarm is Missing or Inadequate	13756	1	LS	1
PA Speakers are missing or need to be replaced	18846	8	Ea.	2
Building not equipped with Card Key Access Control	18011	1	Ea.	3
Computer room lacks independent AC.	18227	1	Ea.	3
Sub Total for System		4		

Technology

Deficiency	ID	Qty	UoM	Priority
Administrative / Support area lacks data drop(s)	17156	25	Ea.	3
Administrative or support area lacks VOIP phone handset	17350	25	Ea.	3
Building lacks enough wireless data points	17049	5	Ea.	3
Classroom lacks technology upgrade	15979	15	Ea.	3
Classroom lacks VOIP phone handset	18538	15	Ea.	3
Room has insufficient dataports.	15968	108	Ea.	5
Room lacks telephone wiring for VOIP system.	15969	1	Ea.	5
Sub Total for System		7		

Conveyances

Deficiency	ID	Qty	UoM	Priority
Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.)	12440	1	Ea.	1
Elevator Is Missing And Needed	18296	1	Ea.	1
Sub Total for System		2		

Specialties

Deficiency	ID	Qty	UoM	Priority
Room has insufficient tackboard area.	15972	5	Ea.	5
Room has insufficient writing area.	15971	2	Ea.	5
Room lacks appropriate amount of teacher storage.	15973	26	Ea.	5
Stage lacks necessary equipment.	13933	1	Ea.	5
Sub Total for System		4		
Sub Total for Building A - Main Building		38		

Building: B - Covered Play Area**Interior**

Deficiency	ID	Qty	UoM	Priority
Interior Ceilings Requires Repainting	2354	6,000	SF	5
Sub Total for System		1		

Fire and Life Safety

Deficiency	ID	Qty	UoM	Priority
PA Speakers are missing or need to be replaced	18847	1	Ea.	2
Sub Total for System		1		
Sub Total for Building B - Covered Play Area		2		

152

Forest Park Elementary School

2/8/2008 1:39 PM

Building: P1 - Portable Classroom 1**Exterior**

Deficiency	ID	Qty	UoM	Priority
Exterior Doors is not equipped with Card Key Access	17985	2	Ea.	3
Sub Total for System		1		

Interior

Deficiency	ID	Qty	UoM	Priority
Classroom door lacks the appropriate vision panel.	16585	2	Ea.	5
Sub Total for System		1		

Electrical

Deficiency	ID	Qty	UoM	Priority
Lightning Protection System is Missing and Needed	2355	1,792	SF	3
Sub Total for System		1		

Plumbing

Deficiency	ID	Qty	UoM	Priority
Room lacks a drinking fountain.	16588	1	Ea.	5
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	16587	2	Ea.	5
Sub Total for System		2		

Technology

Deficiency	ID	Qty	UoM	Priority
Building lacks enough wireless data points	16921	1	Ea.	3
Classroom lacks technology upgrade	16589	2	Ea.	3
Room has insufficient dataports.	16584	8	Ea.	5
Sub Total for System		3		

Specialties

Deficiency	ID	Qty	UoM	Priority
Room lacks appropriate amount of teacher storage.	16586	1	Ea.	5
Sub Total for System		1		
Sub Total for Building P1 - Portable Classroom 1		9		

Building: P2 - Portable 2**Exterior**

Deficiency	ID	Qty	UoM	Priority
Exterior Doors is not equipped with Card Key Access	17990	1	Ea.	3
Sub Total for System		1		

Interior

Deficiency	ID	Qty	UoM	Priority
Classroom door lacks the appropriate vision panel.	16591	2	Ea.	5
Sub Total for System		1		

Electrical

Deficiency	ID	Qty	UoM	Priority
Lightning Protection System is Missing and Needed	2356	1,792	SF	3
Sub Total for System		1		

Plumbing

Deficiency	ID	Qty	UoM	Priority
Room lacks a drinking fountain.	16595	1	Ea.	5
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	16594	2	Ea.	5
Sub Total for System		2		

152	Forest Park Elementary School
------------	--------------------------------------

Technology

Deficiency	ID	Qty	UoM	Priority
Building lacks enough wireless data points	16919	1	Ea.	3
Classroom lacks technology upgrade	16596	2	Ea.	3
Room has insufficient dataports.	16590	8	Ea.	5
Sub Total for System		3		

Specialties

Deficiency	ID	Qty	UoM	Priority
Room has insufficient tackboard area.	16592	2	Ea.	5
Room lacks appropriate amount of teacher storage.	16593	1	Ea.	5
Sub Total for System		2		
Sub Total for Building P2 - Portable 2		10		

Building: P3 - Portable 3

Exterior

Deficiency	ID	Qty	UoM	Priority
Exterior Doors is not equipped with Card Key Access	17991	1	Ea.	3
Sub Total for System		1		

Electrical

Deficiency	ID	Qty	UoM	Priority
Lightning Protection System is Missing and Needed	2357	1,792	SF	3
Sub Total for System		1		

Plumbing

Deficiency	ID	Qty	UoM	Priority
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	16599	2	Ea.	5
Sub Total for System		1		

Technology

Deficiency	ID	Qty	UoM	Priority
Building lacks enough wireless data points	16918	1	Ea.	3
Classroom lacks technology upgrade	16600	2	Ea.	3
Room has insufficient dataports.	16597	8	Ea.	5
Sub Total for System		3		

Specialties

Deficiency	ID	Qty	UoM	Priority
Room has insufficient tackboard area.	16598	4	Ea.	5
Sub Total for System		1		
Sub Total for Building P3 - Portable 3		7		

Building: P4 - Portable 4

Exterior

Deficiency	ID	Qty	UoM	Priority
Exterior Doors is not equipped with Card Key Access	17992	1	Ea.	3
Sub Total for System		1		

Interior

Deficiency	ID	Qty	UoM	Priority
Classroom door lacks the appropriate vision panel.	16602	2	Ea.	5
Sub Total for System		1		

Electrical

Deficiency	ID	Qty	UoM	Priority
Lightning Protection System is Missing and Needed	2358	1,792	SF	3
Sub Total for System		1		

152	Forest Park Elementary School
------------	--------------------------------------

Plumbing

Deficiency	ID	Qty	UoM	Priority
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	16605	2	Ea.	5
Sub Total for System		1		

Technology

Deficiency	ID	Qty	UoM	Priority
Building lacks enough wireless data points	16917	1	Ea.	3
Classroom lacks technology upgrade	16606	2	Ea.	3
Room has insufficient dataports.	16601	8	Ea.	5
Sub Total for System		3		

Specialties

Deficiency	ID	Qty	UoM	Priority
Room has insufficient tackboard area.	16603	4	Ea.	5
Room lacks appropriate amount of teacher storage.	16604	4	Ea.	5
Sub Total for System		2		
Sub Total for Building P4 - Portable 4		9		

Building: P5 - Portable 5

Exterior

Deficiency	ID	Qty	UoM	Priority
Exterior Doors is not equipped with Card Key Access	17993	1	Ea.	3
Sub Total for System		1		

Interior

Deficiency	ID	Qty	UoM	Priority
Classroom door lacks the appropriate vision panel.	16608	2	Ea.	5
Sub Total for System		1		

Electrical

Deficiency	ID	Qty	UoM	Priority
Lightning Protection System is Missing and Needed	2359	1,792	SF	3
Sub Total for System		1		

Plumbing

Deficiency	ID	Qty	UoM	Priority
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	16611	2	Ea.	5
Sub Total for System		1		

Technology

Deficiency	ID	Qty	UoM	Priority
Building lacks enough wireless data points	16916	1	Ea.	3
Classroom lacks technology upgrade	16612	2	Ea.	3
Room has insufficient dataports.	16607	8	Ea.	5
Sub Total for System		3		

Specialties

Deficiency	ID	Qty	UoM	Priority
Room has insufficient tackboard area.	16609	4	Ea.	5
Room lacks appropriate amount of teacher storage.	16610	4	Ea.	5
Sub Total for System		2		
Sub Total for Building P5 - Portable 5		9		
Total for Campus		91		