Qty UoM

ID

1/7/2008 1:59 PM

Priority

168 Kenton Elementary School

**School and Site Level Deficiencies Site** 

Deficiency

טו	Qty UoM	Priority
3287	300 LF	4
3311	1 Ea.	5
11319	43,560 SF Surf	5
3306	1 Ea.	5
Sub Total for System	4	
Sub Total for School and Site Level	4	
ID	Qty UoM	Priority
11752	13,709 SF	1
11751	6 Ea.	3
11750	1 Ea.	3
Sub Total for System	3	
ID	Qty UoM	Priority
3324	3 Door	2
3322	8 Door	2
3330	24 Ea.	2
3328	11 Ea.	3
17907	11 Ea.	3
3333	1 Ea.	3
		5
		5
		3
Sub rotation System	o	
ID	Qty UoM	Priority
		3
3336	1 Door	3
Sub Total for System	2	
ID	Qty UoM	Priority
3343	36,536 SF	4
3346	36,536 SF	5
Sub Total for System	2	
ın	Qtv UoM	Priority
3354	36,536 SF	3
Sub Total for System	1	
-		
	Ob. 11-84	Deio-ite
		Priority 4
	з Ea. 2 Ea.	4
20.40		4
3349		-
3349 Sub Total for System	2 Ea. 2	•
		•
	3287 3311 11319 3306 Sub Total for System Sub Total for School and Site Level    ID	3287   300 LF   3311

# **School Deficiency Listing**

1/7/2008 1:59 PM

Kenton Elementary School 168

Fire and Life Safety

Deficiency	ID	Qty	UoM	Priority
Computer room lacks independent AC.	18219	1	Ea.	3
	Sub Total for System	2		
Technology				
Deficiency	ID	Qty	UoM	Priority
Administrative / Support area lacks data drop(s)	17168	7	Ea.	3
Administrative or support area lacks VOIP phone handset	17362	7	Ea.	3
	Sub Total for System	2		
Conveyances				
Deficiency	ID	Qty	UoM	Priority
Elevator Is Missing And Needed	18299	1	Ea.	1
	Sub Total for System	1		
	Sub Total for Building A - Main Building	23		
Building: B - East Addition				
Roofing				
Deficiency	ID	Qty	UoM	Priority
The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement	11754	11,440		1
Overflow Drain And Piping Is Missing And Is Needed	11753	8	Ea.	3
	Sub Total for System	2		
Exterior				
Deficiency	ID	Qty	UoM	Priority
The Wood Exterior Door Is Damaged And Requires Repair	3365	2	Door	2
The Wood Window Is Damaged And Requires Replacement	3369	4	Ea.	2
Exterior Doors is not equipped with Card Key Access	17906	12	Ea.	3
The Metal Exterior Door Is Damaged And Requires Repair	3368	2	Door	3
The Exterior Requires Painting	3358	5,000	SF Wall	5
The Exterior Soffit Is Damaged And Requires Repair	3361	8,000	SF	5
	Sub Total for System	6		
Interior				
Deficiency	ID	Qty	UoM	Priority
Door is not equiped with Card Key Access	17534	8	Ea.	3
Interior Doors Require Replacement	3382	8	Door	3
The Vinyl Composition Tile Flooring Is Damaged And Requires Replacement	3376	3,500	SF	3
The Wood Flooring Is Damaged And Requires Replacement	3379	6,000	SF	3
Interior Gypboard Walls Require Repainting	3374	15,000	SF Wall	5
The Acoustical Ceilings Tiles Are Damaged And Require Replacement	3371	5,000	SF	5
	Sub Total for System	6		
Mechanical				
Deficiency	ID	Qty	UoM	Priority
Controls Are Inadequate And Should Be Replaced With DDC Controls	3387	10,655	SF	4
Exhaust Fan Ventilation Is Damaged And Should Be Replaced	11680	1	Ea.	4
Duct Cleaning Required	3389	10,655	SF	5
	Sub Total for System	3		
Fire and Life Safety				
		04	HaM	Deionite
Deficiency	ID	Qty	UoM	Priority
Deficiency Computer room lacks independent AC.	ID 18218		Ea.	3

# **School Deficiency Listing**

Kenton Elementary School 168

1/7/2008 1:59 PM

T	ec	hr	ol	0	av

Deficiency	ID	Qty UoM	Priority
Administrative / Support area lacks data drop(s)	17167	4 Ea.	3
Administrative or support area lacks VOIP phone handset	17361	4 Ea.	3
	Sub Total for System	2	
Specialties			
Deficiency	ID	Qty UoM	Priority
Stage lacks necessary equipment.	11681	1 Ea.	5
	Sub Total for System	1	
	Sub Total for Building B - East Addition	21	

# Roofing

Deficiency	ID	Qty UoM	Priority	
Gutter Joints Require Repair	11756	14 Ea.	2	
Gutters Are Damaged	11755	140 LF	2	
The Metal Downspouts Are Damaged Or Missing And Requires Replacement	11757	80 LF	3	
	Sub Total for System	3		

#### Sub Total for System

## **Exterior**

Deficiency	ID	Qty	UoM	Priority
The Wood Exterior Door Is Damaged And Requires Replacement	3402	1	Door	2
The Wood Exterior Is Damaged And Requires Replacement	3399	1,800	SF Wall	2
The Wood Window Is Damaged And Requires Replacement	3405	8	Ea.	2
Exterior Doors is not equipped with Card Key Access	17905	2	Ea.	3
The Exterior Soffit Is Damaged And Requires Replacement	3396	300	SF	4
The Exterior Requires Painting	3394	1,800	SF Wall	5
	Sub Total for System	6		

### Interior

Deficiency	ID	Qty UoM	Priority
Interior Doors Require Replacement	3413	2 Door	3
The Carpet Flooring Is Damaged And Requires Replacement	3411	1,200 SF	3
Interior Gypboard Walls Require Repainting	3410	2,500 SF Wall	5
The Acoustical Ceilings Tiles Are Damaged And Require Replacement	3408	1,200 SF	5
	Sub Total for System	4	

## Mechanical

\$	Sub Total for System	3	
Make-Up Air Inadequate And Should Be Increased	3415	1,217 SF	4
Controls Are Inadequate And Should Be Replaced With DDC Controls	3416	1,217 SF	4
The Radiant Heat HVAC Component Is Damaged And Requires Replacement	3417	2 Ea.	2
Deficiency	ID	Qty UoM	Priority

## **Electrical**

Deficiency	ID	Qty UoM	Priority	
Lightning Protection System is Missing and Needed	3426	1,217 SF	3	
The Electrical Receptacles Are Inadequate And Require Replacement	3432	4 Ea.	3	
The GFCI Electrical Receptacles Are Inadequate And More Are Needed	3433	4 Ea.	3	
The Mounted Building Lighting Is Damaged And Should Be Replaced	3424	2 Ea.	3	
The Pole Lighting Is Missing And Needed	3423	1 Ea.	3	
The 1 X 4 Interior Fluorescent Lighting Is Damaged And Should Be Replaced	3427	10 Ea.	4	
The Electrical Circuit Capacity Is Inadequate	3428	1 EACH	4	
	Sub Total for System	7		

## **School Deficiency Listing**

1/7/2008 1:59 PM 168 Kenton Elementary School

PΙ	um	bi	na

•			
Deficiency	ID	Qty UoM	Priority
The Water Heater Plumbing Fixtures Are Damaged And Should Be Replaced	3418	1 Ea.	2
The Toilets Plumbing Fixtures Are Damaged And Should Be Replaced	3421	3 Ea.	3
The Urinal Plumbing Fixtures Are Damaged And Should Be Replaced	3422	1 Ea.	3
The Non-Refrigerated Drinking Fountain is Damaged And Should Be Replaced	3419	1 Ea.	4
The Rest Room Lavatories Plumbing Fixtures Are Damaged And Should Be Replaced	3420	2 Ea.	4
	Sub Total for System	5	
Fire and Life Safety			
Deficiency	ID	Qty UoM	Priority
Fire Alarm is Missing or Inadequate	3431	1,217 SF	1
Emergency Exit Signage Is Missing And Needed	3430	2 Ea.	2
Emergency Lighting Is Inadequate Or Not Present And Should Be Installed	3429	1,217 SF	2
	Sub Total for System	3	
Technology			
Deficiency	ID	Qty UoM	Priority
Administrative / Support area lacks data drop(s)	17166	1 Ea.	3
Administrative or support area lacks VOIP phone handset	17360	1 Ea.	3
	Sub Total for System	2	
Specialties			
Deficiency	ID	Qty UoM	Priority
The Base Storage Cabinets Require Replacement	3414	10 LF	4

# **Building: P2 - Portable Classroom 2**

### **Exterior**

Deficiency	ID	Qty UoM	Priority
The Wood Exterior Door Is Damaged And Requires Replacement	3441	1 Door	2
The Wood Exterior Is Damaged And Requires Replacement	3439	1,800 SF Wall	2
The Wood Window Is Damaged And Requires Replacement	3442	8 Ea.	2
Exterior Doors is not equipped with Card Key Access	17904	2 Ea.	3
The Exterior Soffit Is Damaged And Requires Replacement	3437	300 SF	4
The Exterior Requires Painting	3435	1,800 SF Wall	5
	Sub Total for System	6	

Sub Total for System

34

Sub Total for Building P1 - Portable Classroom

## Interior

Deficiency	ID	Qty UoM	Priority
Interior Doors Require Replacement	3447	2 Door	3
The Carpet Flooring Is Damaged And Requires Replacement	3446	1,200 SF	3
Interior Gypboard Walls Require Repainting	3445	2,500 SF Wall	5
The Acoustical Ceilings Tiles Are Damaged And Require Replacement	3443	1,200 SF	5
Sub	Total for System	4	

## Mechanical

Deficiency	ID	Qty UoM	Priority
The Radiant Heat HVAC Component Is Damaged And Requires Replacement	3453	2 Ea.	2
Controls Are Inadequate And Should Be Replaced With DDC Controls	3452	1,217 SF	4
Make-Up Air Inadequate And Should Be Increased	3450	1,217 SF	4
Sub T	otal for System	3	

Kenton Elementary School

# **School Deficiency Listing**

1/7/2008 1:59 PM

168

Licoti iodi			
Deficiency	ID	Qty UoM	Priority
Lightning Protection System is Missing and Needed	3465	1,217 SF	3
The Electrical Receptacles Are Inadequate And Require Replacement	3478	4 Ea.	3
The GFCI Electrical Receptacles Are Inadequate And More Are Needed	3479	4 Ea.	3
The Mounted Building Lighting Is Damaged And Should Be Replaced	3464	2 Ea.	3
The Pole Lighting Is Missing And Needed	3462	1 Ea.	3
The 1 X 4 Interior Fluorescent Lighting Is Damaged And Should Be Replaced	3468	10 Ea.	4
The Electrical Circuit Capacity Is Inadequate	3469	1 EACH	4
	Sub Total for System	7	
Plumbing			
Deficiency	ID	Qty UoM	Priority
The Water Heater Plumbing Fixtures Are Damaged And Should Be Replaced	3456	1 Ea.	2
The Toilets Plumbing Fixtures Are Damaged And Should Be Replaced	3460	3 Ea.	3
The Urinal Plumbing Fixtures Are Damaged And Should Be Replaced	3461	1 Ea.	3
The Non-Refrigerated Drinking Fountain is Damaged And Should Be Replaced	3458	1 Ea.	4
The Rest Room Lavatories Plumbing Fixtures Are Damaged And Should Be Replaced	3459	2 Ea.	4
	Sub Total for System	5	
Fire and Life Safety			
Deficiency	ID	Qty UoM	Priority
Fire Alarm is Missing or Inadequate	3476	1,217 SF	1
Emergency Exit Signage Is Missing And Needed	3474	2 Ea.	2
Emergency Lighting Is Inadequate Or Not Present And Should Be Installed	3472	1,217 SF	2
	Sub Total for System	3	
Technology			
Deficiency	ID	Qty UoM	Priority
Administrative / Support area lacks data drop(s)	17165	1 Ea.	3
Administrative or support area lacks VOIP phone handset	17359	1 Ea.	3
	Sub Total for System	2	
Specialties			
Deficiency	ID	Qty UoM	Priority
The Base Storage Cabinets Require Replacement	3448	10 LF	4
	Sub Total for System	1	
Sub Total for Build	ing P2 - Portable Classroom 2	31	
Building: P3 - Portable Classroom 3			
Exterior			
	16	Ohr. 11-84	Delite :
Deficiency	ID	Qty UoM	Priority

Deficiency	ID	Qty UoM	Priority
The Wood Exterior Door Is Damaged And Requires Replacement	3486	2 Door	2
The Wood Exterior Is Damaged And Requires Replacement	3485	1,800 SF Wall	2
The Wood Window Is Damaged And Requires Replacement	3487	8 Ea.	2
Exterior Doors is not equipped with Card Key Access	17903	2 Ea.	3
The Exterior Soffit Is Damaged And Requires Replacement	3481	300 SF	4
The Exterior Requires Painting	3480	1,800 SF Wall	5
	Sub Total for System	6	
• . •			

## Interior

Deficiency	ID	Qty UoM	Priority	
Interior Doors Require Replacement	3491	2 Door	3	
The Vinyl Composition Tile Flooring Is Damaged And Requires Replacement	3490	1,200 SF	3	
Interior Gypboard Walls Require Repainting	3489	2,500 SF Wall	5	

Kenton Elementary School

# **School Deficiency Listing**

1/7/2008 1:59 PM

ı	n	t	ρ	rı	0	r

168

Deficiency	ID	Qty UoM	Priority
The Acoustical Ceilings Tiles Are Damaged And Require Replacement	3488	1,200 SF	5
	Sub Total for System	4	
Mechanical			
Deficiency	ID	Qty UoM	Priority
The Radiant Heat HVAC Component Is Damaged And Requires Replacement	3496	2 Ea.	2
Controls Are Inadequate And Should Be Replaced With DDC Controls	3495	1,217 SF	4
Make-Up Air Inadequate And Should Be Increased	3494	1,217 SF	4
	Sub Total for System	3	
Electrical			
Deficiency	ID	Qty UoM	Priority
Lightning Protection System is Missing and Needed	3504	1,217 SF	3
The Electrical Receptacles Are Inadequate And Require Replacement	3510	4 Ea.	3
The GFCI Electrical Receptacles Are Inadequate And More Are Needed	3511	4 Ea.	3
The Mounted Building Lighting Is Damaged And Should Be Replaced	3503	2 Ea.	3
The Pole Lighting Is Missing And Needed	3502	1 Ea.	3
The 1 X 4 Interior Fluorescent Lighting Is Damaged And Should Be Replaced	3506	10 Ea.	4
The Electrical Circuit Capacity Is Inadequate	3507	1 EACH	4
	Sub Total for System	7	
Plumbing			
Deficiency	ID	Qty UoM	Priority
The Water Heater Plumbing Fixtures Are Damaged And Should Be Replaced	3497	1 Ea.	2
The Toilets Plumbing Fixtures Are Damaged And Should Be Replaced	3500	2 Ea.	3
The Urinal Plumbing Fixtures Are Damaged And Should Be Replaced	3501	1 Ea.	3
The Non-Refrigerated Drinking Fountain is Damaged And Should Be Replaced	3498	1 Ea.	4
The Rest Room Lavatories Plumbing Fixtures Are Damaged And Should Be Replan	ced 3499	2 Ea.	4
	Sub Total for System	5	
Fire and Life Safety			
Deficiency	ID	Qty UoM	Priority
Fire Alarm is Missing or Inadequate	3509	1,217 SF	1
Emergency Lighting System Is Damaged Or Missing And Should Be Replaced	3508	1,217 SF	2
	Sub Total for System	2	
Specialties			
Deficiency	ID	Qty UoM	Priority
The Base Storage Cabinets Require Replacement	3492	10 LF	4
	Sub Total for System	1	
	Sub Total for Building P3 - Portable Classroom 3	28	
	Total for Campus	141	