

282

Scott K-8 School

### School and Site Level Deficiencies

#### Site

| Deficiency  | ID    | Qty      | UoM  | Priority |
|---|-------|----------|------|----------|
| Concrete Walks Are Damaged And Require Replacement            | 1251  | 1,000    | SF   | 3        |
| Asphalt Paving Is Damaged And Requires Replacement            | 1250  | 40       | CAR  | 4        |
| Exterior Basketball Goals Are Damaged And Require Replacement | 1253  | 4        | Ea.  | 4        |
| Bus drop-off area does not have a canopy.                     | 14016 | 150      | LF   | 5        |
| K playground not appropriately fenced or buffered.            | 14049 | 1        | Ea.  | 5        |
| Paved Play Requires Recoating And Resurfacing                 | 1135  | 4,900    | SF   | 5        |
| Paved Play Requires Restriping                                | 1252  | 30,000   | SQFT | 5        |
| School lacks marquee or marquee in poor condition.            | 13886 | 1        | Ea.  | 5        |
| <b>Sub Total for System</b>                                   |       | <b>8</b> |      |          |

#### Technology

| Deficiency  | ID    | Qty       | UoM | Priority |
|---|-------|-----------|-----|----------|
| Facility lacks centralized video distribution equipment | 16726 | 1         | Ea. | 3        |
| Facility lacks VOIP central equipment                   | 16815 | 1         | Ea. | 3        |
| <b>Sub Total for System</b>                             |       | <b>2</b>  |     |          |
| <b>Sub Total for School and Site Level</b>              |       | <b>10</b> |     |          |

### Building: A - Main Building

#### Site

| Deficiency  | ID    | Qty      | UoM | Priority |
|---|-------|----------|-----|----------|
| Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) | 11909 | 1        | LF  | 1        |
| Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) | 13096 | 1        | LF  | 1        |
| Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) | 13126 | 1        | LF  | 1        |
| Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) | 13189 | 1        | LF  | 1        |
| Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) | 13229 | 1        | LF  | 1        |
| Existing curb ramp not compliant.   | 12950 | 1        | Ea. | 3        |
| <b>Sub Total for System</b>   |       | <b>6</b> |     |          |

#### Roofing

| Deficiency                            | ID    | Qty      | UoM | Priority |
|---------------------------------------|-------|----------|-----|----------|
| Wood roof diaphragms need enhancement | 13581 | 1        | LS  | 2        |
| <b>Sub Total for System</b>           |       | <b>1</b> |     |          |

#### Structural

| Deficiency                                   | ID    | Qty      | UoM | Priority |
|--|-------|----------|-----|----------|
| Chimney requires lateral bracing.            | 13580 | 1        | LS  | 1        |
| Wall to roof connections require enhancement | 13579 | 1        | LS  | 1        |
| Wall to roof connections require enhancement | 13582 | 1        | LS  | 1        |
| <b>Sub Total for System</b>                  |       | <b>3</b> |     |          |

#### Exterior

| Deficiency   | ID    | Qty | UoM  | Priority |
|--|-------|-----|------|----------|
| The Aluminum Window Is Damaged And Requires Replacement    | 1257  | 200 | Ea.  | 2        |
| The Aluminum Window Is Damaged And Requires Replacement    | 1258  | 21  | Ea.  | 2        |
| The Aluminum Window Is Damaged And Requires Replacement    | 1259  | 5   | Ea.  | 2        |
| The Aluminum Window Is Damaged And Requires Replacement    | 1260  | 5   | Ea.  | 2        |
| The Aluminum Window Is Damaged And Requires Replacement    | 1261  | 4   | Ea.  | 2        |
| The Wood Exterior Door Is Damaged And Requires Replacement | 1255  | 46  | Door | 2        |
| Exterior door hardware is damaged and should be replaced   | 1256  | 46  | Ea.  | 3        |
| Exterior Doors is not equipped with Card Key Access        | 17777 | 46  | Ea.  | 3        |

|     |                  |
|-----|------------------|
| 282 | Scott K-8 School |
|-----|------------------|

**Exterior**

| Deficiency                     | ID   | Qty      | UoM     | Priority |
|--------------------------------|------|----------|---------|----------|
| The Exterior Requires Cleaning | 1254 | 12,000   | SF Wall | 5        |
| <b>Sub Total for System</b>    |      | <b>9</b> |         |          |

**Interior**

| Deficiency  | ID    | Qty       | UoM     | Priority |
|---|-------|-----------|---------|----------|
| Acoustical Wall Treatment is missing and is needed                      | 14467 | 744       | SF      | 3        |
| Door is not equiped with Card Key Access                                | 17622 | 80        | Ea.     | 3        |
| Interior Doors Require Replacement                                      | 1311  | 40        | Door    | 3        |
| The Carpet Flooring Is Damaged And Requires Replacement                 | 1305  | 4,000     | SF      | 3        |
| The Ceramic Tile Flooring Is Damaged And Requires Replacement           | 1308  | 2,000     | SF      | 3        |
| The Vinyl Composition Tile Flooring Is Damaged And Requires Replacement | 1306  | 40,000    | SF      | 3        |
| Blinds are missing or in poor condition.                                | 14479 | 375       | SF Surf | 4        |
| The Wood Flooring Is Damaged And Requires Repair                        | 1307  | 5,500     | SF      | 4        |
| Elementary School lacks appropriate wayfinding system.                  | 14149 | 1         | Ea.     | 5        |
| Interior Doors Require Repair   | 1310  | 40        | Door    | 5        |
| Interior Millwork Requires Repainting                                   | 1304  | 2,000     | LF      | 5        |
| Interior Walls Require Repainting                                       | 1303  | 53,800    | SF      | 5        |
| Large rooms lack capacity signs.  | 14480 | 4         | Ea.     | 5        |
| The Acoustical Ceilings Tiles Are Damaged And Require Replacement       | 1300  | 47,000    | SF      | 5        |
| The Concrete Flooring Requires Repair or Repainting                     | 1309  | 1,500     | SF      | 5        |
| The Gypboard Ceilings Are Damaged And Requires Repainting               | 1302  | 5,000     | SF      | 5        |
| The Plaster Ceilings Are Damaged And Requires Repainting                | 1301  | 5,000     | SF      | 5        |
| <b>Sub Total for System</b>   |       | <b>17</b> |         |          |

**Mechanical**

| Deficiency   | ID   | Qty       | UoM | Priority |
|--|------|-----------|-----|----------|
| Kitchen Fire Suppression Hood is Missing   | 4214 | 1         | Ea. | 2        |
| LC: The Mechanical / Steam Condensate Reliever / Reliever, Tank and Pump system is beyond its useful life. | 1318 | 1         | Ea. | 2        |
| Small HVAC Circulating Pump requies Replacement  | 9723 | 1         | Ea. | 2        |
| The Air Handler HVAC Component Is Damaged And Requires Replacement   | 1239 | 18,000    | CFM | 2        |
| The Boiler HVAC Component Is Damaged And Requires Replacement  | 1240 | 6,000     | MBH | 2        |
| The Radiant Heat HVAC Component Is Damaged And Requires Replacement  | 1241 | 64        | Ea. | 2        |
| Air Compressor is Inoperable and Requires Replacement  | 1242 | 1         | Ea. | 3        |
| Ductwork Is Damaged And Should Be Replaced   | 1236 | 1,200     | LF  | 3        |
| Kitchen Air/Exhaust Inadequate And Should Be Increased   | 1233 | 1         | Ea. | 3        |
| LC: The Mechanical / HVAC Piping / 2-Pipe Steam System (Hot) system is beyond its useful life.             | 9722 | 53,835    | SF  | 3        |
| Test And Balancing Required  | 1234 | 53,835    | SF  | 3        |
| The 4 X 6 Exhausts/Ventilators Are Missing/Damaged And Require Replacement                                 | 4218 | 1         | Ea. | 3        |
| Controls Are Inadequate And Should Be Replaced With DDC Controls   | 1235 | 53,835    | SF  | 4        |
| The 2 X 2 Exhausts/Hoods Are Missing/Damaged And Require Replacement                                       | 1231 | 2         | Ea. | 4        |
| The Small Diameter Exhausts/Hoods Are Missing/Damaged And Require Replacement                              | 1230 | 6         | Ea. | 4        |
| Duct Register is Damaged And Should Be Replaced  | 1237 | 24        | Ea. | 5        |
| Exhaust Fan Ventilation Is Missing And Should Be Installed   | 1238 | 4         | Ea. | 5        |
| <b>Sub Total for System</b>  |      | <b>17</b> |     |          |

**Electrical**

| Deficiency   | ID    | Qty   | UoM  | Priority |
|--|-------|-------|------|----------|
| The Panelboard Is Damaged And Should Be Replaced                   | 1225  | 2,400 | Amps | 2        |
| Circuits need to be added to support additional outlets            | 16624 | 4     | Ea.  | 3        |
| The Electrical Receptacles Are Inadequate And Require Replacement  | 1227  | 20    | Ea.  | 3        |
| The GFCI Electrical Receptacles Are Inadequate And More Are Needed | 1229  | 6     | Ea.  | 3        |

|     |                  |
|-----|------------------|
| 282 | Scott K-8 School |
|-----|------------------|

**Electrical**

| Deficiency  | ID    | Qty       | UoM  | Priority |
|---|-------|-----------|------|----------|
| The H.I.D. Lighting Is Damaged And Should Be Replaced                     | 1222  | 8         | Ea.  | 3        |
| The Mounted Building Lighting Is Damaged And Should Be Replaced           | 1213  | 6         | Ea.  | 3        |
| The 1 X 4 Interior Fluorescent Lighting Is Damaged And Should Be Replaced | 1221  | 85        | Ea.  | 4        |
| The Canopy Lighting Is Damaged And Should Be Replaced                     | 1212  | 5         | Ea.  | 4        |
| The Electrical Circuit Capacity Is Inadequate                             | 1226  | 20        | EACH | 4        |
| The Incandescent Lighting Is Damaged And Should Be Replaced               | 1223  | 12        | Ea.  | 4        |
| Room does not have tamper-proof light switching.                          | 14470 | 2         | Ea.  | 5        |
| Room has insufficient electrical outlets.                                 | 14468 | 36        | Ea.  | 5        |
| Room lacks controls to partially dim lights.                              | 14478 | 2         | Ea.  | 5        |
| Room lighting is inadequate or in poor condition.                         | 14477 | 21,927    | SF   | 5        |
| <b>Sub Total for System</b>   |       | <b>14</b> |      |          |

**Plumbing**

| Deficiency  | ID    | Qty       | UoM | Priority |
|---|-------|-----------|-----|----------|
| Completely nonaccessible toilet room.   | 13281 | 1         | Ea. | 1        |
| LC: The Plumbing / Domestic Water Piping System system is beyond its useful life. | 9720  | 53,835    | SF  | 3        |
| The Showers Plumbing Fixtures Are Damaged And Should Be Replaced                  | 1249  | 3         | Ea. | 3        |
| The Toilets Plumbing Fixtures Are Damaged And Should Be Replaced                  | 1247  | 20        | Ea. | 3        |
| The Urinal Plumbing Fixtures Are Damaged And Should Be Replaced                   | 1248  | 9         | Ea. | 3        |
| Drinking Fountain unit not accessible.  | 13016 | 2         | Ea. | 4        |
| Drinking Fountain unit not accessible.  | 13206 | 1         | Ea. | 4        |
| The Class Room Lavatories Plumbing Fixtures Are Damaged And Should Be Replaced    | 1244  | 19        | Ea. | 4        |
| The Custodial Mop Or Service Sink Is Damaged And Should Be Replaced               | 1245  | 4         | Ea. | 4        |
| The Non-Refrigerated Drinking Fountain is Damaged And Should Be Replaced          | 1243  | 26        | Ea. | 4        |
| The Rest Room Lavatories Plumbing Fixtures Are Damaged And Should Be Replaced     | 1246  | 19        | Ea. | 4        |
| Room lacks a drinking fountain.   | 14476 | 3         | Ea. | 5        |
| Room lacks private toilets.   | 14474 | 2         | Ea. | 5        |
| The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed   | 14475 | 1         | Ea. | 5        |
| <b>Sub Total for System</b>   |       | <b>14</b> |     |          |

**Fire and Life Safety**

| Deficiency   | ID    | Qty      | UoM | Priority |
|--|-------|----------|-----|----------|
| Fire Alarm is Missing or Inadequate                | 13776 | 1        | LS  | 1        |
| Building not equipped with Card Key Access Control | 18075 | 1        | Ea. | 3        |
| Computer room lacks independent AC.                | 18123 | 1        | Ea. | 3        |
| <b>Sub Total for System</b>                        |       | <b>3</b> |     |          |

**Technology**

| Deficiency  | ID    | Qty      | UoM | Priority |
|---|-------|----------|-----|----------|
| Administrative / Support area lacks data drop(s)        | 17279 | 13       | Ea. | 3        |
| Administrative or support area lacks VOIP phone handset | 17473 | 13       | Ea. | 3        |
| Building lacks enough wireless data points              | 17060 | 5        | Ea. | 3        |
| Classroom lacks technology upgrade                      | 14481 | 23       | Ea. | 3        |
| Room has insufficient dataports.                        | 14469 | 112      | Ea. | 5        |
| <b>Sub Total for System</b>                             |       | <b>5</b> |     |          |

**Conveyances**

| Deficiency  | ID    | Qty      | UoM | Priority |
|---|-------|----------|-----|----------|
| Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) | 13149 | 1        | Ea. | 1        |
| Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) | 13188 | 1        | Ea. | 1        |
| Elevator Is Missing And Needed  | 13020 | 1        | Ea. | 1        |
| <b>Sub Total for System</b>   |       | <b>3</b> |     |          |

|            |                         |
|------------|-------------------------|
| <b>282</b> | <b>Scott K-8 School</b> |
|------------|-------------------------|

**Specialties**

| Deficiency  | ID    | Qty      | UoM | Priority |
|---|-------|----------|-----|----------|
| The Base Storage Cabinets Require Replacement     | 1313  | 276      | LF  | 4        |
| The Upper Storage Cabinets Require Replacement    | 1314  | 276      | LF  | 4        |
| The Wardrobe Storage Cabinets Require Replacement | 1315  | 46       | LF  | 4        |
| Room has insufficient tackboard area.             | 14472 | 8        | Ea. | 5        |
| Room has insufficient writing area.               | 14471 | 54       | Ea. | 5        |
| Room lacks appropriate amount of teacher storage. | 14473 | 22       | Ea. | 5        |
| Stage lacks necessary equipment.                  | 13954 | 1        | Ea. | 5        |
| <b>Sub Total for System</b>                       |       | <b>7</b> |     |          |

**Other**

| Deficiency                                      | ID    | Qty        | UoM | Priority |
|---|-------|------------|-----|----------|
| General hazardous materials deficiency          | 13704 | 1          | LS  | 2        |
| <b>Sub Total for System</b>                     |       | <b>1</b>   |     |          |
| <b>Sub Total for Building A - Main Building</b> |       | <b>100</b> |     |          |

**Building: B - Classroom Annex**

**Exterior**

| Deficiency   | ID    | Qty      | UoM  | Priority |
|--|-------|----------|------|----------|
| The Steel Window Is Damaged And Requires Replacement     | 1168  | 36       | Ea.  | 2        |
| The Steel Window Is Damaged And Requires Replacement     | 1170  | 15       | Ea.  | 2        |
| Exterior door hardware is damaged and should be replaced | 1167  | 7        | Ea.  | 3        |
| Exterior Doors is not equipped with Card Key Access      | 17776 | 7        | Ea.  | 3        |
| Exterior Metal Door Requires Repainting                  | 1166  | 7        | Door | 3        |
| The Exterior Soffit Is Damaged And Requires Repainting   | 1165  | 700      | SF   | 5        |
| <b>Sub Total for System</b>                              |       | <b>6</b> |      |          |

**Interior**

| Deficiency  | ID    | Qty      | UoM  | Priority |
|---|-------|----------|------|----------|
| Door is not equipped with Card Key Access                               | 17621 | 15       | Ea.  | 3        |
| The Carpet Flooring Is Damaged And Requires Replacement                 | 1179  | 150      | SF   | 3        |
| The Vinyl Composition Tile Flooring Is Damaged And Requires Replacement | 1181  | 7,000    | SF   | 3        |
| Interior Doors Require Repainting                                       | 1182  | 15       | Door | 5        |
| Interior Millwork Requires Repainting                                   | 1177  | 2,000    | LF   | 5        |
| Interior Walls Require Repainting                                       | 1176  | 7,700    | SF   | 5        |
| The Acoustical Ceilings Tiles Are Damaged And Require Replacement       | 1172  | 7,000    | SF   | 5        |
| The Gypboard Ceilings Are Damaged And Requires Repainting               | 1174  | 300      | SF   | 5        |
| <b>Sub Total for System</b>   |       | <b>8</b> |      |          |

**Mechanical**

| Deficiency  | ID   | Qty      | UoM | Priority |
|---|------|----------|-----|----------|
| The Air Handler HVAC Component Is Damaged And Requires Replacement  | 1191 | 3,000    | CFM | 2        |
| The Radiant Heat HVAC Component Is Damaged And Requires Replacement | 1316 | 18       | Ea. | 2        |
| Air Compressor is Inoperable and Requires Replacement               | 1192 | 1        | Ea. | 3        |
| Ductwork Is Damaged And Should Be Replaced                          | 1187 | 200      | LF  | 3        |
| Controls Are Inadequate And Should Be Replaced With DDC Controls    | 1317 | 7,779    | SF  | 4        |
| Duct Register is Damaged And Should Be Replaced                     | 1188 | 7        | Ea. | 5        |
| Exhaust Fan Ventilation Is Missing And Should Be Installed          | 1190 | 2        | Ea. | 5        |
| <b>Sub Total for System</b>   |      | <b>7</b> |     |          |

**Electrical**

| Deficiency   | ID   | Qty | UoM  | Priority |
|--|------|-----|------|----------|
| The Panelboard Is Damaged And Should Be Replaced                   | 1204 | 200 | Amps | 2        |
| The GFCI Electrical Receptacles Are Inadequate And More Are Needed | 1205 | 6   | Ea.  | 3        |

|     |                  |
|-----|------------------|
| 282 | Scott K-8 School |
|-----|------------------|

**Electrical**

| Deficiency  | ID    | Qty   | UoM      | Priority |
|---|-------|-------|----------|----------|
| The 1 X 4 Interior Fluorescent Lighting Is Damaged And Should Be Replaced | 1203  | 16    | Ea.      | 4        |
| The Canopy Lighting Is Damaged And Should Be Replaced                     | 1201  | 2     | Ea.      | 4        |
| Room lighting is inadequate or in poor condition.                         | 14465 | 5,064 | SF       | 5        |
| <b>Sub Total for System</b>   |       |       | <b>5</b> |          |

**Plumbing**

| Deficiency   | ID   | Qty | UoM      | Priority |
|--|------|-----|----------|----------|
| The Toilets Plumbing Fixtures Are Damaged And Should Be Replaced               | 1198 | 7   | Ea.      | 3        |
| The Urinal Plumbing Fixtures Are Damaged And Should Be Replaced                | 1199 | 2   | Ea.      | 3        |
| The Class Room Lavatories Plumbing Fixtures Are Damaged And Should Be Replaced | 1194 | 6   | Ea.      | 4        |
| The Custodial Mop Or Service Sink Is Damaged And Should Be Replaced            | 1195 | 1   | Ea.      | 4        |
| The Non-Refrigerated Drinking Fountain is Damaged And Should Be Replaced       | 1193 | 6   | Ea.      | 4        |
| The Rest Room Lavatories Plumbing Fixtures Are Damaged And Should Be Replaced  | 1196 | 5   | Ea.      | 4        |
| <b>Sub Total for System</b>  |      |     | <b>6</b> |          |

**Technology**

| Deficiency  | ID    | Qty | UoM      | Priority |
|---|-------|-----|----------|----------|
| Administrative / Support area lacks data drop(s)        | 17278 | 2   | Ea.      | 3        |
| Administrative or support area lacks VOIP phone handset | 17472 | 2   | Ea.      | 3        |
| Building lacks enough wireless data points              | 16961 | 1   | Ea.      | 3        |
| Classroom lacks technology upgrade                      | 14466 | 6   | Ea.      | 3        |
| Room has insufficient dataports.                        | 14463 | 24  | Ea.      | 5        |
| <b>Sub Total for System</b>                             |       |     | <b>5</b> |          |

**Specialties**

| Deficiency  | ID    | Qty | UoM       | Priority |
|---|-------|-----|-----------|----------|
| The Base Storage Cabinets Require Replacement     | 1184  | 48  | LF        | 4        |
| The Upper Storage Cabinets Require Replacement    | 1185  | 48  | LF        | 4        |
| The Wardrobe Storage Cabinets Require Replacement | 1186  | 24  | LF        | 4        |
| Room has insufficient writing area.               | 14464 | 12  | Ea.       | 5        |
| <b>Sub Total for System</b>                       |       |     | <b>4</b>  |          |
| <b>Sub Total for Building B - Classroom Annex</b> |       |     | <b>41</b> |          |

**Building: C - Industrial Arts Building**

**Exterior**

| Deficiency   | ID    | Qty   | UoM      | Priority |
|--|-------|-------|----------|----------|
| The Aluminum Window Is Damaged And Requires Replacement  | 1142  | 16    | Ea.      | 2        |
| Exterior door hardware is damaged and should be replaced | 1141  | 4     | Ea.      | 3        |
| Exterior Doors is not equipped with Card Key Access      | 17775 | 4     | Ea.      | 3        |
| Exterior Metal Door Requires Repainting                  | 1140  | 4     | Door     | 3        |
| The Exterior Requires Painting                           | 1138  | 2,500 | SF Wall  | 5        |
| <b>Sub Total for System</b>                              |       |       | <b>5</b> |          |

**Interior**

| Deficiency  | ID    | Qty   | UoM      | Priority |
|---|-------|-------|----------|----------|
| Acoustical Wall Treatment is missing and is needed  | 14456 | 456   | SF       | 3        |
| Door is not equipped with Card Key Access           | 17620 | 5     | Ea.      | 3        |
| Interior Walls Require Repainting                   | 1143  | 2,100 | SF       | 5        |
| The Concrete Flooring Requires Repair or Repainting | 1144  | 1,500 | SF       | 5        |
| <b>Sub Total for System</b>                         |       |       | <b>4</b> |          |

**Mechanical**

| Deficiency                           | ID   | Qty   | UoM | Priority |
|--------------------------------------|------|-------|-----|----------|
| Complete HVAC Systemwide Replacement | 1145 | 2,114 | SF  | 2        |

|     |                  |
|-----|------------------|
| 282 | Scott K-8 School |
|-----|------------------|

**Mechanical**

| Deficiency   | ID   | Qty      | UoM | Priority |
|--|------|----------|-----|----------|
| Test And Balancing Required                                      | 1146 | 2,114    | SF  | 3        |
| Controls Are Inadequate And Should Be Replaced With DDC Controls | 1148 | 2,116    | SF  | 4        |
| <b>Sub Total for System</b>                                      |      | <b>3</b> |     |          |

**Electrical**

| Deficiency   | ID   | Qty      | UoM  | Priority |
|--|------|----------|------|----------|
| The Electrical Disconnect Is Damaged And Should Be Repaired        | 1159 | 200      | Amps | 2        |
| The Panelboard Is Damaged And Should Be Replaced                   | 1162 | 200      | Amps | 2        |
| The GFCI Electrical Receptacles Are Inadequate And More Are Needed | 1164 | 6        | Ea.  | 3        |
| The Mounted Building Lighting Is Damaged And Should Be Replaced    | 1157 | 3        | Ea.  | 3        |
| <b>Sub Total for System</b>  |      | <b>4</b> |      |          |

**Plumbing**

| Deficiency  | ID    | Qty      | UoM | Priority |
|---|-------|----------|-----|----------|
| The Toilets Plumbing Fixtures Are Damaged And Should Be Replaced                | 1155  | 1        | Ea. | 3        |
| The Class Room Lavatories Plumbing Fixtures Are Damaged And Should Be Replaced  | 1151  | 1        | Ea. | 4        |
| The Rest Room Lavatories Plumbing Fixtures Are Damaged And Should Be Replaced   | 1153  | 1        | Ea. | 4        |
| The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed | 14461 | 4        | Ea. | 5        |
| <b>Sub Total for System</b>   |       | <b>4</b> |     |          |

**Technology**

| Deficiency                                 | ID    | Qty      | UoM | Priority |
|--|-------|----------|-----|----------|
| Building lacks enough wireless data points | 16933 | 1        | Ea. | 3        |
| Classroom lacks technology upgrade         | 14462 | 2        | Ea. | 3        |
| Room has insufficient dataports.           | 14457 | 8        | Ea. | 5        |
| <b>Sub Total for System</b>                |       | <b>3</b> |     |          |

**Specialties**

| Deficiency   | ID    | Qty       | UoM | Priority |
|--|-------|-----------|-----|----------|
| Room has insufficient writing area.                        | 14458 | 1         | Ea. | 5        |
| Room lacks appropriate amount of teacher storage.          | 14459 | 19        | Ea. | 5        |
| Room lacks the required demonstration table.               | 14460 | 1         | Ea. | 5        |
| <b>Sub Total for System</b>                                |       | <b>3</b>  |     |          |
| <b>Sub Total for Building C - Industrial Arts Building</b> |       | <b>26</b> |     |          |

**Building: D - Covered Play Area**

**Exterior**

| Deficiency   | ID   | Qty        | UoM     | Priority |
|--|------|------------|---------|----------|
| The Exterior Requires Painting                         | 1136 | 1,000      | SF Wall | 5        |
| The Exterior Soffit Is Damaged And Requires Repainting | 1137 | 4,900      | SF      | 5        |
| <b>Sub Total for System</b>                            |      | <b>2</b>   |         |          |
| <b>Sub Total for Building D - Covered Play Area</b>    |      | <b>2</b>   |         |          |
| <b>Total for Campus</b>                                |      | <b>179</b> |         |          |