375

Whitaker Lakeside Middle School

1/7/2008 2:18 PM

School and Site Level Deficiencies

Site

| Deficiency | ID | Qty | UoM | Priority |
|---|-------------------------------------|--------|---------|----------|
| Bleachers Are Damaged And Require Replacement | 1455 | 300 | Seat | 2 |
| Concrete Walks Are Damaged And Require Replacement | 1452 | 300 | SF | 3 |
| Asphalt Paving Is Damaged And Requires Replacement | 1451 | 57 | CAR | 4 |
| Fencing Is Damaged And Should Be Replaced (8' Chain Link Fence) | 1449 | 100 | LF | 4 |
| Gate Is Damaged And Requires Replacement | 1450 | 2 | Ea. | 4 |
| Steel Covered Walkways Require Replacement | 1453 | 400 | SF | 4 |
| Bollards Are Damaged And Require Replacement | 1454 | 4 | Ea. | 5 |
| Play Field Requires Regrading | 11314 | 43,560 | SF Surf | 5 |
| | Sub Total for System | 8 | | |
| | Sub Total for School and Site Level | 8 | | |

Building: A - Main Building

Structural

Interior

| Deficiency | ID | Qty UoM | Priority | |
|-------------------------------------|----------------------|---------|----------|--|
| Concrete beam or column is spalling | 9852 | 9 Ea. | 3 | |
| | Sub Total for System | 1 | | |
| Exterior | | | | |
| Deficiency | ID | Qty UoM | Priority | |

| | ID | QUY UUW | FIIOIIty |
|---|---------------------|------------|----------|
| The Aluminum Window Is Damaged And Requires Replacement | 1458 | 46 Ea. | 2 |
| Exterior Doors is not equipped with Card Key Access | 17731 | 25 Ea. | 3 |
| The Brick Exterior Is Damaged And Requires Replacement | 1457 | 30 SF Wall | 4 |
| Si | ub Total for System | 3 | |

| Deficiency | ID | Qty UoM | Priority |
|---|----------------------|------------|----------|
| Door is not equiped with Card Key Access | 17591 | 77 Ea. | 3 |
| The Carpet Flooring Is Damaged And Requires Replacement | 1465 | 1,500 SF | 3 |
| The Vinyl Composition Tile Flooring Is Damaged And Requires Replacement | 1466 | 2,310 SF | 3 |
| nterior Gypboard Walls Require Repair | 1463 | 10 SF Wall | 4 |
| The Wood Flooring Is Damaged And Requires Repair | 1467 | 900 SF | 4 |
| nterior Doors Require Repainting | 1469 | 77 Door | 5 |
| nterior Toilet Partition Require Repainting | 1464 | 75 SF Wall | 5 |
| nterior Walls Require Repainting | 1462 | 300 SF | 5 |
| he Acoustical Ceilings Tiles Are Damaged And Require Replacement | 1459 | 3,440 SF | 5 |
| he Concrete Flooring Requires Repair or Repainting | 1468 | 1,050 SF | 5 |
| he Exposed Ceilings Are Damaged And Requires Repainting | 1461 | 4,000 SF | 5 |
| he Plaster Ceilings Are Damaged And Requires Repainting | 1460 | 100 SF | 5 |
| | Sub Total for System | 12 | |

Mechanical

| Deficiency | ID | Qty UoM | Priority |
|---|------|------------|----------|
| Kitchen Fire Suppression Hood is Missing | 4215 | 1 Ea. | 2 |
| LC: The Mechanical / Radiant Heaters (Count Basis) / Fin Tube - Water system is beyond its useful life. | 9855 | 5 Ea. | 2 |
| Small HVAC Circulating Pump requies Replacement | 9854 | 5 Ea. | 2 |
| The Air Handler HVAC Component Is Damaged And Requires Replacement | 1482 | 20,000 CFM | 2 |
| The Boiler HVAC Component Is Damaged And Requires Replacement | 1484 | 4,000 MBH | 2 |
| The Chiller HVAC Component Is Damaged And Requires Replacement | 1483 | 70 TonAC | 2 |
| The Cooling Tower Should Be Drained And Recharged | 1474 | 90 TonAC | 2 |
| The Exterior Condenser Is Damaged And Requires Replacement | 1510 | 70 TonAC | 2 |

Whitaker Lakeside Middle School

School Deficiency Listing

375

1/7/2008 2:18 PM

Mechanical

Electrical

| Deficiency | ID | Qty UoM | Priority |
|---|----------------------|-----------|----------|
| The Exterior Cooling Tower Is Damaged And Requires Replacement | 1473 | 90 TonAC | 2 |
| The Fan Coil HVAC Component Is Damaged And Requires Replacement | 1481 | 45 TonAC | 2 |
| The Large Diameter Exhausts/Hoods Are Missing/Damaged And Require Replacement | 1476 | 1 Ea. | 2 |
| The Radiant Heat HVAC Component Is Damaged And Requires Replacement | 1485 | 6 Ea. | 2 |
| Controls Are Inadequate And Should Be Replaced With DDC Controls | 1478 | 40,572 SF | 4 |
| Make-Up Air Inadequate And Should Be Increased | 1477 | 900 SF | 4 |
| The Small Diameter Exhausts/Hoods Are Missing/Damaged And Require Replacement | 1475 | 3 Ea. | 4 |
| Duct Grill is Damaged And Should Be Replaced | 1480 | 10 Ea. | 5 |
| Duct Register is Damaged And Should Be Replaced | 1479 | 10 Ea. | 5 |
| | Sub Total for System | 17 | |

| Deficiency | ID | Qty UoM | Priority |
|---|----------------------|------------|----------|
| Generator Is Damaged And Requires Replacement | 1495 | 20 KW | 1 |
| The Electrical Transformer Is Damaged And Should Be Replaced | 1500 | 30 KVA | 2 |
| The Panelboard Is Damaged And Should Be Replaced | 1501 | 3,000 Amps | 2 |
| The Power Service Is Inadequate And Should Be Replaced | 4201 | 2,000 Amps | 2 |
| The Electrical Receptacles Are Inadequate And Require Replacement | 1504 | 10 Ea. | 3 |
| The GFCI Electrical Receptacles Are Inadequate And More Are Needed | 1505 | 5 Ea. | 3 |
| The Mounted Building Lighting Is Damaged And Should Be Replaced | 1494 | 16 Ea. | 3 |
| The 1 X 4 Interior Fluorescent Lighting Is Damaged And Should Be Replaced | 1496 | 23 Ea. | 4 |
| The 2 X 4 Interior Fluorescent Lighting Is Damaged And Should Be Replaced | 1497 | 33 Ea. | 4 |
| The Canopy Lighting Is Damaged And Should Be Replaced | 1493 | 22 Ea. | 4 |
| The Electrical Circuit Capacity Is Inadequate | 1502 | 10 EACH | 4 |
| The Incandescent Lighting Is Damaged And Should Be Replaced | 1498 | 21 Ea. | 4 |
| | Sub Total for System | 12 | |

Plumbing

| Deficiency | ID | Qty UoM | Priority |
|--|----------------------|---------|----------|
| The Showers Plumbing Fixtures Are Damaged And Should Be Replaced | 1492 | 4 Ea. | 3 |
| The Toilets Plumbing Fixtures Are Damaged And Should Be Replaced | 1490 | 23 Ea. | 3 |
| The Urinal Plumbing Fixtures Are Damaged And Should Be Replaced | 1491 | 10 Ea. | 3 |
| The Class Room Lavatories Plumbing Fixtures Are Damaged And Should Be Replaced | 1487 | 15 Ea. | 4 |
| The Custodial Mop Or Service Sink Is Damaged And Should Be Replaced | 1488 | 2 Ea. | 4 |
| The Non-Refrigerated Drinking Fountain is Damaged And Should Be Replaced | 1486 | 27 Ea. | 4 |
| The Rest Room Lavatories Plumbing Fixtures Are Damaged And Should Be Replaced | 1489 | 22 Ea. | 4 |
| | Sub Total for System | 7 | |

| 5 | | | | |
|---|----------------------|-----------|----------|---|
| Deficiency | ID | Qty UoM | Priority | _ |
| Emergency Lighting Is Inadequate Or Not Present And Should Be Installed | 1503 | 40,572 SF | 2 | |
| Computer room lacks independent AC. | 18100 | 1 Ea. | 3 | |
| | Sub Total for System | 2 | | |

Technology

Fire and Life Safety

| Deficiency | ID | Qty UoM | Priority |
|---|----------------------|---------|----------|
| Administrative / Support area lacks data drop(s) | 17309 | 10 Ea. | 3 |
| Administrative or support area lacks VOIP phone handset | 17503 | 10 Ea. | 3 |
| | Sub Total for System | 2 | |
| Conveyances | | | |
| Deficiency | ID | Qty UoM | Priority |
| Elevator Is Missing And Needed | 17515 | 1 Ea. | 1 |

School Deficiency Listing

1

1/7/2008 2:18 PM

| Specialties | | | |
|--|--|---------|----------|
| Deficiency | ID | Qty UoM | Priority |
| The Base Storage Cabinets Require Replacement | 1470 | 4 LF | 4 |
| Stage lacks necessary equipment. | 11287 | 1 Ea. | 5 |
| The Base Storage Cabinets Require Repainting | 1471 | 182 LF | 5 |
| The Wardrobe Storage Cabinets Require Repainting | 1472 | 54 LF | 5 |
| | Sub Total for System | 4 | |
| | Sub Total for Building A - Main Building | 61 | |

Sub Total for System

Building: B - East Building

Exterior

Interior

| Deficiency | ID | Qty UoM | Priority |
|---|----------------------|---------------|----------|
| The Aluminum Window Is Damaged And Requires Replacement | 1424 | 1 Ea. | 2 |
| The Aluminum Window Is Damaged And Requires Replacement | 1425 | 38 Ea. | 2 |
| The Wood Window Is Damaged And Requires Replacement | 1422 | 51 Ea. | 2 |
| The Wood Window Is Damaged And Requires Replacement | 1423 | 6 Ea. | 2 |
| Exterior Doors is not equipped with Card Key Access | 17730 | 6 Ea. | 3 |
| The Wood Exterior Door Requires Repainting | 1421 | 6 Door | 3 |
| The Exterior Requires Painting | 1420 | 1,000 SF Wall | 5 |
| | Sub Total for System | 7 | |

| Deficiency | ID | Qty Uo | M Priority |
|---|----------------------|-----------|------------|
| Door is not equiped with Card Key Access | 17590 | 17 Ea. | 3 |
| The Carpet Flooring Is Damaged And Requires Replacement | 1429 | 100 SF | 3 |
| The Vinyl Composition Tile Flooring Is Damaged And Requires Replacement | 1430 | 6,000 SF | 3 |
| Interior Doors Require Repainting | 1433 | 17 Do | or 5 |
| Interior Walls Require Repainting | 1428 | 11,978 SF | 5 |
| The Acoustical Ceilings Tiles Are Damaged And Require Replacement | 1426 | 4,500 SF | 5 |
| The Gypboard Ceilings Are Damaged And Requires Repainting | 1427 | 500 SF | 5 |
| | Sub Total for System | 7 | |

| Mechanical | | | |
|---|----------------------|-----------|----------|
| Deficiency | ID | Qty UoM | Priority |
| The Radiant Heat HVAC Component Is Damaged And Requires Replacement | 1436 | 16 Ea. | 2 |
| Controls Are Inadequate And Should Be Replaced With DDC Controls | 1434 | 11,978 SF | 4 |
| Exhaust Fan Ventilation Is Missing And Should Be Installed | 1435 | 2 Ea. | 5 |
| | Sub Total for System | 3 | |

Electrical

| Deficiency | ID | Qty UoM | Priority |
|---|----------------------|------------|----------|
| The Panelboard Is Damaged And Should Be Replaced | 1444 | 1,000 Amps | 2 |
| The Power Service Is Inadequate And Should Be Replaced | 4202 | 800 Amps | 2 |
| The GFCI Electrical Receptacles Are Inadequate And More Are Needed | 1448 | 2 Ea. | 3 |
| The 1 X 4 Interior Fluorescent Lighting Is Damaged And Should Be Replaced | 1445 | 8 Ea. | 4 |
| The Electrical Circuit Capacity Is Inadequate | 1446 | 5 EACH | 4 |
| | Sub Total for System | 5 | |

Plumbing

| Deficiency | ID | Qty UoM | Priority |
|--|------|-----------|----------|
| Install Fire Sprinklers | 1443 | 11,978 SF | 3 |
| The Toilets Plumbing Fixtures Are Damaged And Should Be Replaced | 1441 | 5 Ea. | 3 |
| The Urinal Plumbing Fixtures Are Damaged And Should Be Replaced | 1442 | 3 Ea. | 3 |
| The Class Room Lavatories Plumbing Fixtures Are Damaged And Should Be Replaced | 1438 | 6 Ea. | 4 |

School Deficiency Listing

1/7/2008 2:18 PM

375 Whitaker Lakeside Middle School

Plumbing

| Fiumping | | | |
|---|----------------------|-----------|----------|
| Deficiency | ID | Qty UoM | Priority |
| The Custodial Mop Or Service Sink Is Damaged And Should Be Replaced | 1439 | 1 Ea. | 4 |
| The Non-Refrigerated Drinking Fountain is Damaged And Should Be Replaced | 1437 | 7 Ea. | 4 |
| The Rest Room Lavatories Plumbing Fixtures Are Damaged And Should Be Replaced | 1440 | 4 Ea. | 4 |
| | Sub Total for System | 7 | |
| Fire and Life Safety | | | |
| Deficiency | ID | Qty UoM | Priority |
| Emergency Lighting Is Inadequate Or Not Present And Should Be Installed | 1447 | 11,978 SF | 2 |
| Building not equipped with Card Key Access Control | 18096 | 1 Ea. | 3 |
| Computer room lacks independent AC. | 18099 | 1 Ea. | 3 |
| | Sub Total for System | 3 | |
| Technology | | | |
| Deficiency | ID | Qty UoM | Priority |
| | 17000 | | |

| Administrative / Support area lacks data drop(s) | 17308 | 2 Ea. | 3 |
|---|----------------------|-------|---|
| Administrative or support area lacks VOIP phone handset | 17502 | 2 Ea. | 3 |
| | Sub Total for System | 2 | |

Specialties

| Deficiency | ID | Qty UoM | Priority |
|--|--|---------|----------|
| The Base Storage Cabinets Require Repainting | 1432 | 48 LF | 5 |
| | Sub Total for System | 1 | |
| | Sub Total for Building B - East Building | 35 | |

Building: C - North Building

Exterior

| Deficiency | ID | Qty | UoM | Priority |
|--|----------------------|-------|---------|----------|
| The Glass Pane Is Damaged In The Exterior Window: | 1410 | 2 | SF | 2 |
| Exterior door hardware is damaged and should be replaced | 1409 | 2 | Ea. | 3 |
| Exterior Doors is not equipped with Card Key Access | 17729 | 8 | Ea. | 3 |
| Exterior Metal Door Requires Repainting | 1408 | 8 | Door | 3 |
| The Concrete / CMU Exterior Is Damaged And Requires Repair | 1407 | 40 | SF Wall | 4 |
| The Exterior Requires Cleaning | 1405 | 8,000 | SF Wall | 5 |
| The Exterior Requires Painting | 1406 | 8,000 | SF Wall | 5 |
| | Sub Total for System | 7 | | |

Interior

| Deficiency | ID | Qty UoM | Priority |
|---|----------------------|----------|----------|
| Door is not equiped with Card Key Access | 17589 | 15 Ea. | 3 |
| The Carpet Flooring Is Damaged And Requires Replacement | 1413 | 3,600 SF | 3 |
| Interior Walls Require Repainting | 1415 | 4,500 SF | 5 |
| The Acoustical Ceilings Tiles Are Damaged And Require Replacement | 1411 | 4,300 SF | 5 |
| The Exposed Ceilings Are Damaged And Requires Repainting | 1412 | 3,600 SF | 5 |
| | Sub Total for System | 5 | |

Mechanical

| Deficiency | ID | Qty UoM | Priority |
|--|----------------------|----------|----------|
| Package Roof Top Unit Is Damaged And Requires Replacement | 1416 | 2 TonAC | 2 |
| Test And Balancing Required | 1417 | 9,775 SF | 3 |
| Controls Are Inadequate And Should Be Replaced With DDC Controls | 1418 | 9,775 SF | 4 |
| | Sub Total for System | 3 | |
| Electrical | | | |
| Deficiency | ID | Qty UoM | Priority |

School Deficiency Listing

1/7/2008 2:18 PM

375 Whitaker Lakeside Middle School

Electrical

| Deficiency | ID | Qty UoM | Priority |
|--|-----------------------------|---------------|----------|
| he Power Service Is Inadequate And Should Be Replaced | 4203 | 600 Amps | 2 |
| | Sub Total for System | 1 | |
| Plumbing | | | |
| Deficiency | ID | Qty UoM | Priority |
| LC: The Plumbing / Domestic Water Piping System system is beyond its useful life. | 1507 | 9,775 SF | 3 |
| LC: The Plumbing / Faucets & Fixt (Count Basis) / Faucets and Fixtures system is beyond its useful life. | 1506 | 1 Ea. | 3 |
| | Sub Total for System | 2 | |
| Fire and Life Safety | | | |
| Deficiency | ID | Qty UoM | Priority |
| Fire Alarm is Missing or Inadequate | 1419 | 9,775 SF | 1 |
| | Sub Total for System | 1 | |
| Technology | | | |
| Deficiency | ID | Qty UoM | Priority |
| Administrative / Support area lacks data drop(s) | 17307 | 4 Ea. | 3 |
| Administrative or support area lacks VOIP phone handset | 17501 | 4 Ea. | 3 |
| | Sub Total for System | 2 | |
| Specialties | | | |
| Deficiency | ID | Qty UoM | Priority |
| The Wardrobe Storage Cabinets Require Repainting | 1414 | 4 LF | 5 |
| | Sub Total for System | 1 | |
| Sub Total for E | Building C - North Building | 22 | |
| Building: D - Covered Play Area | | | |
| Exterior | | | |
| Deficiency | ID | Qty UoM | Priority |
| The Wood Exterior Is Damaged And Requires Replacement | 1403 | 800 SF Wall | 2 |
| The Exterior Requires Painting | 1401 | 3,000 SF Wall | 5 |
| The Exterior Soffit Is Damaged And Requires Repainting | 1402 | 3,000 SF | 5 |
| | Sub Total for System | 3 | |
| Electrical | | | |
| Deficiency | ID | Qty UoM | Priority |
| The H.I.D. Lighting Is Damaged And Should Be Replaced | 1404 | 6 Ea. | 3 |
| | Sub Total for System | 1 | |
| | oub rotarior bystem | • | |

Building: E - Covered Play Area

Exterior

| Deficiency | ID | Qty UoM | Priority |
|---|----------------------|---------------|----------|
| Exterior Doors is not equipped with Card Key Access | 17989 | 2 Ea. | 3 |
| The Exterior Requires Cleaning | 1398 | 2,000 SF Wall | 5 |
| The Exterior Requires Painting | 1399 | 2,000 SF Wall | 5 |
| | Sub Total for System | 3 | |
| Electrical | | | |

| Deficiency | ID | Qty UoM | Priority |
|--|--|----------|----------|
| The Power Service Is Inadequate And Should Be Replaced | 4204 | 200 Amps | 2 |
| The H.I.D. Lighting Is Damaged And Should Be Replaced | 1400 | 4 Ea. | 3 |
| | Sub Total for System | 2 | |
| | Sub Total for Building E - Covered Play Area | 5 | |
| | Total for Campus | 135 | |