	Updated: Novemb	per 30, 2018	COMMON ARI	EAS - INCLUDES	KITCHEN FOOD PREPARATION TAPS
S PPS	# FIXTURE LOCATIONS	# RETURNED TO SERVICE	# TURNED OFF DUE TO TEST RESULTS	# REMAINING TO BE RETURNED TO SERVICE	
Totals:	1323	909	184	417	NOTES
ABERNETHY	20	13	2	7	2 fixtures off due to test results (more extensive plumbing repairs needed) 6 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
AINSWORTH	16	12	1	4	1 fixture off due to test results (more extensive plumbing repairs needed) 3 fixtures require reapair prior to testing (refer to Water Quality Program Schedule)
ALAMEDA	17	13	0	4	4 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
APPLEGATE	3	2	0	1	1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
ARLETA	15	6	5	9	 5 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
ASTOR	12	12	0	0	All 12 fixtures returned to service
ATKINSON	5	5	0	0	All 5 fixtures returned to service
BEACH	22	22	0	0	All 22 fixtures returned to service
BEAUMONT	21	13	4	8	 4 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 3 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
BENSON	43	36	5	7	5 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture off due to sharing a water source with an associated fixture that tested above action level (more extensive plumbing repair needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
BEVERLY CLEARY/FERNW	16	14	2	2	2 fixtures off due to test results (more extensive plumbing repairs needed)
BOISE-ELIOT	11	7	3	4	3 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
BRIDGER	13	10	2	3	2 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture off due to sharing a water source with an associated fixture that tested above action level (more extensive plumbing repair needed)
BRIDLEMILE	9	4	0	5	5 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
BUCKMAN	27	18	2	9	 2 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture off due to sharing a water source with an associated fixture that tested above action level (more extensive plumbing repair needed) 6 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
CAPITOL HILL	12	7	5	5	5 fixtures off due to test results (more extensive plumbing repairs needed)

CHAPMAN	11	9	2	2	2 fixtures off due to test results (more extensive plumbing repairs needed)
CHAVEZ	18	17	0	1	1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
CHIEF JOSEPH	6	4	2	2	2 fixtures off due to test results (more extensive plumbing repairs needed)
CLARENDON	4	4	0	0	All 4 fixtures returned to service
CLEVELAND	22	12	8	10	8 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
COLUMBIA	11	0	0	11	11 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
CREATIVE SCIENCE	8	6	2	2	2 fixtures off due to test results (more extensive plumbing repairs needed)

PPS WATER QUALITY PROGRAM SUMMARY

CRESTON	15	13	0	2	2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
DUNIWAY	15	6	6	9	6 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
EAST SYLVAN	6	4	2	2	2 fixtures off due to test results (more extensive plumbing repairs needed)
EDWARDS	6	6	0	0	All 6 fixtures returned to service
FOREST PARK	11	8	1	3	3 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
GEORGE	9	8	0	1	1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule).
GLENCOE	10	9	0	1	1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
GRANT @ MARSHALL	36	20	8	16	8 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 6 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
GREEN THUMB	1	0	0	1	1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
GROUT	33	18	9	15	9 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 3 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
HARRISON PARK	15	12	3	3	3 fixtures off due to test results (more extensive plumbing repairs needed)
HAYHURST	6	6	0	0	All 6 fixtures returned to service
IOLLADAY CENTEI	5	2	1	3	1 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures requires additional repair prior to testing (refer to Water Quality Program Schedule)
HOLLYROOD	1	0	0	1	1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
HOSFORD	23	17	1	6	1 fixture off due to test results (more extensive plumbing repairs needed) 5 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
HUMBOLDT	9	8	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
IRVINGTON	26	23	1	3	1 fixture off due to test results (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
JACKSON	26	18	3	8	3 fixtures off due to test results (more extensive plumbing repairs needed) 5 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
JAMES JOHN	25	20	3	5	3 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule).
JEFFERSON	45	22	10	23	10 fixtures off due to test results (more extensive plumbing repairs needed) 13 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)

KELLY	12	10	2	2	2 fixtures off due to test results (more extensive plumbing repairs needed)
KENTON	9	0	0	9	9 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
KING	23	14	1	9	6 fixtures ready to return to service (refer to Water Quality Program Schedule) 1 fixture off due to test results (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule
LANE	13	11	1	2	1 fixture off due to test results (more extensive plumbing repairs needed) 1 fixture off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed
LAURELHURST	14	14	0	0	All 14 fixtures returned to service

PPS WATER QUALITY PROGRAM SUMMARY

LEE	10	8	1	2	1 fixture are ready to return to service (refer to Water Quality Program Schedule) 1 fixture off due to test results (more extensive plumbing repairs needed)
LENT	15	12	1	3	1 fixture off due to test results (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
LEWIS	10	10	0	0	All 10 fixtures returned to service
LINCOLN	33	8	8	25	8 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 15 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
LLEWELLYN	19	6	10	13	10 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
MADISON	43	18	13	25	13 fixtures off due to test results (more extensive plumbing repairs needed) 6 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 6 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
MAPLEWOOD	9	5	4	4	4 fixtures off due to test results (more extensive plumbing repairs needed)
MARKHAM	8	7	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
MARYSVILLE	10	10	0	0	All 10 fixtures returned to service
MARYSVILLE MEEK PROFESSSIONAL TECHNICAL	10 7	10 4	0	0 3	All 10 fixtures returned to service 2 fixtures ready to return to service (refer to Water Quality Program Schedule). 1 fixture off due to test results (more extensive plumbing repairs needed)
MEEK PROFESSSIONAL					2 fixtures ready to return to service (refer to Water Quality Program Schedule).
MEEK PROFESSSIONAL TECHNICAL	7	4	1	3	 2 fixtures ready to return to service (refer to Water Quality Program Schedule). 1 fixture off due to test results (more extensive plumbing repairs needed) 2 fixtures off due to testing results (more extensive plumbing repairs needed) 1 fixture off due to sharing water source with an associated fixture that tested above action level (more
MEEK PROFESSSIONAL TECHNICAL MLC	7 7	4	1 2	3 3	 2 fixtures ready to return to service (refer to Water Quality Program Schedule). 1 fixture off due to test results (more extensive plumbing repairs needed) 2 fixtures off due to testing results (more extensive plumbing repairs needed) 1 fixture off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed)
MEEK PROFESSSIONAL TECHNICAL MLC IONROE/DA VINC	7 7 24	4 4 22	1 2 0	3 3 2	 2 fixtures ready to return to service (refer to Water Quality Program Schedule). 1 fixture off due to test results (more extensive plumbing repairs needed) 2 fixtures off due to testing results (more extensive plumbing repairs needed) 1 fixture off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule) 1 fixture off due to test results (more extensive plumbing repairs needed)
MEEK PROFESSSIONAL TECHNICAL MLC IONROE/DA VINC MT TABOR	7 7 24 5	4 4 22 3	1 2 0 1	3 3 2 2	 2 fixtures ready to return to service (refer to Water Quality Program Schedule). 1 fixture off due to test results (more extensive plumbing repairs needed) 2 fixtures off due to testing results (more extensive plumbing repairs needed) 1 fixture off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule) 1 fixture off due to test results (more extensive plumbing repairs needed) 1 fixture off due to test results (more extensive plumbing repairs needed) 1 fixture off due to test results (more extensive plumbing repairs needed) 1 fixture off due to test results (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
MEEK PROFESSSIONAL TECHNICAL MLC IONROE/DA VINC MT TABOR OCKLEY GREEN	7 7 24 5 13	4 4 22 3 13	1 2 0 1 0	3 3 2 2 0	 2 fixtures ready to return to service (refer to Water Quality Program Schedule). 1 fixture off due to test results (more extensive plumbing repairs needed) 2 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule) 1 fixture off due to test results (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule) 1 fixture off due to test results (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule) All 13 fixtures returned to service
MEEK PROFESSSIONAL TECHNICAL MLC ONROE/DA VINC MT TABOR OCKLEY GREEN PENINSULA	7 7 24 5 13 10	4 4 22 3 13 7	1 2 0 1 0 3	3 3 2 2 0 3	 2 fixtures ready to return to service (refer to Water Quality Program Schedule). 1 fixture off due to test results (more extensive plumbing repairs needed) 2 fixtures off due to testing results (more extensive plumbing repairs needed) 1 fixture off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule) 1 fixture off due to test results (more extensive plumbing repairs needed) 1 fixture off due to test results (more extensive plumbing repairs needed) 1 fixture off due to test results (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule) All 13 fixtures returned to service 3 fixtures off due to test results (more extensive plumbing repairs needed)

ROBERT GRAY	17	7	6	10	6 fixtures off due to test results (more extensive plumbing repairs needed) 4 fixtures off due to pending test results (refer to Water Quality Program Schedule)
ROSA PARKS	10	9	0	1	1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
ROSE CITY PARK	17	14	1	3	1 fixture off due to test results (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
OSEWAY HEIGHT	12	10	1	2	1 fixture off due to test results (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
SABIN	13	13	0	0	All 13 fixtures returned to service
SACAJAWEA	5	5	0	0	All 5 fixtures returned to service

PPS WATER QUALITY PROGRAM SUMMARY

SCOTT	11	7	3	4	3 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
SELLWOOD	19	10	4	9	4 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 3 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
SITTON	10	8	2	2	2 fixtures off due to test results (more extensive plumbing repairs needed)
SKYLINE	7	6	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
STEPHENSON	8	5	2	3	2 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
SUNNYSIDE	19	9	2	10	3 fixtures ready to return to service (refer to Water Quality Program Schedule) 2 fixtures off due to test results (more extensive plumbing repairs needed) 5 fixtures require additional repair prior to sampling (refer to Water Qualty Program Schedule)
TERWILLIGER	9	0	0	9	9 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
TUBMAN	12	9	2	3	2 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
VERNON	13	13	0	0	All 13 fixtures have been returned to service.
VESTAL	18	18	0	0	All 18 fixtures returned to service
WEST SYLVAN	12	11	0	1	1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
WHITMAN	12	12	0	0	All 12 fixtures returned to service
WILSON	50	29	6	21	6 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 13 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
WINTERHAVEN	12	6	4	6	4 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixture off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed)
WOODLAWN	9	6	1	3	1 fixture off due to test results (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
WOODMERE	8	6	2	2	2 fixtures off due to test results (more extensive plumbing repairs needed)
WOODSTOCK	13	10	0	3	3 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
YOUNGSON	2	1	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)