



Engineering +
Environmental

February 8, 2017

Courtney Wilton
Portland Public Schools
501 North Dixon
Portland, OR 97227

Via email: cwilton@pps.net

Regarding: Lead Paint Condition Assessment
Harrison Park School
2225 SE 87th Avenue
Portland, Oregon 97216
PBS Project: 6500.721 Phase 0024

Dear Mr. Wilton:

On January 20, 2017, PBS Engineering and Environmental Inc. conducted a visual inspection and assessment of painted and varnished surfaces on the interior and exterior of Harrison Park School located at 2225 SE 87th Avenue in Portland, Oregon.

PBS assessed painted and varnished interior and exterior hard surfaces as well as concrete, asphalt, soil, garden spaces, compost piles, playground equipment, and windowsills adjacent or in close proximity to deteriorated painted or varnished surfaces.

Paint and varnish conditions were assessed using US Department of Housing and Urban Development (HUD) guidelines for the Evaluation and Control of Lead Based Paint Hazards in Housing (2012 Addition) Chapter 5: Risk Assessment and Reevaluation.

It is assumed that all paint and varnish at the school contain some concentration of lead. The purpose of this investigation is to identify those finishes in deteriorated condition.

FINDINGS

Overall, the building's painted and varnished surfaces were found to be in intact condition with areas of fair and deteriorated conditions. A table listing the locations and quantity of surfaces in deteriorated condition is attached to this report.

Paint chips were noted in the north planter boxes in Courtyard 2 and adjacent to the north door at Classroom 168, sunroom. Paint chips were also observed in soil on the school's north side, and at its southwest end near the play structure.

The school has metal-frame windows. No paint chips were observed in any window troughs.

Painted playground and parking lot striping and curbing often contain lead and are generally in deteriorated condition due to weatherization and traffic. PBS did not assess this paint, but recommends restriping, as needed, to maintain in intact condition.

4412 SW Corbett Avenue, Portland, OR 97239
503.248.1939 Main
866.727.0140 Fax
888.248.1939 Toll-Free
www.pbsenv.com

RECOMMENDATIONS

PBS recommends that all painted or varnished surfaces in deteriorated condition noted on the attached table be stabilized. All paint chips should be removed.

Please feel free to contact me at 503 417 7691 or clark@pbsenv.com with any questions or comments.

Sincerely,
PBS Engineering and Environmental Inc.



Clark Nelson, CIH
Senior Project Manager

Attachments: Condition Assessment of Deteriorated Paint/Varnish Table
Field Drawing of Deteriorated Paint and Varnish Locations
Lead-based Paint Risk Assessor Certification (Clark Nelson)
Lead-based Paint Activities Firm Certification (PBS Engineering and Environmental)

CN:DM:bmp

Harrison Park School
Assessment of Paint/Varnish in Deteriorated Condition

ID	Interior / Exterior	Location	Structure	Above / Below five feet	K-2nd Grade	Substrate	Quantity
A	Interior	Northeast auditorium storage room, 129	Varnished door, frame and ladder	Below	No	Wood	50
B	Interior	North auditorium custodial closet	Varnished door and frame	Below	No	Wood	60
C	Interior	Auditorium	Painted east wall	Below	Yes	Plaster	20
D	Interior	Auditorium stage	Painted stage trim red	Below	Yes	Concrete	100
E	Interior	Auditorium machine room	Painted south wall with paint chips	Below	No	Plaster	5
F	Interior	Auditorium machine room	Painted door	Below	No	Metal	5
G	Interior	Auditorium machine room	Painted wall near old furnace	Above and below	No	Brick and concrete	600
H	Interior	Northwest auditorium fan room	Painted south wall	Above and below	No	Concrete bricks	400
I	Interior	Custodial office	Painted south wall	Above and below	No	Wood	80
J	Interior	Boiler room	Painted walls, pipes, walks, misc. components	Above and below	No	Concrete and metal	3000
K	Interior	Boiler room	East, west, and south door and frames	Above and below	No	Metal	80
L	Interior	South auditorium storage room	Varnished door and frame	Above and below	No	Wood	30
M	Interior	Southeast auditorium custodial closet	Varnished door, frame and ladder	Above and below	No	Wood	30
N	Interior	East hallway and auditorium hallway	Lockers	Below	Yes	Metal	300
O	Exterior	Southwest auditorium hallway	Door	Below	Yes	Metal	30
P	Interior	Northwest courtyard hallway	Ceiling	Above	Yes	Metal	5
Q	Interior	West courtyard hallway	Lockers	Below	Yes	Metal	100
R	Interior	North arts wing door	Door and frame	Below	Yes	Metal	30
S	Interior	Classroom office 185A	Door and frame	Below	Yes	Metal	30
T	Interior	Classroom 171, 182	Door and frame	Below	Yes	Metal	60
U	Interior	Health clinic 184	Door and frame	Below	Yes	Metal	30
V	Interior	North cafeteria custodial storage 155	Varnished door and frame	Below	No	Wood and metal	100

ID	Interior / Exterior	Location	Structure	Above / Below five feet	K-2nd Grade	Substrate	Quantity
W	Exterior	Door, south courtyard hallway	Door, frame, and pole	Below	Yes	Metal	50
X	Interior	North cafeteria hallway	Door and frame	Below	Yes	Wood	50
Y	Interior	Cafeteria staff room 174D	Varnished door and frame	Below	No	Wood	60
Z	Interior	Cafeteria staff room 174D	Varnished lower walls	Below	No	Wood	90
AA	Interior	Cafeteria staff room 174D	Wall around window and window sill	Above and below	No	Wood and concrete	20
AB	Interior	Cafeteria	Northwest wall	Below	Yes	Plaster	20
AC	Interior	Cafeteria concessions area	Northwest wall	Below	No	Wood	20
AD	Interior	Cafeteria	Varnished door frames	Below	Yes	Metal	50
AE	Interior	Cafeteria	Radiator covers	Above and below	Yes	Metal	50
AF	Interior	Cafeteria	Support beams	Below	Yes	Wood	60
AG	Exterior	Cafeteria	Varnished wall panels	Below	Yes	Metal and wood	60
AH	Interior	Cafeteria	Door and frame	Above	Yes	Plaster	20
AI	Interior	Kitchen	West wall	Below	No	Wood and metal	75
AJ	Interior	Kitchen	Varnished door and frame	Below	No	Wood	100
AK	Interior	Child counseling offices 172	Wood trim, south wall	Below	Yes	Wood	60
AL	Interior	Child counseling offices 172	Varnished door and frame	Below	Yes	Metal	20
AM	Interior	Classroom 149	Varnished door, frame and cabinets	Above and below	Yes	Wood	100
AN	Interior	Classroom 149	Ventilator cover	Below	Yes	Metal	60
AO	Interior	East hallway, south end	Lockers	Below	Yes	Metal	150
AP	Interior	Media center	Varnished door and frame	Below	Yes	Wood	40
AQ	Interior	East custodial closet	Varnished door and frame	Below	No	Wood	20
AR	Interior	East custodial closet 144	Walls and ceiling	Above	No	Plaster	15
AS	Exterior	Northeast hallway door	Columns	Above and below	Yes	Concrete	40

ID	Interior / Exterior	Location	Structure	Above / Below five feet	K-2nd Grade	Substrate	Quantity
AT	Exterior	Northeast wall	Lower painted wall	Below	Yes	Concrete	50
AU	Exterior	West black top	Door posts	Below	Yes	Metal	15
AV	Exterior	West black top	Basketball posts	Below	Yes	Metal	15
AW	Exterior	West black top near play structure	Door posts	Below	Yes	Metal	10
AX	Exterior	Parking lot, west door	Door posts	Below	Yes	Metal	15
AY	Exterior	West playground, southwest auditorium, playground door	Door posts	Below	Yes	Metal	10
AZ	Exterior	Southwest wall	Wall with chips	Below	Yes	Concrete	40
BA	Exterior	Southwest driveway	Metal poles	Below	Yes	Metal	5
BB	Exterior	West cafeteria, trash area	Metal posts	Below	No	Metal	40
BC	Exterior	West trash area storage shed	Metal door	Below	No	Metal	40
BD	Exterior	South cafeteria door	Posts	Below	Yes	Metal	10
BE	Exterior	East cafeteria door	Posts	Below	Yes	Metal	10
BF	Exterior	East media center door	Posts	Below	Yes	Metal	10
BG	Exterior	Main entrance	Posts	Below	Yes	Metal	20
BH	Interior	Classroom 145	Varnished door, frame, and cabinets	Above and below	Yes	Wood	100
BI	Interior	Classroom 145	Radiator covers	Below	Yes	Metal	40
BJ	Interior	Southeast hallway, women's restroom 150	Varnished door and frame	Above and below	Yes	Wood	20
BK	Interior	Southeast hallway, women's restroom 150	East wall	Below	Yes	Concrete	15
BL	Interior	Southeast hallway, men's restroom 147	Varnished door and frame	Above and below	Yes	Wood	20
BM	Interior	Southeast hallway, women staff restroom 142	Doorframe	Below	No	Wood	10
BN	Interior	Office 140	Varnished door, frame, cabinets, and wall panel	Below	No	Wood	40
BO	Interior	Office 140	East upper wall	Above	No	Plaster	10
BP	Interior	Office 138	Varnished door and frame	Above and below	No	Wood	20

ID	Interior / Exterior	Location	Structure	Above / Below five feet	K-2nd Grade	Substrate	Quantity
BQ	Interior	Supplies office 161	Varnished door and frame	Above and below	No	Wood	20
BR	Interior	Men's staff restroom	Varnished door and frame	Above and below	No	Wood	20
BS	Interior	Classroom 163	Varnished door, frame, cabinets, and wall trim	Below	Yes	Wood	75
BT	Interior	Classroom 163	Radiator covers	Below	Yes	Metal	50
BU	Interior	Courtyard	South wall and chips	Below	No	Concrete	10
BV	Interior	South auditorium	Varnished door and frame	Below	Yes	Wood	35
BW	Interior	Hallway restrooms	Walls and ceiling	Below	Yes	Concrete	20
BX	Interior	Classroom 169	Varnished door, frame, cabinets, and walls	Below	No	Wood	100
BY	Interior	Classroom 185	Door and frame	Below	No	Metal	60
BZ	Interior	Wood shop/computer lab restroom and storage	Door and frame	Below	Yes	Wood	80
CA	Interior	Computer lab/art room, stairs	Hand rails	Below	No	Metal	40
CB	Interior	Classroom 169A	Varnished door	Below	No	Wood	20
CC	Interior	Classroom 169B	Varnished door	Below	No	Wood	20
CD	Exterior	Health office, south door	Door	Below	No	Metal	10
CE	Interior	Computer room 101	Varnished door and frame	Below	Yes	Wood	30
CF	Interior	Classroom 130	Varnished door and frame	Below	Yes	Wood	20
CG	Interior	Classroom 130	Walls and ceiling	Above and below	Yes	Gypsum	30
CH	Interior	Classroom 130	Radiator covers	Below	Yes	Metal	100
CI	Interior	Classroom 195	Door	Below	No	Metal	10
CJ	Interior	Fan room 196	Painted door and door frame	Above and below	No	Metal	10
CK	Interior	Northwest hallway by north doors	Wall	Below	Yes	Plaster	10
CL	Interior	North central hallway	Wall	Below	Yes	Concrete	20
CM	Interior	Courtyard B160	Wall	Below	No	Concrete	50

ID	Interior / Exterior	Location	Structure	Above / Below five feet	K-2nd Grade	Substrate	Quantity
CN	Interior	North central hallway custodial closet	Door, walls, and ceiling	Above and below	No	Metal and plaster	200
CO	Interior	Classroom 164	Door, frames, window frames	Above and below	No	Metal	60
CP	Interior	Classroom 164	Wall	Below	No	Concrete	40
CQ	Interior	Classroom 162	Doors, frames, window frames	Above and below	No	Metal	40
CR	Interior	Classroom 162	Wall	Below	No	Concrete	10
CS	Interior	Classroom 166	Doors, frames, window frames	Above and below	No	Metal	40
CT	Interior	Classroom 159	Doors, frames, window frames	Above and below	No	Metal	20
CU	Interior	North central hallway restrooms	Door	Below	No	Metal	15
CV	Interior	Office 160A	Door, frame, and radiator	Below	No	Metal	20
CW	Interior	Office 167	Doors	Below	Yes	Metal	20
CX	Interior	Office 167	Walls	Below	Yes	Plaster	20
CY	Interior	Office 167	Varnished wall	Below	Yes	Wood	10
CZ	Interior	Classroom 194	Door	Below	No	Metal	5
DA	Interior	Main office	Varnished doors, frames, and walls	Below	Yes	Wood	150
DB	Interior	Offices adjacent to main office	Varnished doors, frames, and walls	Below	No	Wood	100
DC	Interior	Offices and counselors room	Varnished doors, frames, and walls	Below	No	Wood	100
DD	Interior	Custodial closet	Varnished doors, frames, and walls	Above and below	No	Wood	50
DE	Interior	Custodial closet	Wall	Above	No	Plaster	10
DF	Exterior	North side of school	Metal storage box	Below	Yes	Metal and wood	50
DG	Exterior	North side of school	Paint chips	Below	Yes	On ground	15
DH	Exterior	Southwest side of school, near the play structure	Paint chips	Below	Yes	On ground	5
DI	Interior	North hallway	Lockers	Below	Yes	Metal	1000
DJ	Interior	Hallway by north restrooms	Wall	Below	Yes	Plaster	10

ID	Interior / Exterior	Location	Structure	Above / Below five feet	K-2nd Grade	Substrate	Quantity
DK	Interior	North gym hall, by door	Wall	Above and below	Yes	Plaster	10
DL	Interior	Old north locker room	Door and frame	Above and below	Yes	Metal	60
DM	Interior	Old north locker room	Wall	Below	Yes	Plaster	20
DN	Interior	Old north locker room storage	Wall	Below	No	Plaster	15
DO	Interior	South gym doors	Door and frame	Below	Yes	Metal	200
DP	Interior	South gym	Walls and bleachers	Below	Yes	Wood	1500
DQ	Interior	Gym office and storage	Walls	Above and below	No	Plaster	60
DR	Interior	North gym doors and east metal wall	Door and frame	Above and below	Yes	Metal	750
DS	Interior	north gym walls	Walls	Above and below	Yes	Concrete	500
DT	Interior	Classroom 188	Door and frame	Above and below	No	Metal	15
DU	Interior	Classroom 188	Varnished cabinets	Below	No	Wood	50
DV	Interior	Classroom 189	Door and frame	Above and below	No	Metal	15
DW	Interior	Classroom 189	Varnished cabinets	Below	No	Wood	50
DX	Interior	Classroom 190	Door and frame	Above and below	No	Metal	15
DY	Interior	Classroom 190	Varnished cabinets	Below	No	Wood	50
DZ	Interior	Classroom 191	Door and frame	Above and below	No	Metal	15
EA	Interior	Classroom 191	Varnished cabinets	Below	No	Wood	50
EB	Interior	Northwest hallway, boy's restroom	Door	Above and below	Yes	Metal	10
EC	Interior	Northwest hallway, girl's restroom	Door and frame	Below	Yes	Metal	15
ED	Interior	Classroom 194	Varnished cabinets	Below	No	Wood	50
EE	Interior	Classroom 194	Varnished door and frame	Above and below	No	Wood	20
EF	Interior	Classroom 195	Varnished cabinets	Below	No	Wood	50
EG	Interior	Classroom 158	Door and frame	Above and below	No	Metal	50

ID	Interior / Exterior	Location	Structure	Above / Below five feet	K-2nd Grade	Substrate	Quantity
EH	Interior	Classroom 158	Varnished cabinets	Below	No	Wood	100
EI	Interior	Classroom	Varnished door and frame	Above and below	No	Wood	200
EJ	Interior	North auditorium hallway restroom	Unit vent cover	Below	Yes	Metal	10
EK	Interior	Classroom 168	Door and frame	Above and below	No	Metal	30
EL	Interior	Classroom 168	Varnished cabinets	Below	No	Wood	100
EM	Interior	Classroom sun room 168	Table poles	Below	No	Metal	25
EN	Interior	Court yard #2	Wall and paint ships	Below	Yes	Concrete	20
EO	Exterior	Classroom sun room 168	Wall	Below	No	Concrete	50
EP	Exterior	Classroom 109	Varnished door, frame, and cabinets	Above and below	Yes	Wood	200
EQ	Interior	Classroom 109	Unit ventilator	Below	Yes	Metal	50
ER	Interior	North hallway, central girl's restroom	Varnished door and frame	Above and below	Yes	Wood	20
ES	Interior	classroom 110	Varnished door, frame, cabinets, and walls	Above and below	Yes	Wood	300
ET	Interior	Classroom 112	Varnished door, frame, and cabinets	Above and below	Yes	Wood	150
EU	Interior	Classroom 112	Unit ventilator	Below	Yes	Metal	40
EV	Interior	Classroom 114	Varnished door, frame, cabinets, and walls	Above and below	Yes	Wood	200
EW	Interior	Classroom 114		Below	Yes	Metal	40
EX	Interior	Classroom 115	Varnished door, frame, and cabinets	Above and below	Yes	Wood	200
EY	Interior	Boy's and girl's restrooms 117, 116	Varnished door and frame	Above and below	Yes	Wood	50
EZ	Interior	Boy's restroom 117	Ceiling	Above	Yes	Metal	20
FA	Interior	Classroom 118	Varnished door, frame, wall, and cabinets	Above and below	Yes	Wood	150
FB	Interior	Classroom 118	Unit ventilator	Below	Yes	Metal	40
FC	Interior	Classroom 119	Varnished door, frame, wall, and cabinets	Above and below	Yes	Wood	150
FD	Interior	Classroom 120	Varnished door, frame, wall, and cabinets	Above and below	Yes	Wood	100


ID	Interior / Exterior	Location	Structure	Above / Below five feet	K-2nd Grade	Substrate	Quantity
FE	Interior	Classroom 120	Unit ventilator	Below	Yes	Metal	50
FF	Interior	Classroom 121	Varnished door, frame, wall, and cabinets	Above and below	Yes	Wood	150
FG	Interior	Classroom 121	Unit ventilator	Below	Yes	Metal	50
FH	Interior	North hall fire doors	Doors	Above and below	Yes	Metal	50
FI	Interior	Classroom 122	Varnished door, frame, and cabinets	Above and below	Yes	Wood	150
FJ	Interior	Classroom 122	Unit ventilator	Below	Yes	Metal	100
FK	Interior	North hallway, north restrooms	Door and frame	Above and below	Yes	Wood	50
FL	Interior	North hallway, north restrooms	Walls	Above	Yes	Plaster	20
FM	Interior	North hallway counselor's office	Walls	Above	Yes	Plaster	20

HARRISON PARK

Binsmead Middle School
2225 SE 87th Street 97216
Facility Plan



SECOND FLOOR PLAN



Page 2 of 2

FIRST FLOOR PLAN
 TOTAL SF 109,059
 ACRES 10.16
 1/4 SECT. 3239



June 9, 2016

Clark R. Nelson
PBS Engineering and Environmental Inc.
4412 S.W. Corbett Ave
Portland, OR 97239

800 NE Oregon Street, Suite 640
Portland, OR 97232
Phone: (971) 673-0440
Fax: (971) 673-0457
TTY Nonvoice: (971) 673-0372

RE: LEAD-BASED PAINT ACTIVITIES, INDIVIDUAL CERTIFICATION NO. 1806--Indv--R

This letter is your official notification that you have met the certification requirements under Oregon Administrative Rule (OAR) 333-069 to conduct lead-based paint activities in Oregon, in the following disciplines: Risk Assessor; Inspector

In addition to certification by the Oregon Health Authority, you are required to be licensed by the Construction Contractors Board (CCB) if you plan to conduct lead-based paint activities in Oregon. This license is different than, and in addition to, the standard contractor license issued by CCB. Both individuals and firms must obtain this license. For more information on CCB lead-based paint licensing, visit their web site at www.oregon.gov/CCB or call 503-378-4621.


As a certified individual in Oregon, you must meet all the requirements of OAR 333-069, including work practice standards for conducting lead-based paint activities in target housing and child-occupied facilities. As a certified individual, you must perform work under a firm that is certified by the Authority for conducting lead-based paint activities.

You are required to wear the enclosed badge in plain view when conducting lead-based paint activities. Please note that the badge and certificate will expire on 6/30/2017. If you wish to maintain your certification after 6/30/2017, you must submit an application postmarked at least 60 days before expiration and document that your lead-based paint activities training is current.

As a public service the Authority publishes a list of individuals performing lead-based paint activities in Oregon. The list is distributed statewide to consumers interested in lead-based paint activities. Individuals that are certified by the state are eligible to be on this list.

If you have any questions concerning your certification or other aspects of the Lead-Based Paint Program, please contact program staff at 971-673-0440.

Sincerely,


Ben Maynard
Lead-Based Paint Program
Oregon Health Authority

Enclosures: 1) Badge; 2) Certificate



Clark R. Nelson

**Risk Assessor
Inspector
Lead-Based Paint
Activities
CERTIFICATION
1806--Indv--R
6/30/2017**

Expires

CERTIFIED


State of Oregon
Oregon Health Authority

Clark R. Nelson

is certified by the Oregon Health Authority to conduct Lead-Based Paint Activities

Risk Assessor

Certification Number:	1806--Indv--R
Issuance Date:	6/9/2016
Expiration Date:	6/30/2017



Oregon
Health
Authority

CLARK RICHARD NELSON
4412 SW CORBETT AVE
PORTLAND, OR 97239

**CONSTRUCTION CONTRACTORS BOARD
LEAD BASED PAINT
RISK ASSESSOR LICENSE**

EXPIRATION DATE: 6/24/2017

This document certifies that

CLARK RICHARD NELSON
4412 SW CORBETT AVE
PORTLAND, OR 97239

is licensed in accordance with Oregon Law as
a Lead Based Paint Risk Assessor.

9151806-RA

**STATE OF OREGON
CONSTRUCTION CONTRACTORS BOARD
LEAD BASED PAINT
RISK ASSESSOR LICENSE**

LICENSE NUMBER: 9151806-RA

This document certifies that:

CLARK RICHARD NELSON
4412 SW CORBETT AVE
PORTLAND, OR 97239

is licensed in accordance with Oregon Law as a Lead Based Paint Risk Assessor.

License Details:

LICENSE NO.: 9151806-RA
EXPIRATION DATE: 6/24/2017

May 17, 2016

PBS Engineering and Environmental Inc.
4412 SW Corbett Ave
Portland, OR 97239

800 NE Oregon Street, Suite 640
Portland, OR 97232
Phone: (971) 673-0440
Fax: (971) 673-0457
TTY Nonvoice: (971) 673-0372

Attention: Derek May

RE: LEAD-BASED PAINT ACTIVITIES, FIRM CERTIFICATION NO. 1038--LBP FIRM

This letter is your official notification that PBS Engineering and Environmental Inc. has met certification requirements under Oregon Administrative Rules (OAR) 333-069 to conduct lead-based paint activities in Oregon. Please note that the enclosed certificate will expire on 6/30/2017.

In addition to certification by the Oregon Health Authority (Authority), PBS Engineering and Environmental Inc. is required to be licensed by the Construction Contractors Board (CCB) prior to conducting lead-based paint activities in Oregon. This license is different than, and in addition to, the standard contractor license issued by CCB. Both individuals and firms must obtain this license. For more information on CCB lead paint licensing, visit their web site at www.oregon.gov/CCB or call 503-378-4621.

As a firm certified to conduct lead-based paint inspection activities in Oregon, PBS Engineering and Environmental Inc. must meet all requirements set forth in OAR 333-069. It must comply with standards for conducting lead-based paint inspection and/or risk assessment activities in target housing and child-occupied facilities and employ only certified individuals to conduct regulated activities.

As a public service, the Authority publishes a list of firms performing lead-based paint activities in Oregon. The list is distributed statewide to consumers interested in lead-based paint services. Only those firms that are certified by the state are eligible to be on this list.

If you have any questions concerning this certification or other aspects of the Lead-Based Paint Program, please contact program staff at (971) 673-0440.

Sincerely,



Ben Maynard
Lead-Based Paint Program
Oregon Health Authority

This document can be obtained in an alternate format by calling: (971) 673-0440.

State of Oregon
Oregon Health Authority

PBS Engineering and Environmental Inc.

is certified by the Oregon Health Authority to conduct Lead-Based Paint Activities

Certification Number:	1038--LBP FIRM
Issuance Date:	5/16/2016
Date of Expiration:	6/30/2017



Oregon
Health
Authority

PBS ENGINEERING & ENVIRONMENTAL INC
4412 SW CORBETT
PORTLAND OR 97239

CONSTRUCTION CONTRACTORS BOARD
LEAD INSPECTION CONTRACTORS LICENSE
LICENSE No.: LBPI129143
EXPIRATION DATE: 7/31/2017

This document certifies that

PBS ENGINEERING & ENVIRONMENTAL INC
4412 SW CORBETT
PORTLAND OR 97239

is licensed in accordance with Oregon Law as
a Lead Inspection Contractor.

STATE OF OREGON
CONSTRUCTION CONTRACTORS BOARD
LEAD INSPECTION CONTRACTORS LICENSE

LICENSE NUMBER: LBPI129143

This document certifies that:

PBS ENGINEERING & ENVIRONMENTAL INC
4412 SW CORBETT
PORTLAND OR 97239

is licensed in accordance with Oregon Law as a Lead Inspection Contractor.

License Details:

LBPI LICENSE NO.: LBPI129143
EXPIRATION DATE: 7/31/2017