1/7/2008 1:53 PM

Glencoe Elementary School

School and Site Level Deficiencies

Site

Deficiency	ID	Qty UoM	Priority
Playground Requires Replacement	8299	2 Ea.	3
Bus drop-off area does not have a canopy.	13974	100 LF	5
K playground not appropriately fenced or buffered.	14032	1 Ea.	5
Paved Play Requires Recoating And Resurfacing	8301	30,000 SF	5
Paving Requires Restriping	8297	37 CAR	5
School lacks marquee or marquee in poor condition.	13832	1 Ea.	5
	Sub Total for System	6	
Interior			
Deficiency	ID	Qty UoM	Priority
Elementary School lacks appropriate wayfinding system.	14132	1 Ea.	5
	Sub Total for System	1	
Electrical	•		
Deficiency	ID	Qty UoM	Priority
School site lacks appropriate lighting.	14070	10 Ea.	5
	Sub Total for System	1	-
Technology	Cab rotal to Gyatem	•	
•		o	D
Deficiency	ID ACTOM	Qty UoM	Priority
Facility lacks centralized video distribution equipment	16781	1 Ea.	3
Facility lacks VOIP central equipment	16869	1 Ea.	3
	0.17.11.0	_	
	Sub Total for School and Site Lovel	2	
	Sub Total for System Sub Total for School and Site Level	2 10	
Building: A - Main Building	•		
Building: A - Main Building Site	•		
Site	•		Priority
Site Deficiency	Sub Total for School and Site Level	10	Priority 1
Deficiency Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.)	Sub Total for School and Site Level	10 Qty UoM	
Deficiency Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.)	Sub Total for School and Site Level ID 12403	Qty UoM	1
Deficiency Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.)	Sub Total for School and Site Level ID 12403 12412	Qty UoM 20 LF 1 LF	1
Deficiency Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.)	ID 12403 12412 12849	Qty UoM 20 LF 1 LF 20 LF	1
Deficiency Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Roofing	Sub Total for School and Site Level ID 12403 12412 12849 Sub Total for System	Qty UoM 20 LF 1 LF 20 LF 3	1 1 1
Site Deficiency Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Roofing Deficiency	Sub Total for School and Site Level ID 12403 12412 12849 Sub Total for System	20 LF 1 LF 20 LF 3	1
Deficiency Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Roofing Deficiency The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement	Sub Total for School and Site Level ID 12403 12412 12849 Sub Total for System ID 9348	Qty UoM 20 LF 1 LF 20 LF 3 Qty UoM 242 SF	1 1 1 Priority 1
Deficiency Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Roofing Deficiency The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement	ID	10 Qty UoM 20 LF 1 LF 20 LF 3 Qty UoM 242 SF 2,834 SF	1 1 1 1
Site Deficiency Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Roofing Deficiency The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement	ID	Qty UoM 20 LF 1 LF 20 LF 3 Qty UoM 242 SF 2,834 SF 3,233 SF	1 1 1 Priority 1 1
Deficiency Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Roofing Deficiency The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement	ID	Qty UoM 20 LF 1 LF 20 LF 3 Qty UoM 242 SF 2,834 SF 3,233 SF 5,126 SF	Priority 1 1 1 1 1 1 1 1
Deficiency Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Roofing Deficiency The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement	ID	Qty UoM 20 LF 1 LF 20 LF 3 Qty UoM 242 SF 2,834 SF 3,233 SF 5,126 SF 8,490 SF	1 1 1 Priority 1 1 1
Deficiency Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Roofing Deficiency The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Clay Tile Roofing Roof Covering Is Damaged And Requires Repair	ID 12403 12412 12849 Sub Total for System ID 9348 9349 9350 9351 9352 115	Qty UoM 20 LF 1 LF 20 LF 3 Qty UoM 242 SF 2,834 SF 3,233 SF 5,126 SF 8,490 SF 1,500 SF	Priority 1 1 1 1 1 1 1 1 2
Deficiency Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Roofing Deficiency The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Clay Tile Roofing Roof Covering Is Damaged And Requires Repair Wood roof diaphrams need enhancement	ID	10 Qty UoM 20 LF 1 LF 20 LF 3 Qty UoM 242 SF 2,834 SF 3,233 SF 5,126 SF 8,490 SF 1,500 SF 1 LS	1 1 1 1 1 1 1 2 2 2
Bite Deficiency Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Roofing Deficiency The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Clay Tile Roofing Roof Covering Is Damaged And Requires Repair Wood roof diaphrams need enhancement Wood roof diaphrams need enhancement	ID	Qty UoM 20 LF 1 LF 20 LF 3 Qty UoM 242 SF 2,834 SF 3,233 SF 5,126 SF 8,490 SF 1,500 SF 1 LS 1 LS	Priority 1 1 1 1 1 1 1 2 2
Bite Deficiency Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Roofing Deficiency The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Clay Tile Roofing Roof Covering Is Damaged And Requires Repair Wood roof diaphrams need enhancement Wood roof diaphrams need enhancement	ID	Qty UoM 20 LF 1 LF 20 LF 3 Qty UoM 242 SF 2,834 SF 3,233 SF 5,126 SF 8,490 SF 1,500 SF 1 LS 1 LS 2 Ea.	1 1 1 1 1 1 1 2 2 2
Bite Deficiency Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Roofing Deficiency The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Clay Tile Roofing Roof Covering Is Damaged And Requires Repair Wood roof diaphrams need enhancement Wood roof diaphrams need enhancement The Roof Operable Hatch Is Damaged And Requires Replacement	ID	Qty UoM 20 LF 1 LF 20 LF 3 Qty UoM 242 SF 2,834 SF 3,233 SF 5,126 SF 8,490 SF 1,500 SF 1 LS 1 LS	Priority 1 1 1 1 1 1 1 2 2
Bite Deficiency Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Roofing Deficiency The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Clay Tile Roofing Roof Covering Is Damaged And Requires Repair Wood roof diaphrams need enhancement Wood roof diaphrams need enhancement The Roof Operable Hatch Is Damaged And Requires Replacement	ID	Qty UoM 20 LF 1 LF 20 LF 3 Qty UoM 242 SF 2,834 SF 3,233 SF 5,126 SF 8,490 SF 1,500 SF 1 LS 1 LS 2 Ea.	Priority 1 1 1 1 1 1 1 2 2
Bite Deficiency Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Roofing Deficiency The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Clay Tile Roofing Roof Covering Is Damaged And Requires Repair Wood roof diaphrams need enhancement Wood roof diaphrams need enhancement The Roof Operable Hatch Is Damaged And Requires Replacement Structural Deficiency	ID	Qty UoM 20 LF 1 LF 20 LF 3 Qty UoM 242 SF 2,834 SF 3,233 SF 5,126 SF 8,490 SF 1,500 SF 1 LS 1 LS 2 Ea. 9 Qty UoM	1 1 1 1 1 1 1 1 2 2 2 3 3 Priority
Bite Deficiency Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Roofing Deficiency The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Clay Tile Roofing Roof Covering Is Damaged And Requires Repair Wood roof diaphrams need enhancement Wood roof diaphrams need enhancement The Roof Operable Hatch Is Damaged And Requires Replacement Structural Deficiency	ID	Qty UoM 20 LF 1 LF 20 LF 3 Qty UoM 242 SF 2,834 SF 3,233 SF 5,126 SF 8,490 SF 1,500 SF 1 LS 1 LS 2 Ea. 9	Priority 1 1 1 1 1 1 1 2 2 3
Bite Deficiency Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Elevation changes prevent access (curbs, stairs, stages, doorway thresholds etc.) Roofing Deficiency The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Multi-Ply Bitumen Roof Covering Is Damaged And Requires Replacement The Clay Tile Roofing Roof Covering Is Damaged And Requires Repair Wood roof diaphrams need enhancement Wood roof diaphrams need enhancement The Roof Operable Hatch Is Damaged And Requires Replacement Structural Deficiency Wall or parapet requires lateral bracing.	ID	Qty UoM 20 LF 1 LF 20 LF 3 Qty UoM 242 SF 2,834 SF 3,233 SF 5,126 SF 8,490 SF 1,500 SF 1 LS 1 LS 2 Ea. 9 Qty UoM	1 1 1 1 1 1 1 1 2 2 2 3 3 Priority
	ID	Qty UoM 20 LF 1 LF 20 LF 3 Qty UoM 242 SF 2,834 SF 3,233 SF 5,126 SF 8,490 SF 1,500 SF 1 LS 1 LS 2 Ea. 9 Qty UoM 1 LS	1 1 1 1 1 1 1 1 1 1 2 2 2 3 Priority 1

School Deficiency Listing

1/7/2008 1:53 PM

157 Glencoe Elementary School

Deficiency	ID	Qty UoM	Priority	
The Aluminum Window Is Damaged And Requires Replacement	8312	138 Ea.	2	
The Aluminum Window Is Damaged And Requires Replacement	8315	6 Ea.	2	
The Aluminum Window Is Damaged And Requires Replacement	8316	19 Ea.	2	
The Aluminum Window Is Damaged And Requires Replacement	8317	5 Ea.	2	
The Wood Exterior Door Is Damaged And Requires Replacement	8306	11 Door	2	
The Wood Window Is Damaged And Requires Replacement	8311	8 Ea.	2	
The Wood Window Is Damaged And Requires Replacement	8314	6 Ea.	2	
Exterior door hardware is damaged and should be replaced	8309	11 Ea.	3	
Exterior Doors is not equipped with Card Key Access	17916	23 Ea.	3	
Exterior Metal Door Requires Repainting	8307	12 Door	3	
The Exterior Requires Painting	8305	15,000 SF Wall	5	
	Sub Total for System	11		

Interior

Deficiency	ID	Qty UoM	Priority
Acoustical Wall Treatment is missing and is needed	15901	3,768 SF	3
Door is not equiped with Card Key Access	17541	60 Ea.	3
The Carpet Flooring Is Damaged And Requires Replacement	8324	8,000 SF	3
The Ceramic Tile Flooring Is Damaged And Requires Replacement	8327	1,000 SF	3
The Suspended Ceiling Grid is Damaged And Require Replacement	8319	2,000 SF	3
The Vinyl Composition Tile Flooring Is Damaged And Requires Replacement	8325	58,000 SF	3
Blinds are missing or in poor condition.	15917	100 SF Surf	4
The Plaster Ceilings Are Damaged And Requires Repair	8320	10,000 SF	4
The Wood Flooring Is Damaged And Requires Repair	8326	11,000 SF	4
Interior Doors Require Repair	8328	60 Door	5
Interior Gypboard Walls Require Repainting	8323	55,000 SF Wall	5
Interior Walls Require Repainting	8322	69,000 SF	5
Large rooms lack capacity signs.	15918	6 Ea.	5
The Acoustical Ceilings Tiles Are Damaged And Require Replacement	8318	58,000 SF	5
The Plaster Ceilings Are Damaged And Requires Repainting	8321	10,000 SF	5

Sub Total for System

Mechanical

Deficiency	ID	Qty UoM	Priority
Heat Exchanger Requires Replacement	8347	1 Ea.	2
Kitchen Fire Suppression Hood Requires Repair	8334	1 LS	2
Lab lacks an air exchange system.	15910	1 Ea.	2
Steam Condensate Reciever requires Replacement	9331	1 Ea.	2
The Boiler HVAC Component Is Damaged And Requires Replacement	8343	3,000 MBH	2
The Fan Coil HVAC Component Is Damaged And Requires Replacement	8340	9 TonAC	2
The Fan Coil HVAC Component Is Damaged And Requires Replacement	8341	6 TonAC	2
The Fan Coil HVAC Component Is Damaged And Requires Replacement	8342	6 TonAC	2
The Radiant Heat HVAC Component Is Damaged And Requires Replacement	8344	60 Ea.	2
Unit Ventilator requires Replacement	8345	2 Ea.	2
Air Compressor is Inoperable and Requires Replacement	8346	1 Ea.	3
Test And Balancing Required	8335	69,790 SF	3
The 2 X 4 Exhausts/Hoods Are Missing/Damaged And Require Replacement	8333	2 Ea.	3
Controls Are Inadequate And Should Be Replaced With DDC Controls	8336	69,790 SF	4
Exhaust Fan Ventilation Is Damaged And Should Be Replaced	8339	8 Ea.	4
Duct Cleaning Required	8337	69,790 SF	5

School Deficiency Listing

1/7/2008 1:53 PM Glencoe Elementary School

N/a-a-a-a	:
Mecha	ınıcaı

Medianida			
Deficiency	ID	Qty_UoM	Priority
Exhaust Fan Ventilation Is Missing And Should Be Installed	8338	6 Ea.	5
	Sub Total for System	17	
Electrical			
Deficiency	ID	Qty UoM	Priority
The Panelboard Is Damaged And Should Be Replaced	8360	1,100 Amps	2
Circuits need to be added to support additional outlets	16683	5 Ea.	3
The Electrical Receptacles Are Inadequate And Require Replacement	8361	5 Ea.	3
The GFCI Electrical Receptacles Are Inadequate And More Are Needed	8362	15 Ea.	3
The Mounted Building Lighting Is Damaged And Should Be Replaced	8358	6 Ea.	3
The 1 X 4 Interior Fluorescent Lighting Is Damaged And Should Be Replaced	8359	110 Ea.	4
Room does not have tamper-proof light switching.	15905	2 Ea.	5
Room has insufficient electrical outlets.	15902	54 Ea.	5
Room lacks controls to partially dim lights.	15916	2 Ea.	5
Room lighting is inadequate or in poor condition.	15915	16,820 SF	5
	Sub Total for System	10	
Plumbing			
Deficiency	ID	Qty UoM	Priority
Completely nonaccessible toilet room.	12410	1 Ea.	1
The Water Heater Plumbing Fixtures Are Damaged And Should Be Replaced	8348	2 Ea.	2
Install Fire Sprinklers	8357	69,790 SF	3
The Showers Plumbing Fixtures Are Damaged And Should Be Replaced	8356	2 Ea.	3
The Toilets Plumbing Fixtures Are Damaged And Should Be Replaced	8354	28 Ea.	3
The Urinal Plumbing Fixtures Are Damaged And Should Be Replaced	8355	4 Ea.	3
Drinking Fountain unit not accessible.	12413	1 Ea.	4
Drinking Fountain unit not accessible.	12414	2 Ea.	4
The Class Room Lavatories Plumbing Fixtures Are Damaged And Should Be Replaced	8351	4 Ea.	4
The Custodial Mop Or Service Sink Is Damaged And Should Be Replaced	8352	3 Ea.	4
The Non-Refrigerated Drinking Fountain is Damaged And Should Be Replaced	8349	10 Ea.	4
The Rest Room Lavatories Plumbing Fixtures Are Damaged And Should Be Replaced	8353	14 Ea.	4
Room lacks a drinking fountain.	15913	8 Ea.	5
Room lacks private toilets.	15911	2 Ea.	5
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	8350	21 Ea.	5
The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed	15912	19 Ea.	5
·	Sub Total for System	16	
Fire and Life Safety			
Deficiency	ID	Qty UoM	Priority
Room lacks an appropriate eyewash.		1 Ea.	1
Emergency Exit Signage Is Damaged Or Missing And Should Be Replaced	8394	11 Ea.	2
Building not equipped with Card Key Access Control	18014	1 Ea.	3
Computer room lacks independent AC.	18224	1 Ea.	3
	Sub Total for System	4	-
Technology	2 2 • , 5	-	
		0	Delevis
Deficiency Administrative / Support area lacks data drop(s)	ID 17159	Qty UoM 21 Ea.	Priority 3
Administrative or support area lacks VOIP phone handset		21 Ea. 21 Ea.	3
·	17353	21 Ea. 7 Ea.	3
Building lacks enough wireless data points	17080		
Classroom lacks technology upgrade	15919	28 Ea.	3
Room has insufficient dataports.	15903	162 Ea.	5

School Deficiency Listing

Glencoe Elementary School 157

1/7/2008 1:53 PM

T	ec	h	n	o	lo	q	۷

Q ty	UoM Ea.	5
Qty 1	UoM	Deioritu
1		Deignitus
1		Deineite
	Ea.	Priority
1		1
	Ea.	1
2		
Qty	UoM	Priority
395	Student	4
130	LF	4
130	LF	4
90	LF	4
29	Ea.	5
34	Ea.	5
22	Ea.	5
1	Ea.	5
1	Ea.	5
9)	
Qtv	UoM	Priority
		2
1		
1 106		
•		
•		
•		
106 Qty	UoM	Priority
106 Qty		Priority 2
106 Qty 3	UoM	
2ty 3 1	UoM Ea.	2
2ty 3 1 1 1	UoM E Ea. Ea.	2
106 Qty 3 1 1	UoM Ea. Ea.	2 3 3
Qty 3 1 1 1 1,200	Ea. Door	2 3 3 3
Qty 3 1 1 1 1,200	Ea. Ea. Door SF Wall	2 3 3 3 5
Qty 3 3 1 1 1,200 150	Ea. Ea. Door SF Wall	2 3 3 3 5
106 Qty 3 1 1 1,200 150 6	Ea. Ea. Door SF Wall	2 3 3 3 5
106 Qty 3 1 1 1,200 150 6	UoM E Ea. Ea. Ea. Door SF Wall	2 3 3 3 5 5
Qty 3 1 1 1 1 1,200 150 6	UoM Ea. Ea. Ea. Door SF Wall SF	2 3 3 3 5 5
Qty 3 1 1 1 1 1,200 150 6 Qty 992 992	UoM Ea. Ea. Door SF Wall SF	2 3 3 3 5 5 5
Qty 3 1 1 1 1 1,200 150 6 Qty 992 992	UoM E Ea. Ea. Door SF Wall SF UOM E SF	2 3 3 3 5 5 5
Qty 3 1 1 1 1,200 150 6 Qty 992 992	UoM E Ea. Ea. Door SF Wall SF UOM E SF	2 3 3 3 5 5 5
Qty 3 1 1 1 1,200 150 6 Qty 992 992 992 3	UoM Ea. Ea. Door SF Wall SF GUOM SF	2 3 3 5 5 5 Priority 3 3 5
Qty 3 1 1 1 1,200 150 6 Qty 992 992 992 3 Qty	UoM E Ea. Ea. Door SF Wall SF UOM E SF	2 3 3 3 5 5 5
Qty 3 11 1 1 1,200 150 6 Qty 992 992 992 3 Qty 992	UoM Ea. Ea. Door SF Wall SF UOM SF SF	2 3 3 3 5 5 Priority 3 3 5
Qty 3 1 1 1 1 1,200 150 6 Qty 992 992 992 992 4	UoM Ea. Ea. Ea. Door SF Wall SF SF SF UoM SF SF SF	2 3 3 3 5 5 Priority 3 5 Priority 2 2
1066 Qty 3 1 1 1 1,200 150 6 Qty 992 992 3 Qty 992 4 992	UoM E Ea. Ea. Door SF Wall SF UoM E SF	2 3 3 3 5 5 Priority 3 5 Priority 2
_	395 130 130 90 29 34 22 1 1 9	Qty UoM 395 Student 130 LF 130 LF 90 LF 29 Ea. 34 Ea. 22 Ea. 1 Ea. 1 Ea. 9 Qty UoM 1 LS

Glencoe Elementary School

School Deficiency Listing

1/7/2008 1:53 PM

Electrical

Deficiency	ID	Qty	UoM	Priority
The Panelboard Is Damaged And Should Be Replaced	8376	200	Amps	2
The GFCI Electrical Receptacles Are Inadequate And More Are Needed	8377	2	Ea.	3
The Mounted Building Lighting Is Damaged And Should Be Replaced	8375	1	Ea.	3
The 2 X 4 Interior Fluorescent Lighting Is Damaged And Should Be Replaced	9340	11	Ea.	4
	Sub Total for System	4		
Plumbing				
Deficiency	ID	Qty	UoM	Priority
The Water Heater Plumbing Fixtures Are Damaged And Should Be Replaced	8372	1	Ea.	2
Install Fire Sprinklers	8374	992	SF	3
The Class Room Lavatories Plumbing Fixtures Are Damaged And Should Be Repl	aced 8373	1	Ea.	4
	Sub Total for System	3		
Technology				
Deficiency	ID	Qty	UoM	Priority
Building lacks enough wireless data points	16899	1	Ea.	3
	Sub Total for System	1		
	Sub Total for Building P1 - Portable Classroom	21		
	Total for Campus	137		