

PORTLAND PUBLIC SCHOOLS – FACILITY ADA ASSESSMENT

Atkinson School K-5
August 31, 2009

Site Accessibility

Parking	No on-site parking is available for the school. Parking in adjacent Clinton Park lot with 2 accessible stalls with striping and signage. Repaint striping to comply with current requirements.
Entry, Main South Front Doors	Compliant pair doors with pull handles, panic at interior. Exits to rear playground. Path slopes down to off-site parking lot with one set of intermediate stairs along the way. Update stair handrails with double handrails.

Accessible Route & Features

Stage 125	Add ramp at north stage access steps.
Classroom doors	Provide all classrooms with lever handle hardware.
Ramps, Interior	3 sets of existing interior ramps. Add double handrails to east ramp leading to east wing. Two ramps down to south wing have compliant double handrails.
East Wing Restroom, Boys east end 181	Replace door with compliant entry for width and clearances.
East Wing Restroom, Girls east end 182	Replace door with compliant entry for width and clearances.

Plumbing Elements

East Wing Restroom, Boys east end 181	Provide accessible toilet stall, clearances, lavatory and accessories within reach ranges.
East Wing Restroom, Girls east end 182	Provide accessible toilet stall, clearances, lavatory and accessories within reach ranges.
Drinking Fountains	Verify that Cafeteria/Auditorium drinking fountain complies with accessibility standards. Provide an accessible high-low drinking fountain in the corridor of the west building, near the ADA restrooms.
Workroom 165	Provide an accessible sink.

Communication Elements

Cafeteria/Auditorium 126	Provide assisted listening devices.
Classrooms	Any need for assisted listening devices in programs at this school? Or within SPED classrooms?
Signage	Provide accessible signage at new accessible restrooms. If signage is



	provided at classrooms, provide accessible signage.
--	---

Special Spaces, Built-in Elements & Recreational Facilities

Play Surface	Verify and test existing play structure safety surfacing. Mulch must be solid enough to allow wheelchair access
Play Structure	Verify that the existing play structure is accessible, and modify if needed.

Field Notes:

1. Boys restroom 159 used for storage.
2. Former Girls restroom 160 used for SPED "time-out" room.

