

PORTLAND PUBLIC SCHOOLS – FACILITY ADA ASSESSMENT

Bridger School K-8
August 31, 2009

Site Accessibility

Entry Accessible Path	Add directional signage at interior of northwest entry door.
East Parking	Add directional signage to accessible stalls at west parking lot.
Portables	Provide an accessible ramp with double handrails for access to the portable classrooms.

Accessible Route & Features

Classroom doors	Provide all classrooms with lever handle hardware.
SPED Classroom 29	Non-compliant narrow entry corridor between existing Custodial and Staff restroom. Provide power door operator from each side of door to room 29.

Plumbing Elements

Drinking Fountains	Verify that Cafeteria/Auditorium drinking fountain complies with accessibility standards.
Boys Locker Room	If this room is still being used for this function, provide an accessible restroom with toilet, grab bar accessories and lavatory, shower, and bench.
Girls Locker Room	If this room is still being used for this function, provide an accessible restroom with toilet, grab bar accessories and lavatory, shower, and bench.
Main Office 46	Provide an accessible sink.

Communication Elements

Northwest Entry	Add 2-way audio/visual communications from accessible entry nearest accessible parking stalls.
Cafeteria/Auditorium 37	Provide assisted listening devices.
Classrooms	Any need for assisted listening devices in programs at this school? Or within SPED classrooms?
Signage	Provide accessible signage at common rooms with signage. If signage is provided at classrooms, provide accessible signage.

Special Spaces, Built-in Elements & Recreational Facilities

Cafeteria/Auditorium 37	Add lift for stage access.
Play Structure	Verify that one play structure is accessible, and modify if needed.

Field Notes:

1. 2 separate groups of play climbing structure areas have existing safety surfacing.
2. 2 interior main corridor ramps have compliant handrails.



