

PORTLAND PUBLIC SCHOOLS – FACILITY ADA ASSESSMENT

DaVinci 6-8
August 31, 2009

Site Accessibility

Fencing	Confirm that fencing between SE entry and play yard allows 32" clearance at gate, and that gate hardware can be operated without pinching, twisting or grasping.
Fencing	Confirm that fencing between play fields and garden (tennis court) allows 32" clearance at gate, and that gate hardware can be operated without pinching, twisting or grasping.

Accessible Route & Features

NW Stair	Provide accessible handrails with extensions at each stair flight (approximately 104 lf.)
Stair SE of Cafeteria	Provide accessible handrails with extensions at the stair flight from basement, and at the stair flight to exterior grade (approximately 36 lf.)
Stage	Provide a lift next to the stairs in the north/south corridor east of the stage (approximately 3 feet of rise.)
Music A	Provide an accessible ramp (approximately 24 lf) with handrails.
Staff/Work	Provide lever hardware.
Computer Room	Provide lever hardware.
Counseling	Provide lever hardware.
Classroom E	Provide lever hardware.
Classroom F	Provide lever hardware.
Health Center	Provide lever hardware.
Classrooms	Provide lever hardware as requested for program access by students and staff (approximately 40 classrooms.)

Plumbing Elements

Boys 2 nd Floor	Provide a unisex boys restroom on the 2 nd floor.
Unisex Locker Room	One locker room was identified on the basement level, but a second was not located. If this function is still being used at this school, provide an accessible locker room/restroom for girls and boys. A reasonable alternate would be to provide a unisex locker/restroom with an accessible bench and occupancy indicator lever hardware on the first floor.
Home Economics	If sinks are provided, provide one at 34" high.
Science	If sinks are provided, provide one at 34" high. If gases are provided, provide one at 34" high counter and within accessible reach ranges.
Office	If a sink is provided, provide one at 34" high. If gases are provided, provide one at 34" high counter and within accessible reach ranges.
Staff/Work	If a sink is provided, provide one at 34" high. If gases are provided, provide one at 34" high counter and within accessible reach ranges.

Communication Elements

Auditorium	Provide assisted listening devices.
------------	-------------------------------------



Signage	Review the interior building signage. Provide accessible signs (using 60" max to bottom of the top line of text and 48" max to the bottom of Braille) at new accessible spaces and permanent signage at common areas where is not already provided. If signage is provided at classrooms, provide accessible signage.
---------	---

Special Spaces, Built-in Elements & Recreational Facilities

Auditorium	Provide four wheelchair and companion seats where the floor is, or can be remodeled to be level, and out of the aisles.
Home Economics	Provide a work counter 34" high and 30" beside the accessible sink counter.
Locker Rooms	Provide an accessible bench in the girls and boys locker rooms.
Play Area Equipment	Review the play area structures for compliance, and modify if needed.
Play Area Surface	Provide an accessible surface material at play area structures (approximately 1,000 sf.)

