

PORTLAND PUBLIC SCHOOLS – FACILITY ADA ASSESSMENT

Hollyrood School K-1
August 31, 2009

Site Accessibility

Parking	No on-site parking is available for the school. Parking at on-street deadend of NE 35 th Place. (1) accessible stalls and access aisles available. Verify paint striping and access aisle width(s) and placement.
Sidewalk Path / Exterior Ramp to Entry	Existing exterior ramp with double handrails on sidewalk route from curb cut appears to be compliant.

Accessible Route & Features

Entry, North Front Doors	Compliant pair doors with pull handles, panic at interior. Verify and adjust closer pressures.
Entry, South	Verify clearances at pair doors. Verify exit hardware. Remove and replace exterior handles and hardware if thumb latch present.
Entry, East	Verify clearances at pair doors. Verify exit hardware. Remove and replace exterior handles and hardware if thumb latch present.
Play Room 10	Verify entry door and play ground exit door have 32" clearances. Provide lever handle hardware.
Classroom doors	Provide all classrooms with lever handle hardware.

Plumbing Elements

Office 1B	Provide an accessible sink.
-----------	-----------------------------

Communication Elements

Signage	Provide accessible signage at the accessible restrooms and common spaces. If signage is provided at classrooms, provide accessible signage.
Classrooms	Any need for assisted listening devices in programs at this school? Or within SPED classrooms?

Special Spaces, Built-in Elements & Recreational Facilities

Office	Provide an accessible (lowered) portion of counter.
Play Surface	Verify and test existing play structure safety surfacing. Mulch must be solid enough to allow wheelchair access.
Play Structure	Verify that existing play structure is accessible, and modify if needed.

Field Notes:

1. Limited exterior play area. Adjacent Grant Park has unfenced, shared hard and soft play surfaces for school use.

