

PORTLAND PUBLIC SCHOOLS – FACILITY ADA ASSESSMENT

Rice (TOSA, Leased)
August 31, 2009

Site Accessibility

East Parking	(2) accessible stalls and access aisle(s) required for size of parking area. Restripe stalls and aisles.
--------------	--

Accessible Route & Features

East Entry	Verify door clearances and threshold, and door hardware for accessibility compliance.
South Entry	Verify door clearances and threshold, and door hardware for accessibility compliance.
West Entry	Verify door clearances and threshold, and door hardware for accessibility compliance.
Rooms	Provide lever handle hardware at all classroom and common room entry doors.

Plumbing Elements

Boys Restroom	Accessible toilet stall, clearances, toilet, grab bars, lavatory and accessories within reach ranges. Verify or replace entry doors for compliant width and clearances.
Girls Restroom	Accessible toilet stall, clearances, toilet, grab bars, lavatory and accessories within reach ranges. Verify or replace entry doors for compliant width and clearances.
Adult Unisex Restroom	An accessible toilet, clearances, grab bars, lavatory and accessories within reach ranges. Verify or replace entry doors for compliant width and clearances.
Drinking Fountain	One compliant height drinking fountain on the main floor.
Office/Faculty	Provide an accessible sink.

Communication Elements

Play Room 8	Provide assisted listening devices.
Room 9	Provide assisted listening devices.
Signage	Provide accessible signage at new accessible restrooms and common spaces. If signage is provided at classrooms, provide accessible signage.

Special Spaces, Built-in Elements & Recreational Facilities

Office	Provide an accessible (lowered) service counter.
Play Surface	There is (1) soft surfacing play areas at this school. Verify and test existing play structure safety surfacing at this area. Mulch/ground cover must be solid enough for wheelchair access.
Play Structure	Verify that the existing play structure is accessible, and modify if needed.

