

PORTLAND PUBLIC SCHOOLS – FACILITY ADA ASSESSMENT

Terwilliger K-5 (leased)
August 31, 2009

Site Accessibility

North Parking	(1) accessible stall with accessible aisle at north parking area. Verify stall accessible signage.
South Parking	No accessible parking at south parking lot (13 total spaces using double deep on one side).

Accessible Route & Features

North Entry	Side entry door has one step from sidewalk. No handrails. Revise paving to a sloped ramp with compliant double handrails (approximately 6 lf of ramp.) Add signage to make this entry the accessible entry. Verify that accessible door hardware is provided. Add ramp to interior 3-steps with compliant double handrails at steps and ramp (approximately 18 lf of ramp.) Alternatively, a lift could be provided.
Northeast Entry	7 steps up to door with non-compliant handrails. Add compliant double handrails at stairs (approximately 36 lf of rail.) Provide accessible double handrails at the interior steps (approximately 20 lf of rail.) Verify that accessible door hardware is provided.
West Front Entry	Steps up to front entry door. Provide compliant double handrails at main stairs (approximately 24 lf of rail.) It would improve accessibility to add compliant ramp to main front entry door sequence. Verify that accessible door hardware is provided.
Corbett Entry Path	Formal front entry path from SW Corbett has stairs leading from sidewalk. No handrails. Add compliant double handrails to exterior stairs (approximately 40 lf of rail.)
Portable Classrooms	Add compliant ramp and stairs up to four classroom entries (approximately 24 lf of ramp.)
Classrooms	Provide lever handle hardware at all classroom entry doors.

Plumbing Elements

Boys Restroom	Accessible toilet stall, clearances, toilet, grab bars, lavatory and accessories within reach ranges. Verify or replace entry doors for compliant width and clearances.
Girls Restroom	Accessible toilet stall, clearances, toilet, grab bars, lavatory and accessories within reach ranges. Verify or replace entry doors for compliant width and clearances.
Adult Unisex Restroom	An accessible toilet, clearances, grab bars, lavatory and accessories within adult reach ranges. Verify or replace entry doors for compliant width and clearances. Provide occupancy indicator lever hardware.
Drinking Fountain	One set of compliant dual height drinking fountains on the main floor.
Office/Faculty	If a sink is provided, provide an accessible sink.



Communication Elements

Assembly	Provide assisted listening devices.
North Entry	If this entry is locker during school hours, provide a 2-way audio/visual communication device at exterior connected to office.
Signage	Provide accessible signage at new accessible restrooms and common spaces. If signage is provided at classrooms, provide accessible signage.

Special Spaces, Built-in Elements & Recreational Facilities

Play Surfaces	There are (3) soft surfacing play areas at this school. Verify and test existing play structure safety surfacing at these areas. Mulch/ground cover must be solid enough to allow wheelchair access.
Play Structure	Verify that at least one existing play structure is accessible, and modify if needed.

