

PORTLAND PUBLIC SCHOOLS – FACILITY ADA ASSESSMENT

Wilcox Facility (CRP)
August 31, 2009

Site Accessibility

Parking	(2) accessible on-site parking spaces marked and striped. Relocate west most accessible space to east of striped median.
---------	--

Accessible Route & Features

Office	Update 3'-2" office entry door with lever handles.
Classroom doors	Provide all classrooms with lever handle hardware. (10) Classrooms.

Plumbing Elements

Main Floor Boys	Provide accessible toilet stall, clearances, lavatory and accessories within reach ranges. Verify door hardware and swing provides 32" clearance each way for entry and exiting.
Main Floor Girls	Provide accessible toilet stall, clearances, lavatory and accessories within reach ranges. Verify door hardware and swing provides 32" clearance each way for entry and exiting.
Drinking Fountain	Update or provide a compliant dual height fountain at the north/south corridor closes to restrooms.
Office/Faculty 16	Provide sink at 34 inches high.

Communication Elements

Main North Entry	Verify entry signage from parking is legible.
Interior signage	Provide accessible signage at upgraded restrooms and common rooms (including the rooms currently being used for student testing.) If signage is provided at the classrooms, provide accessible signage.

Special Spaces, Built-in Elements & Recreational Facilities

Play Area Surface	There is (1) soft play area at the outside play areas. Verify and test existing play structure safety surfacing at this area. Mulch/ground cover must be solid enough to allow wheelchair access.
Play Structure	Verify that the existing play structure is accessible, and modify if needed.

