

# PORTLAND PUBLIC SCHOOLS – FACILITY ADA ASSESSMENT

Woodstock School      K-5  
August 31, 2009

## Site Accessibility

Parking	No on-site parking available at this school. Arrange with City to provide (1) curbside accessible space along SE 50th Avenue just east of main entry, along with signage. There is an existing curbcut in line with the front entrance that can be used for access.
Main South Entry	Existing accessible entry ramp to side of main steps to front door of building. Ramp and handrails are compliant. Steps up to front doors need handrails. Add double height handrails each side of entry steps (approximately 16 lf of rail.)

## Accessible Route & Features

Stage 14C	Add a lift at the east side stage area adjacent to the corridor to provide accessibility for the raised stage area.
Interior Ramp	Verify slope of interior ramp at E/W corridor near cafetorium 14. Verify double height handrails on each side conforming to children and adult handrail heights approximately 50 lf of rail.)
Cafetorium 14	Revise (1) south pair of entry doors with swing clear hinges and appropriate closers to ensure minimum 32-inch single door clearances. (Doors are existing 2'-6" pairs.) Otherwise, replace with 3-0/2-0 unequal pair doors for compliance. Note, 2-6 pair of doors on hold open are fine for accessible ingress, but not for egress when the fire alarm triggers the doors to close.
Classroom doors	Provide all classrooms with lever handle hardware.

## Plumbing Elements

Office/Faculty	Provide a sink at 34 inches high.
----------------	-----------------------------------

## Communication Elements

Cafetorium 14	Provide assisted listening devices.
Classrooms	Any need for assisted listening devices in programs at this school? Or within SPED classrooms?
Signage	Verify accessible signage is provided at accessible restrooms and common spaces. If signage is provided at classrooms, provide accessible signage.

## Special Spaces, Built-in Elements & Recreational Facilities

Play Surface	There is (1) soft play area at the outside play area. Verify and test existing play structure safety surfacing at these areas. Mulch/ground cover must be solid enough to allow wheelchair access.
Play Structure	Verify that the existing play structure is accessible, and modify if needed.

