



# ATKINSON

## ACCESSIBILITY SUMMARY



Atkinson School  
5800 SE Division Street  
Portland, OR 97206

### SUMMARY

All common areas at Atkinson are located on the ground level, but the ground level varies significantly between common areas in three connected buildings. Priority should be given to providing classroom door hardware. The door hardware and a stage ramp comprise the majority of the upgrade work. The major accessibility upgrades for Atkinson are summarized on this sheet.

### ACCESSIBILITY UPGRADES TO MEET 2008 ADA GUIDELINES

Site Elements	Restripe accessible parking stalls Accessible exterior handrails
Accessible Route & Reach Ranges	East wing ramp handrails Accessible ramp Classroom door lever handle hardware
Plumbing Elements	Accessible boys and girls restrooms at east wing
Communication Elements	Assisted listening devices at cafeteria/auditorium Signage
Recreational Facilities	Soft play area surfacing for wheelchair accessibility

### COST BREAKDOWN

Cost information provided is based on 2009 estimated unit costs for direct construction including general contractor overhead. Additionally, estimated hard costs and soft costs provided by PPS have been included.

Site Elements	\$4,836
Accessible Route & Reach Ranges	\$67,172
Plumbing Elements	\$27,673
Communication Elements	\$7,972
Special Spaces	\$0
Built-In Elements	\$0
Recreational Facilities	\$30,234
Special Education	\$2,340
Total	\$140,227