



BRIDGER ACCESSIBILITY SUMMARY



Bridger School
7910 SE Market Street
Portland, OR 97215

SUMMARY

All common areas at Bridger are located on the ground floor. Priority should be given to providing directional signage and door hardware. The door hardware, lift and signage comprise the majority of the upgrade work. The major accessibility upgrades for Bridger are summarized on this sheet.

ACCESSIBILITY UPGRADES TO MEET 2008 ADA GUIDELINES

Accessible Route & Reach Ranges	Lift at stage Widen SPED classroom entry for accessible clearances Classroom lever handle hardware
Plumbing Elements	Cafetorium dual height drinking fountain Accessible locker rooms
Communication Elements	2-way communications at northwest entry Assisted listening devices at cafetorium Signage
Built-In Elements	Accessible benches
Recreation Facilities	Accessible play area surface & structure

COST BREAKDOWN

Cost information provided is based on 2009 estimated unit costs for direct construction including general contractor overhead. Additionally, estimated hard costs and soft costs provided by PPS have been included.

Site Elements	\$0
Accessible Route & Reach Ranges	\$87,792
Plumbing Elements	\$32,228
Communication Elements	\$13,324
Special Spaces	\$0
Built-In Elements	\$4,100
Recreational Facilities	\$6,834
Special Education	\$4,680
Total	\$148,958