



# MARYSVILLE

## ACCESSIBILITY SUMMARY



Marysville School  
7733 SE Raymond Street  
Portland, OR 97206

### SUMMARY

All common areas at Marysville are located on the ground floor. Priority should be given to the handrails, lifts and visual communications device. The lifts, handrails, door hardware and plumbing comprise the majority of upgrade work. The major accessibility upgrades for Marysville are summarized on this sheet.

### ACCESSIBILITY UPGRADES TO MEET 2008 ADA GUIDELINES

Site Elements	Accessible handrails
Accessible Route & Reach Ranges	Lift for stage access
	Lift to access girls gymnasium
	Classroom lever door hardware
Plumbing Elements	Accessible showers at boys and girls lockers
	Accessible sinks at office and art 4
Communication Elements	Additional 2-way visual communications device at west entry
	Assisted listening devices at auditorium/cafeteria
	Accessible interior signage
Built-In Elements	Accessible benches at boys and girls locker rooms
Recreational Facilities	Accessible play area soft surfacing & structure

### COST BREAKDOWN

Cost information provided is based on 2009 estimated unit costs for direct construction including general contractor overhead. Additionally, estimated hard costs and soft costs provided by PPS have been included.

Site Elements	\$11,051
Accessible Route & Reach Ranges	\$157,643
Plumbing Elements	\$31,556
Communication Elements	\$11,617
Special Spaces	\$0
Built-In Elements	\$4,100
Recreational Facilities	\$20,874
Special Education	\$0
<b>Total</b>	<b>\$236,841</b>