

RIGLER

ACCESSIBILITY SUMMARY



Rigler School 5401 NE Prescott Street Portland, OR 97218

SUMMARY

Some common areas at Rigler are located on the ground floor, but the cafeteria is on the inaccessible basement level. Priority should be given to providing an elevator for access to basement cafeteria and basement and second floor classrooms at this school. The elevator, lift, ramp, door hardware and plumbing on floors other than the main level comprise the majority of the upgrade work. The major accessibility upgrades for Rigler are summarized on this sheet.

These two pairs of doors at Rigler are a good example which illustrates a solution to replace two 30-inch inaccessible doors with an accessible unequal pair of 36-inch/24-inch doors.



Non-compliant/Compliant Doors

ACCESSIBILITY UPGRADES TO MEET 2008 ADA GUIDELINES

Site Elements Accessible handrails at sloped path/ramp
Accessible ramp at portable classrooms

& Reach Ranges Lift for stage access

Classroom lever door hardware

Accessible handrails at one interior full height staircase

Plumbing Accessible boys and girls restrooms at second floor
Elements Accessible drinking fountains basement and second floors

Accessible locker rooms

Accessible sink

Communication Assisted listening devices at auditorium

Elements Additional exterior parking and directional signage

Signage

Special Spaces Wheelchair and companion seating

Recreational Facilities

Accessible play area soft surfacing & structure

COST BREAKDOWN

Cost information provided is based on 2009 estimated unit costs for direct construction including general contractor overhead. Additionally, estimated hard costs and soft costs provided by PPS have been included.

Accessible Route & Reach Ranges	\$603,230
Plumbing Elements	\$71,013
Communication Elements	\$11,957
Special Spaces	\$3,273
Built-In Elements	\$98,492
Recreational Facilities	\$21,810
Special Education	\$0
Total	\$931,153