

## PORTLAND PUBLIC SCHOOLS

# ROOSEVELT ACCESSIBILITY SUMMARY



Roosevelt High School 6941 N Central Street Portland, OR 97203

#### SUMMARY

Roosevelt has an elevator, but the it does not provide access to the west library addition basement or the second floor. Additionally, the east wing is not served by the elevator. The cafeteria is connected via an exterior ramp, rather than an interior accessible route. Priority should be given to providing access to the common areas in these spaces, particularly the library and computer labs. The major accessibility upgrades for Roosevelt are summarized on this sheet. This ramp at Roosevelt is an example which illustrates exterior access only between variable main floor levels of building additions in need of an interior accessible route.



Exterior ramp into cafeteria

### ACCESSIBILITY UPGRADES TO MEET 2008 ADA GUIDELINES

| Site Elements                      | Additional accessible parking space with signage<br>Accessible striping a pedestrian route at parking<br>Ramp and handrails at stadium seating and track  |
|------------------------------------|---|
| Accessible Route<br>& Reach Ranges | Replacement handrails in one main stair<br>Elevator or lift to provide access to student support<br>spaces above cafeteria addition<br>Elevator to provide access to gym locker, mat and weight<br>rooms<br>Lift at stage                                   |
| Plumbing<br>Elements               | Accessible student restrooms at cafeteria<br>Accessible staff unisex restroom at cafeteria<br>Accessible locker rooms<br>Accessible drinking fountains<br>Accessible sinks and gases at science classrooms<br>Accessible sinks at home economics classrooms |
| Communication<br>Elements          | Assisted listening devices at performance spaces using audio amplification Signage  |
| Special Spaces                     | Additional wheelchair spaces at auditorium<br>Accessible work counter in home economics   |
| Built-In Elements                  | Accessible benches at locker rooms and play fields<br>Accessible service counter  |
| Recreational<br>Facilities         | Accessible clearances at exercise equipment   |

#### COST BREAKDOWN

Cost information provided is based on 2009 estimated unit costs for direct construction including general contractor overhead. Additionally, estimated hard costs and soft costs provided by PPS have been included.

| Site Elements                   | \$185,131   |
|---------------------------------|-------------|
| Accessible Route & Reach Ranges | \$1,035,236 |
| Plumbing Elements               | \$128,514   |
| Communication Elements          | \$26,693    |
| Special Spaces                  | \$29,916    |
| Built-In Elements               | \$12,755    |
| Recreational Facilities         | \$4,555     |
| Special Education               | \$4,680     |
| Total                           | \$1,427,481 |