

SCOTT

ACCESSIBILITY SUMMARY



Scott Elementary School 6700 NE Prescott Street Portland, OR 97210

SUMMARY

Most common areas at Scott are located on the ground floor, but the ground floor level varies. Priority should be given to providing an elevator to access the basement cafeteria at this school. Secondary concerns are to revise the interior ramp for compliance, upgrade the student restrooms in the east wing and provide a lift for access to the stage. The elevator, ramp, lift, door hardware and plumbing comprise the majority of the upgrade work. The major accessibility upgrades for Scott are summarized on this sheet.

ACCESSIBILITY UPGRADES TO MEET 2008 ADA GUIDELINES

Accessible Route Elevator for access to cafeteria and gym & Reach Ranges Accessible ramp in the classroom building

Lift for stage access
Accessible handrails
Lever hardware on doors

Accessible door and frame remodel

Plumbing Accessible student restrooms in east wing Elements Accessible drinking fountain in east wing

Accessible sinks

Communication Assisted listening device in gym and cafeteria

Signage

Recreational Accessible play area soft surfacing & structure

Facilities

Elements

COST BREAKDOWN

Cost information provided is based on 2009 estimated unit costs for direct construction including general contractor overhead. Additionally, estimated hard costs and soft costs provided by PPS have been included.

Site Elements	\$17,079
Accessible Route & Reach Ranges	\$546,278
Plumbing Elements	\$27,000
Communication Elements	\$11,388
Special Spaces	\$0
Built-In Elements	\$0
Recreational Facilities	\$30,000
Special Education	\$2,340
Total	\$634,085