



Updated: December 07, 2018

COMMON AREAS - INCLUDES KITCHEN FOOD PREPARATION TAPS

FIXTURE LOCATIONS # RETURNED TO SERVICE # TURNED OFF DUE TO TEST RESULTS # REMAINING TO BE RETURNED TO SERVICE

Totals:	1323	925	187	398	NOTES
ABERNETHY	20	13	2	7	2 fixtures off due to test results (more extensive plumbing repairs needed) 5 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
AINSWORTH	16	12	1	4	1 fixture off due to test results (more extensive plumbing repairs needed) 3 fixtures require reappear prior to testing (refer to Water Quality Program Schedule)
ALAMEDA	17	13	0	4	4 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
APPLEGATE	3	2	0	1	1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
ARLETA	15	6	5	9	5 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
ASTOR	12	12	0	0	All 12 fixtures returned to service
ATKINSON	5	5	0	0	All 5 fixtures returned to service
BEACH	22	22	0	0	All 22 fixtures returned to service
BEAUMONT	21	13	4	8	4 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 3 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
BENSON	43	36	5	7	5 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture off due to sharing a water source with an associated fixture that tested above action level (more extensive plumbing repair needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
BEVERLY CLEARY/FERNWO	16	14	2	2	2 fixtures off due to test results (more extensive plumbing repairs needed)
BOISE-ELIOT	11	7	3	4	3 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
BRIDGER	13	10	2	3	2 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture off due to sharing a water source with an associated fixture that tested above action level (more extensive plumbing repair needed)
BRIDLEMILE	9	4	0	5	5 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
BUCKMAN	27	18	2	9	2 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture off due to sharing a water source with an associated fixture that tested above action level (more extensive plumbing repair needed) 6 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
CAPITOL HILL	12	7	5	5	5 fixtures off due to test results (more extensive plumbing repairs needed)
CHAPMAN	11	9	2	2	2 fixtures off due to test results (more extensive plumbing repairs needed)
CHAVEZ	18	17	0	1	1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
CHIEF JOSEPH	6	4	2	2	2 fixtures off due to test results (more extensive plumbing repairs needed)
CLARENDON	4	4	0	0	All 4 fixtures returned to service
CLEVELAND	22	12	8	10	8 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)

PPS WATER QUALITY PROGRAM SUMMARY

COLUMBIA	11	0	0	11	11 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
CREATIVE SCIENCE	8	6	2	2	2 fixtures off due to test results (more extensive plumbing repairs needed)
CRESTON	15	13	0	2	2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
DUNIWAY	15	6	6	9	6 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
EAST SYLVAN	6	4	2	2	2 fixtures off due to test results (more extensive plumbing repairs needed)
EDWARDS	6	6	0	0	All 6 fixtures returned to service
FOREST PARK	11	8	1	3	1 fixture off due to test results (more extensive plumbing repairs required) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
GEORGE	9	8	0	1	1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule).
GLENCOE	10	9	0	1	1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
GRANT @ MARSHALL	36	20	8	16	8 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 6 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
GREEN THUMB	1	0	0	1	1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
GROUT	33	18	9	15	9 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 3 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
HARRISON PARK	15	12	3	3	3 fixtures off due to test results (more extensive plumbing repairs needed)
HAYHURST	6	6	0	0	All 6 fixtures returned to service
HOLLADAY CENTER	5	2	1	3	1 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures requires additional repair prior to testing (refer to Water Quality Program Schedule)
HOLLYROOD	1	0	0	1	1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
HOSFORD	23	17	1	6	1 fixture off due to test results (more extensive plumbing repairs needed) 5 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
HUMBOLDT	9	8	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
IRVINGTON	26	23	1	3	1 fixture off due to test results (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
JACKSON	26	18	3	8	3 fixtures off due to test results (more extensive plumbing repairs needed) 5 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
JAMES JOHN	25	20	3	5	3 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule).
JEFFERSON	45	22	10	23	10 fixtures off due to test results (more extensive plumbing repairs needed) 13 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
KELLY	12	10	2	2	2 fixtures off due to test results (more extensive plumbing repairs needed)
KENTON	9	0	0	9	9 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
KING	23	20	1	3	1 fixture off due to test results (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)

PPS WATER QUALITY PROGRAM SUMMARY

LANE	13	11	1	2	1 fixture off due to test results (more extensive plumbing repairs needed) 1 fixture off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed)
LAURELHURST	14	14	0	0	All 14 fixtures returned to service
LEE	10	8	1	2	1 fixture are ready to return to service (refer to Water Quality Program Schedule) 1 fixture off due to test results (more extensive plumbing repairs needed)
LENT	15	12	1	3	1 fixture off due to test results (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
LEWIS	10	10	0	0	All 10 fixtures returned to service
LINCOLN	33	8	8	25	8 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 15 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
LLEWELLYN	19	6	10	13	10 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
MADISON	43	18	13	25	13 fixtures off due to test results (more extensive plumbing repairs needed) 6 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 6 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
MAPLEWOOD	9	5	4	4	4 fixtures off due to test results (more extensive plumbing repairs needed)
MARKHAM	8	7	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
MARYSVILLE	10	10	0	0	All 10 fixtures returned to service
MEEK PROFESSIONAL TECHNICAL	7	4	1	3	2 fixtures ready to return to service (refer to Water Quality Program Schedule). 1 fixture off due to test results (more extensive plumbing repairs needed)
MLC	7	4	2	3	2 fixtures off due to testing results (more extensive plumbing repairs needed) 1 fixture off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed)
MONROE/DA VINCI	24	22	0	2	2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
MT TABOR	5	3	1	2	1 fixture off due to test results (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
OCKLEY GREEN	13	13	0	0	All 13 fixtures returned to service
PENINSULA	10	7	3	3	3 fixtures off due to test results (more extensive plumbing repairs needed)
RICHMOND	20	18	0	2	2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
RIEKE	11	7	0	4	4 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
RIGLER	15	12	3	3	3 fixtures off due to test results (more extensive plumbing repairs needed)
ROBERT GRAY	17	7	10	10	10 fixtures off due to test results (more extensive plumbing repairs needed)
ROSA PARKS	10	9	0	1	1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
ROSE CITY PARK	17	14	1	3	1 fixture off due to test results (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
ROSEWAY HEIGHTS	12	10	1	2	1 fixture off due to test results (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)

PPS WATER QUALITY PROGRAM SUMMARY

SABIN	13	13	0	0	All 13 fixtures returned to service
SACAJAWEA	5	5	0	0	All 5 fixtures returned to service
SCOTT	11	7	3	4	3 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
SELLWOOD	19	10	4	9	4 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 3 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
SITTON	10	9	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
SKYLINE	7	6	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
STEPHENSON	8	5	2	3	2 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
SUNNYSIDE	19	12	2	7	2 fixtures off due to test results (more extensive plumbing repairs needed) 5 fixtures require additional repair prior to sampling (refer to Water Quality Program Schedule)
TERWILLIGER	9	0	0	9	9 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
TUBMAN	12	9	2	3	2 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
VERNON	13	13	0	0	All 13 fixtures have been returned to service.
VESTAL	18	18	0	0	All 18 fixtures returned to service
WEST SYLVAN	12	11	0	1	1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
WHITMAN	12	12	0	0	All 12 fixtures returned to service
WILSON	50	29	6	21	6 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 13 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
WINTERHAVEN	12	6	4	6	4 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed)
WOODLAWN	9	8	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
WOODMERE	8	6	2	2	2 fixtures off due to test results (more extensive plumbing repairs needed)
WOODSTOCK	13	10	0	3	3 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
YOUNGSON	2	1	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)