



COMMON AREA - INCLUDES KITCHEN FOOD PREPARATION TAPS

FIXTURE LOCATIONS # RETURNED TO SERVICE # TURNED OFF DUE TO TEST RESULTS # REMAINING TO BE RETURNED TO SERVICE

Updated:
Friday, February 22, 2019

TOTALS	1333	934	176	399	NOTES
Abernethy	20	12	0	8	8 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Ainsworth	12	11	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Alameda	17	13	0	4	2 fixtures ready to return to service (refer to Water Quality Program Schedule) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Applegate	4	3	0	1	1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
Arleta	15	6	7	9	7 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to sampling (refer to Water Quality Program Schedule)
Astor	12	12	0	0	All 12 fixtures returned to service
Atkinson	5	5	0	0	All 5 fixtures returned to service
Beach	22	22	0	0	All 22 fixtures returned to service
Beaumont	23	13	6	10	6 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 3 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Benson	43	37	4	6	4 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture off due to sharing a water source with an associated fixture that tested above action level (more extensive plumbing repair needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
Beverly Cleary/Fernwood	15	12	1	3	1 fixture off due to test results (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Beverly Cleary/Hollywood	1	0	0	1	1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
Boise-Eliot	10	7	3	3	3 fixtures off due to test results (more extensive plumbing repairs needed)
Bridger	17	10	2	7	2 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture off due to sharing a water source with an associated fixture that tested above action level (more extensive plumbing repair needed) 4 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Bridlemile	8	4	0	4	4 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Buckman	27	22	2	5	2 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture off due to sharing a water source with an associated fixture that tested above action level (more extensive plumbing repair needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Capitol Hill	13	7	3	6	3 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Chapman	11	9	2	2	2 fixtures off due to test results (more extensive plumbing repairs needed)
Chavez	22	17	0	5	5 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Chief Joseph	6	4	2	2	2 fixtures off due to test results (more extensive plumbing repairs needed)
Clarendon	4	4	0	0	All 4 fixtures returned to service
Cleveland	24	12	8	12	8 fixtures off due to test results (more extensive plumbing repairs needed) 4 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Columbia	11	3	0	8	4 fixtures off due to test results (refer to Water Quality Program Schedule) 4 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Creative Science	8	6	2	2	2 fixtures off due to test results (more extensive plumbing repairs needed)



COMMON AREA - INCLUDES KITCHEN FOOD PREPARATION TAPS

FIXTURE LOCATIONS # RETURNED TO SERVICE # TURNED OFF DUE TO TEST RESULTS # REMAINING TO BE RETURNED TO SERVICE

Updated:
Friday, February 22, 2019

TOTALS	1333	934	176	399	NOTES
Creston	16	13	0	3	3 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Duniway	13	4	6	9	6 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
East Sylvan	5	3	2	2	2 fixtures off due to test results (more extensive plumbing repairs needed)
Edwards	6	6	0	0	All 6 fixtures returned to service
Forest Park	11	9	1	2	1 fixture off due to test results (more extensive plumbing repairs required) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
George	8	6	1	2	1 fixture off due to test results (more extensive plumbing repairs required) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule).
Glencoe	10	9	0	1	1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
Grant @ Marshall	33	22	10	11	10 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed)
Green Thumb	3	0	0	3	3 fixtures ready to be commissioned
Grout	33	8	10	25	10 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 12 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Harrison Park	15	12	3	3	3 fixtures off due to test results (more extensive plumbing repairs needed)
Hayhurst	6	6	0	0	All 6 fixtures returned to service
Holladay Center	5	3	0	2	2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Hosford	22	16	2	6	2 fixtures off due to test results (more extensive plumbing repairs needed) 4 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Humboldt	9	8	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Irvington	26	22	1	4	1 fixture off due to test results (more extensive plumbing repairs needed) 3 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Jackson	27	20	3	7	3 fixtures off due to test results (more extensive plumbing repairs needed) 4 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
James John	25	20	2	5	2 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
Jefferson	44	25	10	19	10 fixtures off due to test results (more extensive plumbing repairs needed) 9 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Kelly	12	9	1	3	1 fixture off due to test results (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Kenton	11	0	0	11	11 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
King	22	20	1	2	1 fixture off due to test results (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
Lane	13	11	2	2	2 fixtures off due to test results (more extensive plumbing repairs needed)
Laurelhurst	14	14	0	0	All 14 fixtures returned to service



COMMON AREA - INCLUDES KITCHEN FOOD PREPARATION TAPS

FIXTURE LOCATIONS # RETURNED TO SERVICE # TURNED OFF DUE TO TEST RESULTS # REMAINING TO BE RETURNED TO SERVICE

Updated:
Friday, February 22, 2019

TOTALS	1333	934	176	399	NOTES
Lee	10	8	1	2	1 fixture off due to test results (more extensive plumbing repairs needed) 1 fixture are ready to return to service (refer to Water Quality Program Schedule)
Lent	15	12	1	3	1 fixture off due to test results (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Lewis	10	10	0	0	All 10 fixtures returned to service
Lincoln	33	19	7	14	7 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 5 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Llewellyn	19	2	8	17	8 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 7 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Madison	43	15	8	28	8 fixtures off due to test results (more extensive plumbing repairs needed) 6 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 14 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Maplewood	13	5	2	8	2 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Markham	8	7	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Marysville	10	10	0	0	All 10 fixtures returned to service
Meek	7	5	2	2	2 fixtures off due to test results (more extensive plumbing repairs needed)
MLC	7	5	2	2	2 fixtures off due to testing results (more extensive plumbing repairs needed)
Monroe/da Vinci	24	21	0	3	3 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Mt. Tabor	5	4	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Ockley Green	11	11	0	0	All 11 fixtures returned to service
Peninsula	11	8	3	3	3 fixtures off due to test results (more extensive plumbing repairs needed)
Richmond	20	19	0	1	1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
Rieke	14	8	0	6	6 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Rigler	18	11	4	7	4 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Robert Gray	17	7	7	10	7 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Rosa Parks	9	9	0	0	All 9 fixtures have been returned to service
Rose City Park	17	16	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Roseway Heights	12	11	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Sabin	13	13	0	0	All 13 fixtures returned to service
Sacajawea	5	4	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Scott	11	7	3	4	3 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)



COMMON AREA - INCLUDES KITCHEN FOOD PREPARATION TAPS

FIXTURE LOCATIONS # RETURNED TO SERVICE # TURNED OFF DUE TO TEST RESULTS # REMAINING TO BE RETURNED TO SERVICE

Updated:
Friday, February 22, 2019

TOTALS	1333	934	176	399	NOTES
Sellwood	18	11	2	7	2 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 3 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Sitton	10	9	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Skyline	7	6	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Stephenson	8	4	2	4	2 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Sunnyside	19	12	1	7	1 fixtures off due to test results (more extensive plumbing repairs needed) 6 fixtures require additional repair prior to sampling (refer to Water Quality Program Schedule)
Terwilliger	9	2	0	7	7 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Tubman	12	11	1	1	1 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
Vernon	13	13	0	0	All 13 fixtures have been returned to service.
Vestal	18	18	0	0	All 18 fixtures returned to service
West Sylvan	12	11	0	1	1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
Whitman	12	12	0	0	All 12 fixtures returned to service
Wilson	56	29	8	27	8 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 17 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Winterhaven	12	5	3	7	3 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Woodlawn	9	6	1	3	1 fixture off due to test results (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Woodmere	8	6	2	2	2 fixtures off due to test results (more extensive plumbing repairs needed)
Woodstock	13	12	0	1	1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
Youngson	2	1	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)



COMMON AREA - INCLUDES KITCHEN FOOD PREPARATION TAPS

FIXTURE LOCATIONS # RETURNED TO SERVICE # TURNED OFF DUE TO TEST RESULTS # REMAINING TO BE RETURNED TO SERVICE

Updated:
Friday, February 22, 2019

TOTALS	1333	934	176	399	NOTES
Abernethy	20	12	0	8	8 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Ainsworth	12	11	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Alameda	17	13	0	4	2 fixtures ready to return to service (refer to Water Quality Program Schedule) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Applegate	4	3	0	1	1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
Arleta	15	6	7	9	7 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to sampling (refer to Water Quality Program Schedule)
Astor	12	12	0	0	All 12 fixtures returned to service
Atkinson	5	5	0	0	All 5 fixtures returned to service
Beach	22	22	0	0	All 22 fixtures returned to service
Beaumont	23	13	6	10	6 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 3 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Benson	43	37	4	6	4 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture off due to sharing a water source with an associated fixture that tested above action level (more extensive plumbing repair needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
Beverly Cleary/Fernwood	15	12	1	3	1 fixture off due to test results (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Beverly Cleary/Hollywood	1	0	0	1	1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
Boise-Eliot	10	7	3	3	3 fixtures off due to test results (more extensive plumbing repairs needed)
Bridger	17	10	2	7	2 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture off due to sharing a water source with an associated fixture that tested above action level (more extensive plumbing repair needed) 4 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Bridlemile	8	4	0	4	4 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Buckman	27	22	2	5	2 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture off due to sharing a water source with an associated fixture that tested above action level (more extensive plumbing repair needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Capitol Hill	13	7	3	6	3 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Chapman	11	9	2	2	2 fixtures off due to test results (more extensive plumbing repairs needed)
Chavez	22	17	0	5	5 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Chief Joseph	6	4	2	2	2 fixtures off due to test results (more extensive plumbing repairs needed)
Clarendon	4	4	0	0	All 4 fixtures returned to service
Cleveland	24	12	8	12	8 fixtures off due to test results (more extensive plumbing repairs needed) 4 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Columbia	11	3	1	8	8 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Creative Science	8	6	2	2	2 fixtures off due to test results (more extensive plumbing repairs needed)



COMMON AREA - INCLUDES KITCHEN FOOD PREPARATION TAPS

FIXTURE LOCATIONS # RETURNED TO SERVICE # TURNED OFF DUE TO TEST RESULTS # REMAINING TO BE RETURNED TO SERVICE

Updated:
Friday, February 22, 2019

TOTALS	1333	934	176	399	NOTES
Creston	16	13	0	3	3 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Duniway	13	4	6	9	6 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
East Sylvan	5	3	2	2	2 fixtures off due to test results (more extensive plumbing repairs needed)
Edwards	6	6	0	0	All 6 fixtures returned to service
Forest Park	11	9	1	2	1 fixture off due to test results (more extensive plumbing repairs required) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
George	8	6	1	2	1 fixture off due to test results (more extensive plumbing repairs required) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule).
Glencoe	10	9	0	1	1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
Grant @ Marshall	33	22	10	11	10 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed)
Green Thumb	3	0	0	3	3 fixtures ready to be commissioned
Grout	33	8	10	25	10 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 12 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Harrison Park	15	12	3	3	3 fixtures off due to test results (more extensive plumbing repairs needed)
Hayhurst	6	6	0	0	All 6 fixtures returned to service
Holladay Center	5	3	0	2	2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Hosford	22	16	2	6	2 fixtures off due to test results (more extensive plumbing repairs needed) 4 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Humboldt	9	8	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Irvington	26	22	1	4	1 fixture off due to test results (more extensive plumbing repairs needed) 3 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Jackson	27	20	3	7	3 fixtures off due to test results (more extensive plumbing repairs needed) 4 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
James John	25	20	2	5	2 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
Jefferson	44	25	10	19	10 fixtures off due to test results (more extensive plumbing repairs needed) 9 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Kelly	12	9	1	3	1 fixture off due to test results (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Kenton	11	0	0	11	11 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
King	22	20	1	2	1 fixture off due to test results (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
Lane	13	11	2	2	2 fixtures off due to test results (more extensive plumbing repairs needed)
Laurelhurst	14	14	0	0	All 14 fixtures returned to service



COMMON AREA - INCLUDES KITCHEN FOOD PREPARATION TAPS

FIXTURE LOCATIONS # RETURNED TO SERVICE # TURNED OFF DUE TO TEST RESULTS # REMAINING TO BE RETURNED TO SERVICE

Updated:
Friday, February 22, 2019

TOTALS	1333	934	176	399	NOTES
Lee	10	8	1	2	1 fixture off due to test results (more extensive plumbing repairs needed) 1 fixture are ready to return to service (refer to Water Quality Program Schedule)
Lent	15	12	1	3	1 fixture off due to test results (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Lewis	10	10	0	0	All 10 fixtures returned to service
Lincoln	33	19	7	14	7 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 5 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Llewellyn	19	2	8	17	8 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 7 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Madison	43	15	8	28	8 fixtures off due to test results (more extensive plumbing repairs needed) 6 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 14 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Maplewood	13	5	2	8	2 fixtures off due to test results (more extensive plumbing repairs needed) 6 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Markham	8	7	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Marysville	10	10	0	0	All 10 fixtures returned to service
Meek	7	5	2	2	2 fixtures off due to test results (more extensive plumbing repairs needed)
MLC	7	5	2	2	2 fixtures off due to test results (more extensive plumbing repairs needed)
Monroe/da Vinci	24	21	0	3	3 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Mt. Tabor	5	4	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Ockley Green	11	11	0	0	All 11 fixtures returned to service
Peninsula	11	8	3	3	3 fixtures off due to test results (more extensive plumbing repairs needed)
Richmond	20	19	0	1	1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
Rieke	14	8	0	6	6 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Rigler	18	11	4	7	4 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Robert Gray	17	7	7	10	7 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Rosa Parks	9	9	0	0	All 9 fixtures have been returned to service
Rose City Park	17	16	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Roseway Heights	12	11	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Sabin	13	13	0	0	All 13 fixtures returned to service
Sacajawea	5	4	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Scott	11	7	3	4	3 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)



COMMON AREA - INCLUDES KITCHEN FOOD PREPARATION TAPS

FIXTURE LOCATIONS # RETURNED TO SERVICE # TURNED OFF DUE TO TEST RESULTS # REMAINING TO BE RETURNED TO SERVICE

Updated:
Friday, February 22, 2019

TOTALS	1333	934	176	399	NOTES
Sellwood	18	11	2	7	2 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 3 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Sitton	10	9	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Skyline	7	6	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Stephenson	8	4	2	4	2 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Sunnyside	19	12	1	7	1 fixtures off due to test results (more extensive plumbing repairs needed) 6 fixtures require additional repair prior to sampling (refer to Water Quality Program Schedule)
Terwilliger	9	2	0	7	7 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Tubman	12	11	1	1	1 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
Vernon	13	13	0	0	All 13 fixtures have been returned to service.
Vestal	18	18	0	0	All 18 fixtures returned to service
West Sylvan	12	11	0	1	1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
Whitman	12	12	0	0	All 12 fixtures returned to service
Wilson	56	29	8	27	8 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 17 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Winterhaven	12	5	3	7	3 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Woodlawn	9	6	1	3	1 fixture off due to test results (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Woodmere	8	6	2	2	2 fixtures off due to test results (more extensive plumbing repairs needed)
Woodstock	13	12	0	1	1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
Youngson	2	2	1	0	1 fixture off due to test results (more extensive plumbing repairs needed)