



COMMON AREA - INCLUDES KITCHEN FOOD PREPARATION TAPS

FIXTURE LOCATIONS # RETURNED TO SERVICE # TURNED OFF DUE TO TEST RESULTS # REMAINING TO BE RETURNED TO SERVICE

Updated:
Thursday, June 20, 2019

TOTALS	1340	1006	132	334	NOTES
Abernethy	20	20	0	0	All 20 fixtures returned to service
Ainsworth	12	12	0	0	All 12 fixtures returned to service
Alameda	17	13	0	4	2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule) 2 fixtures pending commissioning; planned for summer, 2019
Applegate	4	4	0	0	All 4 fixtures returned to service
Arleta	15	6	6	9	6 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 2 fixture requires additional repair prior to sampling (refer to Water Quality Program Schedule)
Astor	12	12	0	0	All 12 fixtures returned to service
Atkinson	5	5	0	0	All 5 fixtures returned to service
Beach	22	22	0	0	All 22 fixtures returned to service
Beaumont	24	13	3	11	3 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 7 fixtures pending commissioning; planned for summer, 2019
Benson	43	39	3	4	3 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture off due to sharing a water source with an associated fixture that tested above action level (more extensive plumbing repair needed)
Beverly Cleary/Fernwood	15	12	1	3	1 fixture off due to test results (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Beverly Cleary/Hollyrood	1	0	0	1	1 fixture pending commissioning; planned for summer, 2019
Boise-Eliot	10	10	0	0	All 10 fixtures returned to service
Bridger	17	10	0	7	7 fixtures pending commissioning; planned for summer, 2019
Bridlemile	9	8	0	1	1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Buckman	27	23	2	4	2 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture off due to sharing a water source with an associated fixture that tested above action level (more extensive plumbing repair needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
Capitol Hill	13	7	2	6	2 fixtures off due to test results (more extensive plumbing repairs needed) 4 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Chapman	11	11	0	0	All 11 fixtures returned to service
Chavez	22	17	0	5	5 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Chief Joseph	6	6	0	0	All 6 fixtures returned to service
Clarendon	4	4	0	0	All 4 fixtures returned to service
Cleveland	24	18	5	6	5 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixtures requires additional repair prior to testing (refer to Water Quality Program Schedule)
Columbia	14	2	4	12	5 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule) 4 fixtures pending commissioning; planned for summer, 2019
Creative Science	8	6	2	2	2 fixtures off due to test results (more extensive plumbing repairs needed)
Creston	16	13	1	3	1 fixture off due to test results (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Duniway	13	4	4	9	4 fixtures off due to test results (more extensive plumbing repairs needed) 5 fixtures pending commissioning; planned for summer, 2019



COMMON AREA - INCLUDES KITCHEN FOOD PREPARATION TAPS

FIXTURE LOCATIONS # RETURNED TO SERVICE # TURNED OFF DUE TO TEST RESULTS # REMAINING TO BE RETURNED TO SERVICE

Updated:
Thursday, June 20, 2019

TOTALS	1340	1006	132	334	NOTES
East Sylvan	6	5	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Edwards	6	6	0	0	All 6 fixtures returned to service
Forest Park	11	10	0	1	1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule).
George	8	6	1	2	1 fixture off due to test results (more extensive plumbing repairs required) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule).
Glencoe	10	9	0	1	1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
Grant @ Marshall	33	25	8	8	8 fixtures off due to test results (more extensive plumbing repairs needed)
Green Thumb	3	0	0	3	3 fixtures ready to be commissioned
Grout	33	7	17	26	19 fixtures off due to test results (more extensive plumbing repairs needed) 7 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Harrison Park	15	15	0	0	All 15 fixtures returned to service
Hayhurst	6	5	0	1	1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
Holladay Center	5	3	0	2	2 fixtures off due to test results (more extensive plumbing repairs needed)
Hosford	22	19	1	3	1 fixture off due to test results (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Humboldt	9	8	0	1	1 fixture pending commissioning; planned for summer, 2019
Irvington	26	24	1	2	1 fixture off due to test results (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
Jackson	27	20	3	7	3 fixtures off due to test results (more extensive plumbing repairs needed) 4 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
James John	25	20	2	5	2 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
Jefferson	44	37	7	7	6 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
Kelly	12	10	1	2	1 fixture off due to test results (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
Kenton	11	9	0	2	2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
King	22	18	1	4	1 fixture off due to test results (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule) 2 fixtures pending commissioning; planned for summer, 2019
Lane	13	9	0	4	2 fixtures pending commissioning; planned for summer, 2019
Laurelhurst	14	14	0	0	All 14 fixtures returned to service
Lee	10	10	0	0	All 10 fixtures returned to service
Lent	15	12	0	3	3 fixtures pending commissioning; planned for summer, 2019
Lewis	10	10	0	0	All 10 fixtures returned to service
Lincoln	33	26	5	7	5 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed)



COMMON AREA - INCLUDES KITCHEN FOOD PREPARATION TAPS

FIXTURE LOCATIONS # RETURNED TO SERVICE # TURNED OFF DUE TO TEST RESULTS # REMAINING TO BE RETURNED TO SERVICE

Updated:
Thursday, June 20, 2019

TOTALS	1340	1006	132	334	NOTES
Llewellyn	19	6	6	13	6 fixtures off due to test results (more extensive plumbing repairs needed) 4 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule) 3 fixtures pending commissioning; planned for summer, 2019
Madison	43	22	8	21	8 fixtures off due to test results (more extensive plumbing repairs needed) 6 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 14 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Maplewood	11	5	2	6	2 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule) 2 fixtures off due to test results (more extensive plumbing repairs needed)
Markham	8	7	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Marysville	10	10	0	0	All 10 fixtures returned to service
Meek	7	4	1	3	1 fixture off due to test results (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule) 1 fixture pending commissioning; planned for summer, 2019
MLC	7	5	2	2	2 fixtures off due to test results (more extensive plumbing repairs needed)
Monroe/da Vinci	24	21	1	3	1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule) 2 fixtures pending commissioning; planned for summer, 2019
Mt. Tabor	5	4	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Ockley Green	11	11	0	0	All 11 fixtures returned to service
Peninsula	11	9	2	2	2 fixtures off due to test results (more extensive plumbing repairs needed)
Richmond	20	19	0	1	1 fixture pending commissioning; planned for summer, 2019
Rieke	12	8	0	4	4 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Rigler	18	11	4	7	4 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule) 1 fixture pending commissioning; planned for summer, 2019
Robert Gray	17	7	5	10	4 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule) 3 fixtures pending commissioning; planned for summer, 2019
Rosa Parks	9	9	0	0	All 9 fixtures have been returned to service
Rose City Park	17	16	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Roseway Heights	12	12	0	0	All 12 fixtures returned to service
Sabin	13	13	0	0	All 13 fixtures returned to service
Sacajawea	5	4	0	1	1 fixture pending commissioning; planned for summer, 2019
Scott	11	7	0	4	4 fixtures pending commissioning; planned for summer, 2019
Sellwood	18	11	0	7	7 fixtures pending commissioning; planned for summer, 2019
Sitton	10	9	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Skyline	7	6	0	1	1 fixture pending commissioning; planned for summer, 2019
Stephenson	8	4	1	4	1 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Sunnyside	19	12	0	7	1 fixtures off due to test results (more extensive plumbing repairs needed) 6 fixtures require additional repair prior to sampling (refer to Water Quality Program Schedule)



COMMON AREA - INCLUDES KITCHEN FOOD PREPARATION TAPS

# FIXTURE LOCATIONS	# RETURNED TO SERVICE	# TURNED OFF DUE TO TEST RESULTS	# REMAINING TO BE RETURNED TO SERVICE
---------------------	-----------------------	----------------------------------	---------------------------------------

Updated:
Thursday, June 20, 2019

TOTALS	1340	1006	132	334	NOTES
Terwilliger	9	0	1	9	1 fixture off due to test results (more extensive plumbing repairs needed) 3 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule) 5 fixtures pending commissioning; planned for summer, 2019
Tubman	12	12	0	0	All 12 fixtures returned to service
Vernon	13	13	0	0	All 13 fixtures have been returned to service.
Vestal	18	18	0	0	All 18 fixtures returned to service
West Sylvan	12	11	0	1	1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
Whitman	12	12	0	0	All 12 fixtures returned to service
Wilson	56	29	8	27	8 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 17 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Winterhaven	11	5	3	6	3 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
Woodlawn	9	6	1	3	1 fixture off due to test results (more extensive plumbing repairs needed) 2 fixtures pending commissioning; planned for summer, 2019
Woodmere	8	6	1	2	1 fixture off due to test results (more extensive plumbing repairs needed) 1 fixture pending commissioning; planned for summer, 2019
Woodstock	13	10	0	3	1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule) 2 fixtures pending commissioning; planned for summer, 2019
Youngson	2	1	0	1	1 fixture pending commissioning; planned for summer, 2019