



COMMON AREA - INCLUDES KITCHEN FOOD PREPARATION TAPS

FIXTURE LOCATIONS # RETURNED TO SERVICE # TURNED OFF DUE TO TEST RESULTS # REMAINING TO BE RETURNED TO SERVICE

Updated:
Wednesday, July 24, 2019

| TOTALS | 1337 | 1092 | 130 | 245 | NOTES |
|--------------------------|-------------|-------------|------------|------------|---|
| Abernethy | 20 | 20 | 0 | 0 | All 20 fixtures returned to service |
| Ainsworth | 12 | 12 | 0 | 0 | All 12 fixtures returned to service |
| Alameda | 17 | 15 | 0 | 2 | 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule) |
| Applegate | 4 | 4 | 0 | 0 | All 4 fixtures returned to service |
| Arleta | 15 | 8 | 6 | 7 | 6 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) |
| Astor | 12 | 12 | 0 | 0 | All 12 fixtures returned to service |
| Atkinson | 5 | 5 | 0 | 0 | All 5 fixtures returned to service |
| Beach | 22 | 22 | 0 | 0 | All 22 fixtures returned to service |
| Beaumont | 24 | 20 | 3 | 4 | 3 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) |
| Benson | 43 | 39 | 3 | 4 | 3 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture off due to sharing a water source with an associated fixture that tested above action level (more extensive plumbing repair needed) |
| Beverly Cleary/Fernwood | 15 | 13 | 1 | 2 | 1 fixture off due to test results (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule) |
| Beverly Cleary/Hollyrood | 1 | 1 | 0 | 0 | All 1 fixture returned to service |
| Boise-Eliot | 10 | 10 | 0 | 0 | All 10 fixtures returned to service |
| Bridger | 17 | 17 | 0 | 0 | All 17 fixtures returned to service |
| Bridlemile | 9 | 8 | 0 | 1 | 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule) |
| Buckman | 27 | 23 | 2 | 4 | 2 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture off due to sharing a water source with an associated fixture that tested above action level (more extensive plumbing repair needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule) |
| Capitol Hill | 13 | 10 | 2 | 3 | 2 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule) |
| Chapman | 11 | 11 | 0 | 0 | All 11 fixtures returned to service |
| Chavez | 22 | 21 | 0 | 1 | 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule) |
| Chief Joseph | 6 | 6 | 0 | 0 | All 6 fixtures returned to service |
| Clarendon | 4 | 4 | 0 | 0 | All 4 fixtures returned to service |
| Cleveland | 24 | 18 | 5 | 6 | 5 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule) |
| Columbia | 12 | 7 | 4 | 5 | 4 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) |
| Creative Science | 8 | 6 | 2 | 2 | 2 fixtures off due to test results (more extensive plumbing repairs needed) |
| Creston | 16 | 15 | 1 | 1 | 1 fixture off due to test results (more extensive plumbing repairs needed) |
| Duniway | 13 | 9 | 4 | 4 | 4 fixtures off due to test results (more extensive plumbing repairs needed) |



COMMON AREA - INCLUDES KITCHEN FOOD PREPARATION TAPS

| # FIXTURE LOCATIONS | # RETURNED TO SERVICE | # TURNED OFF DUE TO TEST RESULTS | # REMAINING TO BE RETURNED TO SERVICE |
|---------------------|-----------------------|----------------------------------|---------------------------------------|
|---------------------|-----------------------|----------------------------------|---------------------------------------|

Updated:
Wednesday, July 24, 2019

| | | | | | |
|------------------|----|----|----|----|--|
| East Sylvan | 6 | 5 | 1 | 1 | 1 fixture off due to test results (more extensive plumbing repairs needed) |
| Edwards | 6 | 6 | 0 | 0 | All 6 fixtures returned to service |
| Forest Park | 11 | 10 | 0 | 1 | 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule). |
| George | 8 | 8 | 0 | 0 | All 8 fixtures have been returned to service |
| Glencoe | 10 | 9 | 0 | 1 | 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule) |
| Grant @ Marshall | 33 | 25 | 8 | 8 | 8 fixtures off due to test results (more extensive plumbing repairs needed) |
| Green Thumb | 3 | 3 | 0 | 0 | All 3 fixtures returned to service |
| Grout | 33 | 7 | 17 | 26 | 19 fixtures off due to test results (more extensive plumbing repairs needed) 7 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule) |
| Harrison Park | 15 | 15 | 0 | 0 | All 15 fixtures returned to service |
| Hayhurst | 6 | 6 | 0 | 0 | All 6 fixtures have been returned to service |
| Holladay Center | 5 | 3 | 0 | 2 | 2 fixtures off due to test results (more extensive plumbing repairs needed) |
| Hosford | 22 | 19 | 1 | 3 | 1 fixture off due to test results (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule) |
| Humboldt | 9 | 8 | 0 | 1 | 1 fixture pending commissioning; planned for summer, 2019 |
| Irvington | 26 | 24 | 1 | 2 | 1 fixture off due to test results (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule) |
| Jackson | 26 | 20 | 3 | 6 | 3 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule) |
| James John | 25 | 21 | 2 | 4 | 2 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) |
| Jefferson | 44 | 37 | 7 | 7 | 6 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule) |
| Kelly | 12 | 10 | 1 | 2 | 1 fixture off due to test results (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule) |
| Kenton | 11 | 9 | 0 | 2 | 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule) |
| King | 22 | 20 | 1 | 2 | 1 fixture off due to test results (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule) |
| Lane | 13 | 13 | 0 | 0 | All 13 fixtures returned to service |
| Laurelhurst | 14 | 14 | 0 | 0 | All 14 fixtures returned to service |
| Lee | 10 | 10 | 0 | 0 | All 10 fixtures returned to service |
| Lent | 15 | 14 | 0 | 1 | 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule) |
| Lewis | 10 | 10 | 0 | 0 | All 10 fixtures returned to service |
| Lincoln | 33 | 26 | 5 | 7 | 5 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) |



COMMON AREA - INCLUDES KITCHEN FOOD PREPARATION TAPS

| # FIXTURE LOCATIONS | # RETURNED TO SERVICE | # TURNED OFF DUE TO TEST RESULTS | # REMAINING TO BE RETURNED TO SERVICE |
|---------------------|-----------------------|----------------------------------|---------------------------------------|
|---------------------|-----------------------|----------------------------------|---------------------------------------|

Updated:
Wednesday, July 24, 2019

| | | | | | |
|-----------------|----|----|---|----|--|
| Llewellyn | 19 | 9 | 6 | 10 | 6 fixtures off due to test results (more extensive plumbing repairs needed) 4 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule) |
| Madison | 42 | 22 | 8 | 20 | 8 fixtures off due to test results (more extensive plumbing repairs needed) 6 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 14 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule) |
| Maplewood | 11 | 7 | 2 | 4 | 2 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule) |
| Markham | 8 | 7 | 1 | 1 | 1 fixture off due to test results (more extensive plumbing repairs needed) |
| Marysville | 10 | 10 | 0 | 0 | All 10 fixtures returned to service |
| Meek | 7 | 6 | 1 | 1 | 1 fixture off due to test results (more extensive plumbing repairs needed) |
| MLC | 7 | 5 | 2 | 2 | 2 fixtures off due to test results (more extensive plumbing repairs needed) |
| Monroe/da Vinci | 24 | 23 | 1 | 1 | 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule) |
| Mt. Tabor | 5 | 4 | 1 | 1 | 1 fixture off due to test results (more extensive plumbing repairs needed) |
| Ockley Green | 11 | 11 | 0 | 0 | All 11 fixtures returned to service |
| Peninsula | 11 | 9 | 2 | 2 | 2 fixtures off due to test results (more extensive plumbing repairs needed) |
| Richmond | 20 | 20 | 0 | 0 | All 20 fixtures returned to service |
| Rieke | 12 | 8 | 0 | 4 | 4 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule) |
| Rigler | 18 | 11 | 4 | 7 | 4 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule) 1 fixture pending commissioning; planned for summer, 2019 |
| Robert Gray | 17 | 11 | 5 | 6 | 5 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule) |
| Rosa Parks | 10 | 10 | 0 | 0 | All 10 fixtures have been returned to service |
| Rose City Park | 17 | 16 | 1 | 1 | 1 fixture off due to test results (more extensive plumbing repairs needed) |
| Roseway Heights | 12 | 12 | 0 | 0 | All 12 fixtures returned to service |
| Sabin | 13 | 13 | 0 | 0 | All 13 fixtures returned to service |
| Sacajawea | 5 | 4 | 0 | 1 | 1 fixture pending commissioning; planned for summer, 2019 |
| Scott | 11 | 7 | 0 | 4 | 4 fixtures pending commissioning; planned for summer, 2019 |
| Sellwood | 18 | 18 | 0 | 0 | All 18 fixtures have been returned to service. |
| Sitton | 10 | 9 | 1 | 1 | 1 fixture off due to test results (more extensive plumbing repairs needed) |
| Skyline | 7 | 6 | 0 | 1 | 1 fixture pending commissioning; planned for summer, 2019 |
| Stephenson | 8 | 6 | 1 | 2 | 1 fixture off due to test results (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule) |
| Sunnyside | 19 | 12 | 0 | 7 | 1 fixture off due to test results (more extensive plumbing repairs needed) 6 fixtures require additional repair prior to sampling (refer to Water Quality Program Schedule) |



COMMON AREA - INCLUDES KITCHEN FOOD PREPARATION TAPS

| # FIXTURE LOCATIONS | # RETURNED TO SERVICE | # TURNED OFF DUE TO TEST RESULTS | # REMAINING TO BE RETURNED TO SERVICE |
|---------------------|-----------------------|----------------------------------|---------------------------------------|
|---------------------|-----------------------|----------------------------------|---------------------------------------|

Updated:
Wednesday, July 24, 2019

| | | | | | |
|-------------|----|----|---|----|--|
| Terwilliger | 9 | 0 | 1 | 9 | 1 fixture off due to test results (more extensive plumbing repairs needed) 3 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule) 5 fixtures pending commissioning; planned for summer, 2019 |
| Tubman | 12 | 12 | 0 | 0 | All 12 fixtures returned to service |
| Vernon | 13 | 13 | 0 | 0 | All 13 fixtures have been returned to service. |
| Vestal | 18 | 18 | 0 | 0 | All 18 fixtures returned to service |
| West Sylvan | 12 | 11 | 0 | 1 | 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule) |
| Whitman | 12 | 12 | 0 | 0 | All 12 fixtures returned to service |
| Wilson | 56 | 29 | 8 | 27 | 8 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 17 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule) |
| Winterhaven | 11 | 5 | 3 | 6 | 3 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule) |
| Woodlawn | 9 | 8 | 1 | 1 | 1 fixture off due to test results (more extensive plumbing repairs needed) |
| Woodmere | 8 | 7 | 1 | 1 | 1 fixture off due to test results (more extensive plumbing repairs needed) |
| Woodstock | 13 | 12 | 0 | 1 | 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule) |
| Youngson | 2 | 1 | 0 | 1 | 1 fixture pending commissioning; planned for summer, 2019 |