



COMMON AREA - INCLUDES KITCHEN FOOD PREPARATION TAPS

FIXTURE LOCATIONS # RETURNED TO SERVICE # TURNED OFF DUE TO TEST RESULTS # REMAINING TO BE RETURNED TO SERVICE

Updated:
Wednesday, October 16, 2019

TOTALS	1332	1161	92	171	NOTES
Abernethy	20	20	0	0	All 20 fixtures returned to service
Ainsworth	12	12	0	0	All 12 fixtures returned to service
Alameda	17	15	0	2	2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Applegate	4	4	0	0	All 4 fixtures returned to service
Arleta Pilot Program School	14	14	0	0	Pilot Project: This school had (5) filtered drinking water stations installed. Information about the pilot can be found at: https://www.pps.net/Page/13976
Astor	16	16	0	0	All 16 fixtures returned to service
Atkinson	5	5	0	0	All 5 fixtures returned to service
Beach	22	22	0	0	All 22 fixtures returned to service
Beaumont	21	17	3	4	3 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed)
Benson	43	39	3	4	3 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture off due to sharing a water source with an associated fixture that tested above action level (more extensive plumbing repair needed)
Beverly Cleary/Fernwood	15	13	1	2	1 fixture off due to test results (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
Beverly Cleary/Hollyrood	1	1	0	0	All 1 fixture returned to service
Boise-Eliot	10	10	0	0	All 10 fixtures returned to service
Bridger	17	17	0	0	All 17 fixtures returned to service
Bridlemile	9	8	0	1	1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Buckman	27	23	2	4	2 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture off due to sharing a water source with an associated fixture that tested above action level (more extensive plumbing repair needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
Capitol Hill	13	10	2	3	2 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
Chapman	11	11	0	0	All 11 fixtures returned to service
Chavez	22	21	0	1	1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
Chief Joseph	6	6	0	0	All 6 fixtures returned to service
Clarendon	4	4	0	0	All 4 fixtures returned to service



COMMON AREA - INCLUDES KITCHEN FOOD PREPARATION TAPS

FIXTURE LOCATIONS # RETURNED TO SERVICE # TURNED OFF DUE TO TEST RESULTS # REMAINING TO BE RETURNED TO SERVICE

Updated:
Wednesday, October 16, 2019

Cleveland	26	20	5	6	5 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
Columbia	12	7	4	5	4 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed)
Creative Science	8	6	2	2	2 fixtures off due to test results (more extensive plumbing repairs needed)
Creston	16	15	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Duniway Pilot Program School	15	15	0	0	Pilot Project: This school had (5) filtered drinking water stations installed. Information about the pilot can be found at: https://www.pps.net/Page/13976
East Sylvan	6	5	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Edwards	6	6	0	0	All 6 fixtures returned to service
Forest Park	11	10	0	1	1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule).
George	8	8	0	0	All 8 fixtures have been returned to service
Glencoe	10	9	0	1	1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
Green Thumb	3	3	0	0	All 3 fixtures returned to service
Grout	33	11	12	22	12 fixtures off due to test results (more extensive plumbing repairs needed) 10 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed)
Harrison Park	15	15	0	0	All 15 fixtures returned to service
Hayhurst	6	6	0	0	All 6 fixtures have been returned to service
Holladay Center	5	5	0	0	All 5 fixtures returned to service
Hosford	22	19	1	3	1 fixture off due to test results (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Humboldt	9	9	0	0	All 9 fixtures returned to service
Irvington	26	24	1	2	1 fixture off due to test results (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
Jackson	28	27	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
James John	25	21	2	4	2 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed)
Jefferson Pilot Program School	30	30	0	0	Pilot Project: This school had (10) filtered drinking water stations installed. (2) Additional drinking water stations planned. Information about the pilot can be found at: https://www.pps.net/Page/13976



COMMON AREA - INCLUDES KITCHEN FOOD PREPARATION TAPS

FIXTURE LOCATIONS # RETURNED TO SERVICE # TURNED OFF DUE TO TEST RESULTS # REMAINING TO BE RETURNED TO SERVICE

Updated:
Wednesday, October 16, 2019

Kelly	12	10	1	2	1 fixture off due to test results (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
Kenton	11	9	0	2	2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
King	22	20	1	2	1 fixture off due to test results (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
Lane	13	13	0	0	All 13 fixtures returned to service
Laurelhurst	14	14	0	0	All 14 fixtures returned to service
Lee	10	10	0	0	All 10 fixtures returned to service
Lent	15	14	0	1	1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
Lewis	10	10	0	0	All 10 fixtures returned to service
Lincoln	33	26	5	7	5 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed)
Llewellyn Pilot Program School	15	15	0	0	Pilot Project: This school had (4) filtered drinking water stations installed. Information about the pilot can be found at: https://www.pps.net/Page/13976
Madison	42	27	8	15	Madison is currently being renovated
Maplewood	12	8	2	4	2 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Markham	8	7	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Marshall	33	25	8	8	8 fixtures off due to test results (more extensive plumbing repairs needed)
Marysville	10	10	0	0	All 10 fixtures returned to service
Meek	7	6	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
MLC	7	5	2	2	2 fixtures off due to test results (more extensive plumbing repairs needed)
Monroe/da Vinci	24	23	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Mt. Tabor	5	4	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Ockley Green	11	11	0	0	All 11 fixtures returned to service
Peninsula	11	9	2	2	2 fixtures off due to test results (more extensive plumbing repairs needed)
Richmond	20	20	0	0	All 20 fixtures returned to service
Rieke	13	9	0	4	4 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)



COMMON AREA - INCLUDES KITCHEN FOOD PREPARATION TAPS

FIXTURE LOCATIONS # RETURNED TO SERVICE # TURNED OFF DUE TO TEST RESULTS # REMAINING TO BE RETURNED TO SERVICE

Updated:
Wednesday, October 16, 2019

Rigler	18	15	0	3	Pilot Project: This school has (4) filtered drinking water stations proposed. Stations should be operational by the end of October. Information about the pilot can be found at: https://www.pps.net/Page/13976
Pilot Program School					
Robert Gray	21	21	0	0	Pilot Project: This school had (6) filtered drinking water stations installed. Information about the pilot can be found at: https://www.pps.net/Page/13976
Pilot Program School					
Rosa Parks	10	10	0	0	All 10 fixtures have been returned to service
Rose City Park	18	17	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Roseway Heights	12	12	0	0	All 12 fixtures returned to service
Sabin	13	13	0	0	All 13 fixtures returned to service
Sacajawea	5	5	0	0	All 5 fixtures have been returned to service
Scott	11	11	0	0	All 11 fixtures have been returned to service
Sellwood	18	18	0	0	All 18 fixtures have been returned to service
Sitton	12	11	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Skyline	7	7	0	0	1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
Stephenson	8	6	1	2	1 fixture off due to test results (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
Sunnyside	19	12	0	7	7 fixtures require additional repair prior to sampling (refer to Water Quality Program Schedule)
Terwilliger	9	5	1	4	1 fixture off due to test results (more extensive plumbing repairs needed) 3 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Tubman	12	12	0	0	All 12 fixtures returned to service
Vernon	13	13	0	0	All 13 fixtures have been returned to service.
Vestal	18	18	0	0	All 18 fixtures returned to service
West Sylvan	12	11	0	1	1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
Whitman	12	12	0	0	All 12 fixtures returned to service
Wilson	55	34	9	21	9 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 9 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Winterhaven	10	5	3	5	3 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixtures off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
Woodlawn	9	8	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)



COMMON AREA - INCLUDES KITCHEN FOOD PREPARATION TAPS

# FIXTURE LOCATIONS	# RETURNED TO SERVICE	# TURNED OFF DUE TO TEST RESULTS	# REMAINING TO BE RETURNED TO SERVICE
---------------------	-----------------------	----------------------------------	---------------------------------------

Updated:
Wednesday, October 16, 2019

Woodmere	8	7	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Woodstock	13	12	0	1	1 fixture requires additional repair prior to testing (refer to Water Quality Program Schedule)
Youngson	2	2	0	0	All 2 fixtures have been returned to service