

BINNSMEAD ACCESSIBILITY SUMMARY



Clark @ Binnsmead School 2225 SE 87th Avenue Portland, OR 97216

SUMMARY

Common areas at Clark @ Binnsmead are all located on the ground level. The door hardware and plumbing comprise the majority of the upgrade work. The major accessibility upgrades for Clark @ Binnsmead are s ummarized on this sheet.

ACCESSIBILITY UPGRADES TO MEET 2008 ADA GUIDELINES

Site Elements No site element items

Accessible Route Double handrails at auditorium stage & Reach Ranges Classroom lever handle hardware

Accessible handrails

Plumbing Drinking fountains near gymnasium

Elements Accessible showers

Accessible sinks

Communication Assisted listening devices in auditorium

Elements Signage

Special Spaces Wheelchair access with companion seating in auditorium

Recreational Accessible benches at boys and girls locker room

Facilities Accessible benches at sports play fields

COST BREAKDOWN

Cost information provided is based on 2009 estimated unit costs for direct construction including general contractor overhead. Additionally, estimated hard costs and soft costs provided by PPS have been included.

Site Elements	\$0
Accessible Route & Reach Ranges	\$88,700
Plumbing Elements	\$49,875
Communication Elements	\$12,755
Special Spaces	\$0
Built-In Elements	\$8,199
Recreational Facilities	\$0
Special Education	\$2,340
Total	\$161,869