

JACKSON ACCESSIBILITY SUMMARY



Jackson Middle School 10625 SW 35th Avenue Portland, OR 97219

SUMMARY

Most of the common areas at Jackson are located on the ground floor. Priority should be given to providing an elevator for access to basement locker rooms at this school. The elevator, ramp, door hardware and plumbing on floors other than the main level comprise the majority of the upgrade work. The major accessibility upgrades for Jackson are summarized on this sheet.

ACCESSIBILITY UPGRADES TO MEET 2008 ADA GUIDELINES

Accessible Route Elevator for basement access below gymnasium

Classroom lever door hardware

Plumbing Drinking fountain in basement

Elements Accessible sink heights at science, home economics, art

and main office

Accessible showers at boys and girls locker rooms

Communication Accessibility parking signage
Elements Accessibility interior signage

Assisted listening devices at auditorium/multi-purpose

Special Spaces Accessible work counter at home economics

COST BREAKDOWN

Cost information provided is based on 2009 estimated unit costs for direct construction including general contractor overhead. Additionally, estimated hard costs and soft costs provided by PPS have been included.

Site Elements	\$0
Accessible Route & Reach Ranges	\$369,831
Plumbing Elements	\$48,117
Communication Elements	\$16,171
Special Spaces	\$2,005
Built-In Elements	\$8,199
Recreational Facilities	\$0
Special Education	\$2,340
Total	\$446,662