



# VESTAL

## ACCESSIBILITY SUMMARY



Vestal Elementary School  
161 NE 82nd Avenue  
Portland, OR 97220

### SUMMARY

All common areas at Vestal are located on the ground floor. Priority should be given to providing an elevator for access to the second floor classrooms at this school. The elevator, lift, ramp and plumbing on the second floor comprise the majority of the upgrade work. The major accessibility upgrades for Vestal are summarized on this sheet.

### ACCESSIBILITY UPGRADES TO MEET 2008 ADA GUIDELINES

Site Elements	Accessible pavement striping at pedestrian route Fence modification to allow accessible width opening Accessible ramps at portable classrooms
Accessible Route & Reach Ranges	Elevator to provide access to second floor classrooms Lift to access the stage Accessible handrails in auditorium Accessible handrail replacement at one main stair Door lever hardware
Plumbing Elements	Accessible student restrooms on the second floor Accessible drinking fountain on the second floor Accessible sink
Communication Elements	Assisted listening devices in spaces using audio Amplification Signage
Special Spaces	Wheelchair and companion seating at auditorium
Recreational Facilities	Accessible play area soft surface & structure

### COST BREAKDOWN

Cost information provided is based on 2009 estimated unit costs for direct construction including general contractor overhead. Additionally, estimated hard costs and soft costs provided by PPS have been included.

Site Elements	\$119,284
Accessible Route & Reach Ranges	\$408,631
Plumbing Elements	\$27,673
Communication Elements	\$9,110
Special Spaces	\$15,949
Built-In Elements	\$0
Recreational Facilities	\$36,356
Special Education	\$0
<b>Total</b>	<b>\$617,003</b>