



WOODSTOCK ACCESSIBILITY SUMMARY



Woodstock Elementary School
5601 SE 50th Avenue
Portland, OR 97202

SUMMARY

All common areas at Woodstock are located on the ground floor at this single level school. Priority should be given to providing an accessible street parking spot off of SE 50th avenue, a lift to allow access to the stage in the Cafetorium, and accessible door hardware and clearances. The handrails, lift, door hardware comprise the majority of the upgrade work. The major accessibility upgrades for Woodstock are summarized on this sheet.

ACCESSIBILITY UPGRADES TO MEET 2008 ADA GUIDELINES

Site Elements	Accessible handrails at entry steps
Accessible Route & Reach Ranges	Accessible handrails in interior ramp at corridor
	Cafetorium doors
	Lift for access to Cafetorium stage
	Lever hardware on doors
Plumbing Elements	Sink at Faculty room
Communication Elements	Assisted listening devices at Cafetorium and spaces using audio amplification
	Signage
Recreational Facilities	Accessible play area soft surfacing & structure

COST BREAKDOWN

Cost information provided is based on 2009 estimated unit costs for direct construction including general contractor overhead. Additionally, estimated hard costs and soft costs provided by PPS have been included.

Site Elements	\$4,019
Accessible Route & Reach Ranges	\$121,376
Plumbing Elements	\$5,296
Communication Elements	\$10,021
Special Spaces	\$0
Built-In Elements	\$0
Recreational Facilities	\$38,424
Special Education	\$2,340
Total	\$181,476