## **PPS Educational Adequacy and Facility Assessment**

## **School Deficiency Listing**

2/8/2008 1:42 PM

Rosa Parks Elementary School 175

**School and Site Level Deficiencies** 

## Site

Deficiency	ID	Qty UoM	Priority
Playground Requires Replacement	13904	1 Ea.	5
School lacks marquee or marquee in poor condition.	13840	1 Ea.	5
	Sub Total for System	2	
Technology			
Deficiency	ID	Qty UoM	Priority
Facility lacks centralized video distribution equipment	16773	1 Ea.	3
Facility lacks VOIP central equipment	16862	1 Ea.	3
	Sub Total for System	2	
	Sub Total for School and Site Level	4	
Building: A - Main Building			
Interior			
Deficiency	ID	Qty UoM	Priority
Door is not equiped with Card Key Access	17529	97 Ea.	3
	Sub Total for System	1	
Fire and Life Safety			
Deficiency	ID	Qty UoM	Priority
PA Speakers are missing or need to be replaced	18866	7 Ea.	2
	Sub Total for System	1	
Technology			
Deficiency	ID	Qty UoM	Priority
Administrative or support area lacks VOIP phone handset	17367	34 Ea.	3
Building lacks enough wireless data points	17087	8 Ea.	3
Classroom lacks technology upgrade	15760	3 Ea.	3
Classroom lacks technology upgrade (not including projector)	15761	25 Ea.	3
Classroom lacks VOIP phone handset	18524	28 Ea.	3
Room has insufficient dataports.	15749	160 Ea.	5
	Sub Total for System	6	
	Sub Total for Building A - Main Building	8	
Building: B - Covered Play Area			
Fire and Life Safety			
Deficiency	ID	Qty UoM	Priority
PA Speakers are missing or need to be replaced	18865	1 Ea.	2
	Sub Total for System	1	
	Sub Total for Building B - Covered Play Area	1	
	Total for Campus	13	