

PORTLAND PUBLIC SCHOOLS – FACILITY ADA ASSESSMENT

Humboldt School PK-8
August 31, 2009

Site Accessibility

Parking	(1) accessible space at the north parking lot. Provide a striped crosswalk across the vehicular way to the curb cut leading to the accessible entrance.
---------	--

Accessible Route & Features

Northeast Main Entry	Existing main building entry located next to office with power operated 2-6 pair doors and accessibility signage. Verify that power operator complies with current accessibility requirements for speed and rate of operation.
Portable Classrooms	Existing ramps to portable classrooms P1/P2 and P3/P4 have compliant slopes. Update and add compliant railings at the landings and compliant double handrails at the stairs and ramps (approximately 100lf of rail at P1/P2.)
South Entry to Play Yard	Verify that the pair of exterior doors next to room 25 allow a 32" clear opening with or without an astragal, and that the doors have lever hardware or pulls from the exterior side. Provide replacement doors if needed for clearance. Provide a ramp with double handrails for the step down to the play yard (approximately 6lf of ramp.)
Classroom doors	Provide all classrooms with lever handle hardware (approximately 16 doors.)

Plumbing Elements

Drinking Fountain	Verify existing and add a new dual height drinking fountain that complies with revised accessibility standards for children and adults at corridor opposite Multi-Purpose 20A
Girls Locker 30D	If this room is still used for this function, provide an accessible toilet, stall, grab bars, lavatory, accessories and shower.
Boys Locker 30C	If this room is still used for this function, provide an accessible toilet, stall, grab bars, lavatory, accessories and shower.
Office/Faculty	Provide an accessible sink.

Communication Elements

Multi-Purpose Room 30	Provide assisted listening devices.
Classrooms	Any need for assisted listening devices in programs at this school? Or within SPED classrooms?
Signage	Provide accessible signage at new accessible restrooms and common spaces. If signage is provided at classrooms, provide accessible signage.



Special Spaces, Built-in Elements & Recreational Facilities

Girls Locker 30D	Provide an accessible bench.
Boys Locker 30C	Provide an accessible bench.
Play Surface	There is (1) soft play areas at the south end of the outside play area. Verify and test existing play structure safety surfacing at these areas. Mulch/ground cover must be solid enough to allow wheelchair access.
Play Structure	Verify that the existing play structure is accessible, and modify if needed.

