PORTLAND PUBLIC SCHOOLS – FACILITY ADA ASSESSMENT

Kelly School K-5 August 31, 2009

Site Accessibility

| corner. Although not required, providing a sidewalk direct from the parking to the existing sidewalk with a curb cut and detectable warning would increase accessibility. | Parking | |
|---|---------|--|
|---|---------|--|

Accessible Route & Features

| Accessible Route & Features | | |
|-----------------------------|--|--|
| Stage 31A | Add a lift in room136B to allow access at northwest corner of stage | |
| Gym 35 | Revise (1) north pair of entry doors with swing clear hinges and appropriate | |
| | closers to ensure minimum 32-inch single door clearances. (Doors are | |
| | existing 2'-8" pairs.) | |
| | Otherwise, replace with 3-0/2-4 unequal pair doors for compliance. | |
| Computer Room | Modify wall recess and entry door to provide accessible clearance from the | |
| 119 | corridor, or provide a power operator at the corridor side. | |
| Library 118 | Modify wall recess and entry door to provide accessible clearance from the | |
| | corridor, or provide a power operator at the corridor side. | |
| Sun Office | Provide lever door hardware. | |
| Classroom doors | Provide all classrooms with lever handle hardware. (40) classrooms. | |

Plumbing Elements

| 0 | |
|-------------------|--|
| Office/Faculty | If a sink is provided, provide an accessible sink. |
| Boys Locker Room | If this room is still being used for this function (rather than as storage as in |
| 121B | many K-5's), provide an accessible toilet, stall, grab bars, lavatory, |
| | accessories and shower. |
| Girls Locker Room | If this room is still being used for this function (rather than as storage as in |
| 121E | many K-5's), provide an accessible toilet, stall, grab bars, lavatory, |
| | accessories and shower. |

Communication Elements

| Cafetorium 136 | Provide assisted listening devices. |
|----------------|--|
| Classrooms | Any need for assisted listening devices in programs at this school? Or |
| | within SPED classrooms? |
| Signage | Verify that accessible signage is provided at accessible restrooms and |
| | common areas, and provide if needed. If signage is provided at |
| | classrooms, provide accessible signage. |

Special Spaces, Built-in Elements & Recreational Facilities

Boys Locker Room Verify current locker room use. If still active, update one locker bench to

ANKROM MOISAN ARCHITECTURE INTERIORS PLANNING

PORTLAND: 6720 SW MACADAM, PORTLAND, OREGON 97219 | 503-245-7100 SEATTLE: 117 S MAIN STREET, SUITE 400, SEATTLE, WASHINGTON 98104 | 206-576-1600

| 121B | new requirements which includes a backrest. |
|--------------------|--|
| Girls Locker Room | Verify current locker room use. If still active, update one locker bench to |
| 121E | new requirements which includes a backrest. |
| Exterior Courtyard | Where benches are provided, provide an accessible bench. |
| Play Surface | There is (1) soft play area at the outside play areas. Verify and test existing play structure safety surfacing at these areas. Mulch/ground cover must be |
| | solid enough to allow wheelchair access. |
| Play Structure | Verify that the existing play structure is accessible, and modify if needed. |