

PORTLAND PUBLIC SCHOOLS – FACILITY ADA ASSESSMENT

Lewis School K-5
 August 31, 2009

Site Accessibility

Southeast Parking	Facility plan notes one accessible stall, aerial shows 2, but PPS notes show 4 accessible stalls recently restriped with signage, pavement striping, and curb cut to entry.
-------------------	---

Accessible Route & Features

Southeast Entry	Verify closer pressures to 8 lbs maximum for exterior doors.
Entry from Play Yard	Verify that the pair of doors from the corridor south of the cafeteria exiting to the play yard have lever or pull hardware on the exterior.
Stage	Add lift at south stage access room.
Classroom doors	Provide all classrooms with lever handle hardware.

Plumbing Elements

Office/Faculty	If a sink is provided, provide an accessible sink.
----------------	--

Communication Elements

Cafeteria/Auditorium	Provide assisted listening devices.
Classrooms	Any need for assisted listening devices in programs at this school? Or within SPED classrooms?
Signage	Verify accessible signage is provided at accessible restrooms and common spaces. If signage is provided at classrooms, provide accessible signage.

Special Spaces, Built-in Elements & Recreational Facilities

Play Surfaces	Verify safety surfacing at 2 outdoor play structure areas for wheelchair access.
Play Structures	Verify that at least one of the existing play structures is accessible, and modify if needed.

