

# PORTLAND PUBLIC SCHOOLS – FACILITY ADA ASSESSMENT

Rieke School K-5  
August 31, 2009

## Site Accessibility

East Parking	3 accessible stalls available. Restripe and verify size and spacing of stalls and aisles per compliant guidelines.
Exterior Stairs	Verify handrail compliance of stairway from main road (high school overflow) parking lot with adult standards.

## Accessible Route & Features

Special Education 15	Provide lever door hardware.
Classroom doors	Provide all classrooms and common rooms with lever handle hardware.

## Plumbing Elements

Drinking Fountain	Replace drinking fountain near adult Unisex restroom with double height fountain for adults and children. <b>Drinking fountain near Library is compliant children's height.</b>
Drinking Fountain Annex	Replace drinking fountain in corridor with a double height fountain.
Office/Faculty	Provide an accessible sink.

## Communication Elements

Multi-Purpose Room 16	Provide assisted listening devices.
Classrooms	Any need for assisted listening devices in programs at this school? Or within SPED classrooms?
Signage	Verify accessible signage at accessible restrooms and common spaces. If signage is provided at classrooms, provide accessible signage.

## Special Spaces, Built-in Elements & Recreational Facilities

Play Fields	Where benches are provided at play fields, provide accessible benches.
Play Surface	There is one existing exterior play structure area with accessible impact safety surfacing.
Play Structure	Verify that the existing play structure is accessible, and modify if needed.

## Field Notes:

1. Accessible parking is at lower level of school, and avoids exterior grand entry stairs coming in from main parking lot and drop-off zone.
2. Multi-purpose Gym/Cafeteria has been updated for entry/exit compliance.

