PORTLAND PUBLIC SCHOOLS – FACILITY ADA ASSESSMENT

Woodmere School K-5 August 31, 2009

Site Accessibility

Parking	 (2) accessible spaces at north on-site parking available at this school. Restripe and reconfigure for current accessibility stall guidelines. Verify that van access aisle is 8 ft width. Relocate signage for each stall. Additional parking at south of building between building and play area. Recommend restriping (2) pedestrian crosswalks between school and play area.
---------	--

Accessible Route & Features

Accessible Route & readures		
Main North Entry	Existing accessible entry at center of front courtyard. Entry is on grade.	
	Verify closer pressures at front doors for compliant 8-1/2 lb. maximum.	
Stage	Add a lift at the north side stage area adjacent to the corridor to provide	
	accessibility for the raised stage area.	
Portables	Verify compliant ramps and stairs to portable Classrooms P1/P2 and P3/P4.	
	Verify compliant double handrails at each side of ramps and railings.	
	Provide lever hardware at doors.	
Sun Office	Provide lever door hardware.	
Classroom doors	Provide all classrooms with lever handle hardware.	
Cafeteria	Verify that the door from the cafeteria to the play yard has lever or pull	
	hardware on the exterior.	

Plumbing Elements

Office/Faculty	rovide an accessible sink.	
Art	a sink is provided, provide an accessible sink.	

Communication Elements

Cafeteria 33	Provide assisted listening devices.
Classrooms	Any need for assisted listening devices in programs at this school? Or
	within SPED classrooms?
Signage	Verify accessible signage is provided at accessible restrooms and common spaces. If signage is provided at classrooms, provide accessible signage.
	provide a classionily, provide accessible signage.

Special Spaces, Built-in Elements & Recreational Facilities

Cafeteria 33	Verify the serving counter height and line width are accessible per PPS		
	children's standards. Alternatively, provide an accessible mobile serving		
	line to augment the tight confines of the fixed serving line.		
Play Surface	There is (1) soft play area at the outside play area. Verify and test existing		
	play structure safety surfacing at these areas. Mulch/ground cover must be		
	solid enough to allow wheelchair access.		
Play Structure	Verify that the existing play structure is accessible, and modify if needed.		