



Updated: December 07, 2018

**CLASSROOM FIXTURES - INCLUDES CTE, MEDICAL AND STAFF AREAS**

	# FIXTURE LOCATIONS	# RETURNED TO SERVICE	# TURNED OFF DUE TO TEST RESULTS	# REMAINING TO BE RETURNED TO SERVICE	NOTES
<b>Totals:</b>	<b>1273</b>	<b>683</b>	<b>328</b>	<b>590</b>	
ABERNETHY	12	6	4	6	4 fixtures off due to testing results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
AINSWORTH	24	4	5	20	5 fixtures off due to testing results (more extensive plumbing repairs needed) 15 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
ALAMEDA	15	6	3	9	3 fixtures off due to testing results (more extensive plumbing repairs needed) 6 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
APPLEGATE	12	4	3	8	3 fixtures are off due to testing results (more extensive plumbing repairs needed) 5 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
ARLETA	11	2	8	9	8 fixtures off due to testing results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
ASTOR	18	14	3	4	3 fixtures are off due to testing results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
ATKINSON	25	25	0	0	All 25 fixtures have been returned to service
BEACH	18	12	3	6	3 fixtures are off due to testing results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
BEAUMONT	1	0	1	1	1 fixture off due to testing results (more extensive plumbing repairs needed)
BENSON	27	15	7	12	7 fixtures off due to testing results (more extensive plumbing repairs needed) 5 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
BEVERLY CLEARY/FERNWO	10	9	1	1	1 fixture off due to testing results (more extensive plumbing repairs needed).
BOISE-ELIOT	36	15	9	21	9 fixtures off due to testing results (more extensive plumbing repairs needed) 12 fixtures require repair prior to testing (refer to Water Quality Program Schedule).
BRIDGER	21	16	3	5	3 fixtures off due to testing results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
BRIDLEMILE	28	17	3	11	3 fixtures off due to testing results (more extensive plumbing repairs needed) 8 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
BUCKMAN	27	14	6	13	6 fixtures off due to testing results (more extensive plumbing repairs needed) 7 fixtures require additional repair prior to sampling (refer to Water Quality Program Schedule)
CAPITOL HILL	14	5	3	9	3 fixtures off due to testing results (more extensive plumbing repairs needed) 6 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
CHAPMAN	15	12	0	3	3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
CHAVEZ	9	0	3	9	3 fixtures off due to testing results (more extensive plumbing repairs needed) 6 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
CHIEF JOSEPH	16	9	5	7	5 fixtures off due to testing results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
CLARENDON	13	6	2	7	2 fixtures off due to testing results (more extensive plumbing repairs needed) 5 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
CLEVELAND	5	3	1	2	1 fixture off due to testing results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)

## PPS WATER QUALITY PROGRAM SUMMARY

COLUMBIA	3	0	0	3	3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
CREATIVE SCIENCE	17	12	3	5	3 fixtures off due to testing results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
CRESTON	13	9	0	4	4 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
DUNIWAY	14	3	9	11	9 fixtures off due to testing results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
EAST SYLVAN	1	0	1	1	1 fixture off due to testing results (more extensive plumbing repairs needed).
EDWARDS	11	4	2	7	2 fixtures off due to testing results (more extensive plumbing repairs needed) 5 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
FOREST PARK	2	2	0	0	All 2 fixtures have been returned to service
GEORGE	28	12	13	16	13 fixtures off due to testing results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
GLENCOE	5	3	2	2	2 fixtures off due to testing results (more extensive plumbing repairs needed)
GRANT @ MARSHALL	3	3	0	0	All 3 fixtures have been returned to service
GREEN THUMB	1	0	0	1	1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
GROUT	10	2	8	8	8 fixtures off due to test results (more extensive plumbing repairs needed)
HARRISON PARK	30	12	10	18	10 fixtures off due to testing results (more extensive plumbing repairs needed) 8 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
HAYHURST	22	13	4	9	4 fixtures off due to testing results (more extensive plumbing repairs needed) 5 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
HOLLADAY CENTER	8	8	0	0	All 8 fixtures returned to service
HOLLYROOD	11	7	3	4	3 fixtures off due to testing results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
HOSFORD	10	9	1	1	1 fixture off due to testing results (more extensive plumbing repairs needed)
HUMBOLDT	20	12	3	8	3 fixture off due to testing results (more extensive plumbing repairs needed) 5 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
IRVINGTON	7	3	2	4	2 fixtures off due to testing results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
JACKSON	8	3	1	5	1 fixture off due to testing results (more extensive plumbing repairs needed) 4 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
JAMES JOHN	10	6	3	4	3 fixtures off due to testing results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
JEFFERSON	27	8	11	19	11 fixtures off due to testing results (more extensive plumbing repairs needed) 1 fixture off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 7 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
KELLY	29	16	5	13	5 fixtures off due to testing results (more extensive plumbing repairs needed) 8 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
KENTON	1	0	0	1	1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
KING	15	10	2	5	2 fixtures off due to testing results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)

## PPS WATER QUALITY PROGRAM SUMMARY

LANE	8	7	1	1	1 fixture off due to testing results (more extensive plumbing repairs needed)
LAURELHURST	7	4	3	3	3 fixtures off due to testing results (more extensive plumbing repairs needed)
LEE	25	13	9	12	9 fixtures off due to testing results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
LENT	31	17	9	14	9 fixtures off due to testing results (more extensive plumbing repairs needed) 5 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
LEWIS	22	17	4	5	4 fixtures off due to testing results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
LINCOLN	12	2	0	10	10 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
LLEWELLYN	7	4	2	3	2 fixtures off due to testing results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
MADISON	23	13	4	10	4 fixtures off due to testing results (more extensive plumbing repairs needed) 6 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
MAPLEWOOD	13	9	2	4	2 fixtures off due to testing results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
MARKHAM	24	7	13	17	13 fixtures off due to testing results (more extensive plumbing repairs needed) 4 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
MARYSVILLE	14	14	0	0	All 14 fixtures returned to service
MEEK PROFESSIONAL TECHNICAL	11	3	5	8	5 fixtures off due to testing results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
MLC	1	0	0	1	1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
MONROE/DA VINCI	1	0	0	1	1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
MT TABOR	30	20	7	10	7 fixtures off due to testing results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
OCKLEY GREEN	4	4	0	0	All 4 fixtures returned to service
PENINSULA	27	16	4	11	4 fixtures off due to testing results (more extensive plumbing repairs needed) 7 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
RICHMOND	11	9	1	2	1 fixture off due to testing results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
RIEKE	13	11	1	2	1 fixture off due to testing results (more extensive plumbing repairs needed) 1 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
RIGLER	14	6	6	8	6 fixtures off due to testing results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
ROBERT GRAY	29	3	25	26	25 fixtures off due to testing results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
ROSA PARKS	23	14	7	9	7 fixtures off due to testing results (more extensive plumbing repairs needed) 2 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
ROSE CITY PARK	3	0	3	3	3 fixtures off due to testing results (more extensive plumbing repairs needed)
ROSEWAY HEIGHTS	5	0	0	5	5 fixtures require repair prior to testing (refer to Water Quality Program Schedule)

## PPS WATER QUALITY PROGRAM SUMMARY

SABIN	13	5	6	8	6 fixtures off due to testing results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
SACAJAWEA	8	5	2	3	2 fixtures off due to testing results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
SCOTT	25	16	8	9	8 fixtures off due to testing results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
SELLWOOD	1	0	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
SITTON	20	6	11	14	11 fixtures off due to testing results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
SKYLINE	6	6	0	0	All 11 fixtures returned to service
STEPHENSON	15	12	0	3	3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
SUNNYSIDE	5	4	0	1	1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
TERWILLIGER	0	0	0	0	There are no classroom drinking fixtures at Terwilliger
TUBMAN	34	14	8	20	8 fixtures off due to testing results (more extensive plumbing repairs needed) 12 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
VERNON	9	4	3	5	3 fixtures off due to testing results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
VESTAL	13	5	5	8	5 fixtures off due to testing results (more extensive plumbing repairs needed) 1 fixture off due to sharing water source with an associated fixture that tested above action level (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
WEST SYLVAN	6	2	2	4	2 fixtures off due to testing results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
WHITMAN	25	16	3	9	3 fixtures off due to testing results (more extensive plumbing repairs needed) 6 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
WILSON	12	5	4	7	4 fixtures off due to testing results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
WINTERHAVEN	7	4	1	3	1 fixture off due to testing results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
WOODLAWN	9	8	0	1	1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
WOODMERE	20	18	1	2	1 fixture off due to testing results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
WOODSTOCK	13	6	4	7	4 fixtures off due to testing results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
YOUNGSON	11	3	7	8	7 fixtures off due to testing results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)