



**CLASSROOM FIXTURES - INCLUDES CTE, MEDICAL AND STAFF AREAS**

**# FIXTURE LOCATIONS    # RETURNED TO SERVICE    # TURNED OFF DUE TO TEST RESULTS    # REMAINING TO BE RETURNED TO SERVICE**

**Updated:  
Friday, February 22, 2019**

<b>TOTALS</b>	<b>1272</b>	<b>655</b>	<b>340</b>	<b>617</b>	<b>NOTES</b>
Abernethy	12	6	4	6	4 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Ainsworth	24	3	5	21	5 fixtures are off due to test results (more extensive plumbing repairs needed) 16 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Alameda	15	6	3	9	3 fixtures off due to test results (more extensive plumbing repairs needed) 6 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Applegate	12	4	3	8	3 fixtures off due to test results (more extensive plumbing repairs needed) 5 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Arleta	11	2	8	9	8 fixtures are off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Astor	18	14	4	4	4 fixtures are off due to test results (more extensive plumbing repairs needed)
Atkinson	26	25	0	1	1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Beach	18	12	3	6	3 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Beaumont	1	0	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Benson	27	14	7	13	7 fixtures off due to test results (more extensive plumbing repairs needed) 6 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Beverly Cleary/Fernwood	10	9	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Beverly Cleary/Hollyrood	11	7	3	4	3 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Boise-Eliot	36	15	9	21	9 fixtures off due to test results (more extensive plumbing repairs needed) 12 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Bridger	21	16	3	5	3 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Bridlemile	28	17	3	11	3 fixtures off due to test results (more extensive plumbing repairs needed) 8 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Buckman	27	14	6	13	6 fixtures off due to test results (more extensive plumbing repairs needed) 7 fixtures require repair prior to testing (refer to Water Quality Program Schedule).
Capitol Hill	14	5	3	9	3 fixtures off due to test results (more extensive plumbing repairs needed) 6 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Chapman	15	12	0	3	3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Chavez	9	2	3	7	3 fixtures off due to test results (more extensive plumbing repairs needed) 4 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Chief Joseph	16	9	5	7	5 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Clarendon	13	6	2	7	2 fixtures off due to test results (more extensive plumbing repairs needed) 5 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Cleveland	7	3	1	4	1 fixture off due to test results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Columbia	3	0	0	3	3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Creative Science	17	12	3	5	3 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Creston	12	4	4	8	4 fixtures off due to test results (more extensive plumbing repairs needed) 4 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Duniway	14	2	9	12	9 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)



CLASSROOM FIXTURES - INCLUDES CTE, MEDICAL AND STAFF AREAS

# FIXTURE LOCATIONS    # RETURNED TO SERVICE    # TURNED OFF DUE TO TEST RESULTS    # REMAINING TO BE RETURNED TO SERVICE

Updated:  
Friday, February 22, 2019

TOTALS	1272	655	340	617	NOTES
East Sylvan	1	0	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Edwards	11	3	2	8	2 fixtures off due to test results (more extensive plumbing repairs needed) 6 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Forest Park	2	2	0	0	All 2 fixtures have been returned to service
George	28	12	13	16	13 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Glencoe	5	3	2	2	2 fixtures off due to test results (more extensive plumbing repairs needed)
Grant @ Marshall	3	1	0	2	2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Green Thumb	1	0	0	1	1 fixture pending commissioning (refer to Water Quality Program Schedule)
Grout	10	2	7	8	7 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Harrison Park	33	12	10	21	10 fixtures off due to test results (more extensive plumbing repairs needed) 11 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Hayhurst	22	13	4	9	4 fixtures off due to pending test results (refer to Water Quality Program Schedule) 5 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Holladay Center	8	8	0	0	All 8 fixtures have been returned to service
Hosford	10	9	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Humboldt	20	12	3	8	3 fixtures off due to test results (more extensive plumbing repairs needed) 5 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Irvington	7	2	2	5	2 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Jackson	8	3	1	5	1 fixture off due to test results (more extensive plumbing repairs needed) 4 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
James John	10	6	3	4	3 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Jefferson	27	9	13	18	13 fixtures off due to test results (more extensive plumbing repairs needed) 5 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Kelly	29	0	7	29	7 fixtures off due to test results (more extensive plumbing repairs needed) 22 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Kenton	1	0	0	1	1 fixture pending commissioning (refer to Water Quality Program Schedule)
King	15	10	2	5	2 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Lane	8	7	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Laurelhurst	8	4	3	4	3 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Lee	26	13	10	13	10 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Lent	31	15	7	16	7 fixtures off due to test results (more extensive plumbing repairs needed) 9 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Lewis	22	17	4	5	4 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Lincoln	12	3	0	9	9 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Llewellyn	7	4	2	3	2 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)



**CLASSROOM FIXTURES - INCLUDES CTE, MEDICAL AND STAFF AREAS**

**# FIXTURE LOCATIONS    # RETURNED TO SERVICE    # TURNED OFF DUE TO TEST RESULTS    # REMAINING TO BE RETURNED TO SERVICE**

**Updated:**  
Friday, February 22, 2019

<b>TOTALS</b>	<b>1272</b>	<b>655</b>	<b>340</b>	<b>617</b>	<b>NOTES</b>
Madison	23	12	4	11	4 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Maplewood	13	8	2	5	2 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Markham	24	6	14	18	14 fixtures off due to test results (more extensive plumbing repairs needed) 4 fixtures requires repair prior to testing (refer to Water Quality Program Schedule)
Marysville	14	13	0	1	1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Meek	11	3	5	8	5 fixtures require repair prior to testing (refer to Water Quality Program Schedule) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
MLC	1	1	0	0	All 1 fixture has been returned to service
Monroe/da Vinci	1	0	0	1	1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Mt. Tabor	30	19	8	11	8 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Ockley Green	6	4	0	2	2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Peninsula	27	15	4	12	4 fixtures off due to test results (more extensive plumbing repairs needed) 8 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Richmond	11	9	1	2	1 fixture off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Rieke	13	11	1	2	1 fixture off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Rigler	14	6	6	8	6 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Robert Gray	29	3	25	26	25 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Rosa Parks	23	14	7	9	7 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Rose City Park	3	0	3	3	3 fixtures off due to test results (more extensive plumbing repairs needed)
Roseway Heights	5	0	1	5	1 fixture off due to test results (more extensive plumbing repairs needed) 4 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Sabin	13	5	6	8	6 fixtures off due to test results (more extensive plumbing repairs needed) 8 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Sacajawea	8	5	2	3	2 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Scott	25	16	8	9	8 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Sellwood	1	0	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Sitton	20	6	11	14	11 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Skyline	6	6	0	0	All 6 fixtures returned to service
Stephenson	15	12	1	3	1 fixture off due to test results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Sunnyside	5	4	0	1	1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Tubman	34	14	8	20	8 fixtures off due to test results (more extensive plumbing repairs needed) 12 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Vernon	11	4	3	7	3 fixtures require repair prior to testing (refer to Water Quality Program Schedule) 4 fixtures require repair prior to testing (refer to Water Quality Program Schedule)



**CLASSROOM FIXTURES - INCLUDES CTE, MEDICAL AND STAFF AREAS**

**# FIXTURE LOCATIONS    # RETURNED TO SERVICE    # TURNED OFF DUE TO TEST RESULTS    # REMAINING TO BE RETURNED TO SERVICE**

**Updated:**  
Friday, February 22, 2019

<b>TOTALS</b>	<b>1272</b>	<b>655</b>	<b>340</b>	<b>617</b>	<b>NOTES</b>
Vestal	13	6	5	7	5 fixtures require repair prior to testing (refer to Water Quality Program Schedule) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
West Sylvan	6	2	2	4	2 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Whitman	25	16	3	9	3 fixtures off due to test results (more extensive plumbing repairs needed) 6 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Wilson	12	6	5	6	5 fixtures are off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Winterhaven	7	4	1	3	1 fixture off due to test results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Woodlawn	9	8	0	1	1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Woodmere	20	18	1	2	1 fixture off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Woodstock	12	6	4	6	4 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Youngson	11	3	7	8	7 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)



**CLASSROOM FIXTURES - INCLUDES CTE, MEDICAL AND STAFF AREAS**

**# FIXTURE LOCATIONS    # RETURNED TO SERVICE    # TURNED OFF DUE TO TEST RESULTS    # REMAINING TO BE RETURNED TO SERVICE**

**Updated:  
Friday, February 22, 2019**

<b>TOTALS</b>	<b>1272</b>	<b>655</b>	<b>340</b>	<b>617</b>	<b>NOTES</b>
Abernethy	12	6	4	6	4 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Ainsworth	24	3	5	21	5 fixtures are off due to test results (more extensive plumbing repairs needed) 16 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Alameda	15	6	3	9	3 fixtures off due to test results (more extensive plumbing repairs needed) 6 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Applegate	12	4	3	8	3 fixtures off due to test results (more extensive plumbing repairs needed) 5 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Arleta	11	2	8	9	8 fixtures are off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Astor	18	14	4	4	4 fixtures are off due to test results (more extensive plumbing repairs needed)
Atkinson	26	25	0	1	1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Beach	18	12	3	6	3 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Beaumont	1	0	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Benson	27	14	7	13	7 fixtures off due to test results (more extensive plumbing repairs needed) 6 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Beverly Cleary/Fernwood	10	9	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Beverly Cleary/Hollyrood	11	7	3	4	3 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Boise-Eliot	36	15	9	21	9 fixtures off due to test results (more extensive plumbing repairs needed) 12 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Bridger	21	16	3	5	3 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Bridlemile	28	17	3	11	3 fixtures off due to test results (more extensive plumbing repairs needed) 8 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Buckman	27	14	6	13	6 fixtures off due to test results (more extensive plumbing repairs needed) 7 fixtures require repair prior to testing (refer to Water Quality Program Schedule).
Capitol Hill	14	5	3	9	3 fixtures off due to test results (more extensive plumbing repairs needed) 6 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Chapman	15	12	0	3	3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Chavez	9	2	3	7	3 fixtures off due to test results (more extensive plumbing repairs needed) 4 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Chief Joseph	16	9	5	7	5 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Clarendon	13	6	2	7	2 fixtures off due to test results (more extensive plumbing repairs needed) 5 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Cleveland	7	3	1	4	1 fixture off due to test results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Columbia	3	0	0	3	3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Creative Science	17	12	3	5	3 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Creston	12	4	4	8	4 fixtures off due to test results (more extensive plumbing repairs needed) 4 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Duniway	14	2	9	12	9 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)



**CLASSROOM FIXTURES - INCLUDES CTE, MEDICAL AND STAFF AREAS**

**# FIXTURE LOCATIONS    # RETURNED TO SERVICE    # TURNED OFF DUE TO TEST RESULTS    # REMAINING TO BE RETURNED TO SERVICE**

**Updated:**  
Friday, February 22, 2019

<b>TOTALS</b>	<b>1272</b>	<b>655</b>	<b>340</b>	<b>617</b>	<b>NOTES</b>
East Sylvan	1	0	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Edwards	11	3	2	8	2 fixtures off due to test results (more extensive plumbing repairs needed) 6 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Forest Park	2	2	0	0	All 2 fixtures have been returned to service
George	28	12	13	16	13 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Glencoe	5	3	2	2	2 fixtures off due to test results (more extensive plumbing repairs needed)
Grant @ Marshall	3	1	0	2	2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Green Thumb	1	0	0	1	1 fixture pending commissioning (refer to Water Quality Program Schedule)
Grout	10	2	7	8	7 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Harrison Park	33	12	10	21	10 fixtures off due to test results (more extensive plumbing repairs needed) 11 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Hayhurst	22	13	4	9	4 fixtures off due to pending test results (refer to Water Quality Program Schedule) 5 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Holladay Center	8	8	0	0	All 8 fixtures have been returned to service
Hosford	10	9	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Humboldt	20	12	3	8	3 fixtures off due to test results (more extensive plumbing repairs needed) 5 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Irvington	7	2	2	5	2 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Jackson	8	3	1	5	1 fixture off due to test results (more extensive plumbing repairs needed) 4 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
James John	10	6	3	4	3 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Jefferson	27	9	13	18	13 fixtures off due to test results (more extensive plumbing repairs needed) 5 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Kelly	29	0	7	29	7 fixtures off due to test results (more extensive plumbing repairs needed) 22 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Kenton	1	0	0	1	1 fixture pending commissioning (refer to Water Quality Program Schedule)
King	15	10	2	5	2 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Lane	8	7	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Laurelhurst	8	4	3	4	3 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Lee	26	13	10	13	10 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Lent	31	15	7	16	7 fixtures off due to test results (more extensive plumbing repairs needed) 9 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Lewis	22	17	4	5	4 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Lincoln	12	3	0	9	9 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Llewellyn	7	4	2	3	2 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)



**CLASSROOM FIXTURES - INCLUDES CTE, MEDICAL AND STAFF AREAS**

**# FIXTURE LOCATIONS    # RETURNED TO SERVICE    # TURNED OFF DUE TO TEST RESULTS    # REMAINING TO BE RETURNED TO SERVICE**

**Updated:  
Friday, February 22, 2019**

<b>TOTALS</b>	<b>1272</b>	<b>655</b>	<b>340</b>	<b>617</b>	<b>NOTES</b>
Madison	23	12	4	11	4 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Maplewood	13	8	2	5	2 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Markham	24	6	14	18	14 fixtures off due to test results (more extensive plumbing repairs needed) 4 fixtures requires repair prior to testing (refer to Water Quality Program Schedule)
Marysville	14	13	0	1	1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Meek	11	3	5	8	5 fixtures require repair prior to testing (refer to Water Quality Program Schedule) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
MLC	1	1	0	0	All 1 fixture has been returned to service
Monroe/da Vinci	1	0	0	1	1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Mt. Tabor	30	19	8	11	8 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Ockley Green	6	4	0	2	2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Peninsula	27	15	4	12	4 fixtures off due to test results (more extensive plumbing repairs needed) 8 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Richmond	11	9	1	2	1 fixture off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Rieke	13	11	1	2	1 fixture off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Rigler	14	6	6	8	6 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Robert Gray	29	3	25	26	25 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Rosa Parks	23	14	7	9	7 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Rose City Park	3	0	3	3	3 fixtures off due to test results (more extensive plumbing repairs needed)
Roseway Heights	5	0	1	5	1 fixture off due to test results (more extensive plumbing repairs needed) 4 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Sabin	13	5	6	8	6 fixtures off due to test results (more extensive plumbing repairs needed) 8 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Sacajawea	8	5	2	3	2 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Scott	25	16	8	9	8 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Sellwood	1	0	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Sitton	20	6	11	14	11 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Skyline	6	6	0	0	All 6 fixtures returned to service
Stephenson	15	12	1	3	1 fixture off due to test results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Sunnyside	5	4	0	1	1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Tubman	34	14	8	20	8 fixtures off due to test results (more extensive plumbing repairs needed) 12 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Vernon	11	4	3	7	3 fixtures require repair prior to testing (refer to Water Quality Program Schedule) 4 fixtures require repair prior to testing (refer to Water Quality Program Schedule)



**CLASSROOM FIXTURES - INCLUDES CTE, MEDICAL AND STAFF AREAS**

**# FIXTURE LOCATIONS    # RETURNED TO SERVICE    # TURNED OFF DUE TO TEST RESULTS    # REMAINING TO BE RETURNED TO SERVICE**

**Updated:**  
Friday, February 22, 2019

<b>TOTALS</b>	<b>1272</b>	<b>655</b>	<b>340</b>	<b>617</b>	<b>NOTES</b>
Vestal	13	6	5	7	5 fixtures require repair prior to testing (refer to Water Quality Program Schedule) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
West Sylvan	6	2	2	4	2 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Whitman	25	16	3	9	3 fixtures off due to test results (more extensive plumbing repairs needed) 6 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Wilson	12	6	5	6	5 fixtures are off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Winterhaven	7	4	1	3	1 fixture off due to test results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Woodlawn	9	8	0	1	1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Woodmere	20	18	1	2	1 fixture off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Woodstock	12	6	4	6	4 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Youngson	11	3	7	8	7 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)





**CLASSROOM FIXTURES - INCLUDES CTE, MEDICAL AND STAFF AREAS**

**# FIXTURE LOCATIONS    # RETURNED TO SERVICE    # TURNED OFF DUE TO TEST RESULTS    # REMAINING TO BE RETURNED TO SERVICE**

**Updated:  
Friday, February 22, 2019**

<b>TOTALS</b>	<b>1272</b>	<b>655</b>	<b>340</b>	<b>617</b>	<b>NOTES</b>
Abernethy	12	6	4	6	4 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Ainsworth	24	3	5	21	5 fixtures are off due to test results (more extensive plumbing repairs needed) 16 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Alameda	15	6	3	9	3 fixtures off due to test results (more extensive plumbing repairs needed) 6 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Applegate	12	4	3	8	3 fixtures off due to test results (more extensive plumbing repairs needed) 5 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Arleta	11	2	8	9	8 fixtures are off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Astor	18	14	4	4	4 fixtures are off due to test results (more extensive plumbing repairs needed)
Atkinson	26	25	0	1	1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Beach	18	12	3	6	3 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Beaumont	1	0	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Benson	27	14	7	13	7 fixtures off due to test results (more extensive plumbing repairs needed) 6 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Beverly Cleary/Fernwood	10	9	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Beverly Cleary/Hollyrood	11	7	3	4	3 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Boise-Eliot	36	15	9	21	9 fixtures off due to test results (more extensive plumbing repairs needed) 12 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Bridger	21	16	3	5	3 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Bridlemile	28	17	3	11	3 fixtures off due to test results (more extensive plumbing repairs needed) 8 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Buckman	27	14	6	13	6 fixtures off due to test results (more extensive plumbing repairs needed) 7 fixtures require repair prior to testing (refer to Water Quality Program Schedule).
Capitol Hill	14	5	3	9	3 fixtures off due to test results (more extensive plumbing repairs needed) 6 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Chapman	15	12	0	3	3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Chavez	9	2	3	7	3 fixtures off due to test results (more extensive plumbing repairs needed) 4 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Chief Joseph	16	9	5	7	5 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Clarendon	13	6	2	7	2 fixtures off due to test results (more extensive plumbing repairs needed) 5 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Cleveland	7	3	1	4	1 fixture off due to test results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Columbia	3	0	0	3	3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Creative Science	17	12	3	5	3 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Creston	12	4	4	8	4 fixtures off due to test results (more extensive plumbing repairs needed) 4 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Duniway	14	2	9	12	9 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)



**CLASSROOM FIXTURES - INCLUDES CTE, MEDICAL AND STAFF AREAS**

**# FIXTURE LOCATIONS    # RETURNED TO SERVICE    # TURNED OFF DUE TO TEST RESULTS    # REMAINING TO BE RETURNED TO SERVICE**

**Updated:**  
Friday, February 22, 2019

<b>TOTALS</b>	<b>1272</b>	<b>655</b>	<b>340</b>	<b>617</b>	<b>NOTES</b>
East Sylvan	1	0	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Edwards	11	3	2	8	2 fixtures off due to test results (more extensive plumbing repairs needed) 6 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Forest Park	2	2	0	0	All 2 fixtures have been returned to service
George	28	12	13	16	13 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Glencoe	5	3	2	2	2 fixtures off due to test results (more extensive plumbing repairs needed)
Grant @ Marshall	3	1	0	2	2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Green Thumb	1	0	0	1	1 fixture pending commissioning (refer to Water Quality Program Schedule)
Grout	10	2	7	8	7 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Harrison Park	33	12	10	21	10 fixtures off due to test results (more extensive plumbing repairs needed) 11 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Hayhurst	22	13	4	9	4 fixtures off due to pending test results (refer to Water Quality Program Schedule) 5 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Holladay Center	8	8	0	0	All 8 fixtures have been returned to service
Hosford	10	9	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Humboldt	20	12	3	8	3 fixtures off due to test results (more extensive plumbing repairs needed) 5 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Irvington	7	2	2	5	2 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Jackson	8	3	1	5	1 fixture off due to test results (more extensive plumbing repairs needed) 4 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
James John	10	6	3	4	3 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Jefferson	27	9	13	18	13 fixtures off due to test results (more extensive plumbing repairs needed) 5 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Kelly	29	0	7	29	7 fixtures off due to test results (more extensive plumbing repairs needed) 22 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Kenton	1	0	0	1	1 fixture pending commissioning (refer to Water Quality Program Schedule)
King	15	10	2	5	2 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Lane	8	7	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Laurelhurst	8	4	3	4	3 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Lee	26	13	10	13	10 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Lent	31	15	7	16	7 fixtures off due to test results (more extensive plumbing repairs needed) 9 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Lewis	22	17	4	5	4 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Lincoln	12	3	0	9	9 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Llewellyn	7	4	2	3	2 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)



**CLASSROOM FIXTURES - INCLUDES CTE, MEDICAL AND STAFF AREAS**

**# FIXTURE LOCATIONS    # RETURNED TO SERVICE    # TURNED OFF DUE TO TEST RESULTS    # REMAINING TO BE RETURNED TO SERVICE**

**Updated:**  
Friday, February 22, 2019

<b>TOTALS</b>	<b>1272</b>	<b>655</b>	<b>340</b>	<b>617</b>	<b>NOTES</b>
Madison	23	12	4	11	4 fixtures off due to test results (more extensive plumbing repairs needed) 7 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Maplewood	13	8	2	5	2 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Markham	24	6	14	18	14 fixtures off due to test results (more extensive plumbing repairs needed) 4 fixtures requires repair prior to testing (refer to Water Quality Program Schedule)
Marysville	14	13	0	1	1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Meek	11	3	5	8	5 fixtures require repair prior to testing (refer to Water Quality Program Schedule) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
MLC	1	1	0	0	All 1 fixture has been returned to service
Monroe/da Vinci	1	0	0	1	1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Mt. Tabor	30	19	8	11	8 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Ockley Green	6	4	0	2	2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Peninsula	27	15	4	12	4 fixtures off due to test results (more extensive plumbing repairs needed) 8 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Richmond	11	9	1	2	1 fixture off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Rieke	13	11	1	2	1 fixture off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Rigler	14	6	6	8	6 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Robert Gray	29	3	25	26	25 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Rosa Parks	23	14	7	9	7 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Rose City Park	3	0	3	3	3 fixtures off due to test results (more extensive plumbing repairs needed)
Roseway Heights	5	0	1	5	1 fixture off due to test results (more extensive plumbing repairs needed) 4 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Sabin	13	5	6	8	6 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Sacajawea	8	5	2	3	2 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Scott	25	16	8	9	8 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Sellwood	1	0	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Sitton	20	6	11	14	11 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Skyline	6	6	0	0	All 6 fixtures returned to service
Stephenson	15	12	1	3	1 fixture off due to test results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Sunnyside	5	4	0	1	1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Tubman	34	14	8	20	8 fixtures off due to test results (more extensive plumbing repairs needed) 12 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Vernon	11	4	3	7	3 fixtures require repair prior to testing (refer to Water Quality Program Schedule) 4 fixtures require repair prior to testing (refer to Water Quality Program Schedule)



**CLASSROOM FIXTURES - INCLUDES CTE, MEDICAL AND STAFF AREAS**

**# FIXTURE LOCATIONS    # RETURNED TO SERVICE    # TURNED OFF DUE TO TEST RESULTS    # REMAINING TO BE RETURNED TO SERVICE**

**Updated:**  
Friday, February 22, 2019

<b>TOTALS</b>	<b>1272</b>	<b>655</b>	<b>340</b>	<b>617</b>	<b>NOTES</b>
Vestal	13	6	5	7	5 fixtures require repair prior to testing (refer to Water Quality Program Schedule) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
West Sylvan	6	2	2	4	2 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Whitman	25	16	3	9	3 fixtures off due to test results (more extensive plumbing repairs needed) 6 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Wilson	12	6	5	6	5 fixtures are off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Winterhaven	7	4	1	3	1 fixture off due to test results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Woodlawn	9	8	0	1	1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Woodmere	20	18	1	2	1 fixture off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Woodstock	12	6	4	6	4 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Youngson	11	3	7	8	7 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)