



CLASSROOM FIXTURES - INCLUDES CTE, MEDICAL AND STAFF AREAS

FIXTURE LOCATIONS # RETURNED TO SERVICE # TURNED OFF DUE TO TEST RESULTS # REMAINING TO BE RETURNED TO SERVICE

Updated:
Wednesday, October 16, 2019

TOTALS	1261	811	381	450	NOTES
Abernethy	12	6	5	6	5 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Ainsworth	24	12	11	12	11 fixtures are off due to test results (more extensive plumbing repairs needed) 1 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Alameda	15	11	4	4	4 fixtures off due to test results (more extensive plumbing repairs needed)
Applegate	12	8	3	4	3 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Arleta	11	2	9	9	9 fixtures are off due to test results (more extensive plumbing repairs needed)
Astor	18	14	4	4	4 fixtures are off due to test results (more extensive plumbing repairs needed)
Atkinson	26	26	0	0	All 26 fixtures returned to service
Beach	18	15	3	3	3 fixtures off due to test results (more extensive plumbing repairs needed)
Beaumont	1	0	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Benson	27	19	8	8	8 fixtures off due to test results (more extensive plumbing repairs needed)
Beverly Cleary/Fernwood	11	10	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Beverly Cleary/Hollyrood	11	8	3	3	3 fixtures off due to test results (more extensive plumbing repairs needed)
Boise-Eliot	36	27	9	9	9 fixtures off due to test results (more extensive plumbing repairs needed)
Bridger	21	18	3	3	3 fixtures off due to test results (more extensive plumbing repairs needed)
Bridlemile	27	23	3	4	3 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Buckman	27	18	6	9	6 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule).
Capitol Hill	14	7	5	7	5 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Chapman	15	14	0	1	1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Chavez	9	3	6	6	6 fixtures off due to test results (more extensive plumbing repairs needed)
Chief Joseph	16	9	5	7	5 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures require additional repair prior to testing (refer to Water Quality Program Schedule)
Clarendon	13	10	2	3	2 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Cleveland	6	5	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Columbia	3	2	0	1	1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Creative Science	17	14	3	3	3 fixtures off due to test results (more extensive plumbing repairs needed)
Creston	13	8	4	5	4 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Duniway	14	3	9	11	9 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
East Sylvan	1	0	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Edwards	11	4	4	7	4 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Forest Park	3	3	0	0	All 3 fixtures have been returned to service



CLASSROOM FIXTURES - INCLUDES CTE, MEDICAL AND STAFF AREAS

FIXTURE LOCATIONS # RETURNED TO SERVICE # TURNED OFF DUE TO TEST RESULTS # REMAINING TO BE RETURNED TO SERVICE

NOTES

Updated:
Wednesday, October 16, 2019

George	28	12	14	16	14 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Glencoe	5	3	2	2	2 fixtures off due to test results (more extensive plumbing repairs needed)
Green Thumb	1	0	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Grout	9	2	7	7	7 fixtures off due to test results (more extensive plumbing repairs needed)
Harrison Park	33	18	12	15	12 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Hayhurst	22	16	5	6	5 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Holladay Center	8	8	0	0	All 8 fixtures have been returned to service
Hosford	10	9	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Humboldt	20	12	4	8	4 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule) 2 fixtures are pending commissioning; planned for summer, 2019
Irvington	7	3	2	4	2 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Jackson	6	3	2	3	2 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
James John	10	6	4	4	4 fixtures off due to test results (more extensive plumbing repairs needed)
Jefferson	26	11	12	15	12 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Kelly	28	18	8	10	8 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Kenton	1	1	0	0	All 1 fixtures returned to service
King	15	10	2	5	2 fixtures off due to test results (more extensive plumbing repairs needed) 3 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Lane	8	7	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Laurelhurst	9	5	3	4	3 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Lee	26	14	10	12	10 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Lent	31	19	10	12	10 fixtures off due to test results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Lewis	22	17	4	5	4 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Lincoln	10	9	0	1	1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Llewellyn	7	4	3	3	3 fixtures off due to test results (more extensive plumbing repairs needed)
Madison	23	13	9	10	9 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Maplewood	13	10	2	3	2 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Markham	24	9	15	15	15 fixtures off due to test results (more extensive plumbing repairs needed)
Marshall	3	3	0	0	All 3 fixtures returned to service
Marysville	14	13	0	1	1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Meek	11	3	6	8	6 fixtures require repair prior to testing (refer to Water Quality Program Schedule) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)



CLASSROOM FIXTURES - INCLUDES CTE, MEDICAL AND STAFF AREAS

FIXTURE LOCATIONS # RETURNED TO SERVICE # TURNED OFF DUE TO TEST RESULTS # REMAINING TO BE RETURNED TO SERVICE

NOTES

Updated:
Wednesday, October 16, 2019

MLC	1	1	0	0	All 1 fixture has been returned to service
Monroe/da Vinci	1	0	0	1	1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Mt. Tabor	30	22	8	8	8 fixtures off due to test results (more extensive plumbing repairs needed)
Ockley Green	6	5	0	1	1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Peninsula	27	21	5	6	5 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Richmond	11	9	2	2	1 fixture off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Rieke	13	11	1	2	1 fixture off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Rigler	14	6	7	8	7 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Robert Gray	29	4	24	25	24 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Rosa Parks	23	15	7	8	7 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Rose City Park	3	0	3	3	3 fixtures off due to test results (more extensive plumbing repairs needed)
Roseway Heights	5	2	1	3	1 fixture off due to test results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Sabin	13	6	6	7	6 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Sacajawea	8	5	2	3	2 fixtures off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Scott	24	16	8	8	8 fixtures off due to test results (more extensive plumbing repairs needed)
Sellwood	1	0	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Sitton	19	7	12	12	12 fixtures off due to test results (more extensive plumbing repairs needed)
Skyline	6	6	0	0	All 6 fixtures returned to service
Stephenson	14	12	1	2	1 fixture off due to test results (more extensive plumbing repairs needed) 1 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Sunnyside	5	5	0	0	All 5 fixtures returned to service
Tubman	24	15	9	9	9 fixtures off due to test results (more extensive plumbing repairs needed)
Vernon	11	8	3	3	3 fixtures off due to test results (more extensive plumbing repairs needed)
Vestal	13	8	5	5	5 fixtures off due to test results (more extensive plumbing repairs needed)
West Sylvan	6	4	2	2	2 fixtures off due to test results (more extensive plumbing repairs needed)
Whitman	21	18	3	3	3 fixtures off due to test results (more extensive plumbing repairs needed)
Wilson	12	6	5	6	5 fixtures are off due to test results (more extensive plumbing repairs needed) 1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Winterhaven	7	4	1	3	1 fixture off due to test results (more extensive plumbing repairs needed) 2 fixtures require repair prior to testing (refer to Water Quality Program Schedule)
Woodlawn	9	8	0	1	1 fixture requires repair prior to testing (refer to Water Quality Program Schedule)
Woodmere	20	19	1	1	1 fixture off due to test results (more extensive plumbing repairs needed)
Woodstock	12	7	5	5	5 fixtures off due to test results (more extensive plumbing repairs needed)



CLASSROOM FIXTURES - INCLUDES CTE, MEDICAL AND STAFF AREAS

# FIXTURE LOCATIONS	# RETURNED TO SERVICE	# TURNED OFF DUE TO TEST RESULTS	# REMAINING TO BE RETURNED TO SERVICE
---------------------	-----------------------	----------------------------------	---------------------------------------

NOTES

Updated:
Wednesday, October 16, 2019

Youngson	11	4	7	7	7 fixtures off due to test results (more extensive plumbing repairs needed)
----------	----	---	---	---	---